





General information

Make	KIA
Model	SOUL CRDI QUANTUM
Colour	Red
Year of manufacture	2014
Top speed	112 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	64.2 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history	
Entry 1	
Date	2021-02-01
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-03-14
MOT pass rate	57 %
MOT passed	8
Failed MOT tests	6
Total advice items	15
Total items failed	12

MOT #14	2024-03-12 16:32
MOT test number	733213052691
Result	✓ Passed
Next expiry date	2025-03-14

MOT #13	2024-03-12 08:51
MOT test number	834912846186
Result	🗙 Failed
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge nail in tyre (5.2.3 (e))	
Fail Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Nearside Track rod end ball joint has excessive play (2.1.3 (b) (i))	

MOT #12	2023-03-15 16:42
MOT test number	113651295373
Result	✓ Passed



MOT #	11	2023-03-13 12:23
MOT te	est number	943721721567
Result		🗙 Failed
Fail	Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Fail	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))	
Fail	Offside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))	
Advid	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #10		2022-03-11 08:55
MOT test	number	277105030272
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Tyre slightly damaged/cracking or perishing slight damaged to both offside tyres (5.2.3 (d) (ii))		

MOT #9		2021-03-09 16:37
MOT test	number	707078301713
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #8	2021-03-05 18:39
MOT test number	668082955603
Result	🗙 Failed
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))	
Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Offside Front Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))	

MOT #7	2020-02-07 10:26
MOT test number	720369641769
Result	✓ Passed

MOT #6		2020-02-07 10:26
MOT test number		920575365273
Result		🗙 Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

MOT #5		2019-02-11 14:17
MOT test i	number	964057124341
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge o/s & n/s ON MINIMUM	LEGAL DEPTH (5.2.3 (e))
Advice	Engine covers fitted	
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	

MOT #4	2018-02-12 11:08
MOT test number	969124124914
Result	✓ Passed





МОТ #3	2018-02-12 11:08
MOT test number	424302310504
Result	🗙 Failed
Pass with rectification Registration plate lamp not working o/s & n/s (1.1.C.1d)	
MOT #2	2017-02-06 10:36
MOT test number	216805235909
Result	✓ Passed
Advice Engine covers fitted	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
MOT #1	2017-02-06 10:36
MOT test number	459476670046
Result	🗙 Failed
Advice Engine covers fitted	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Pass with rectificationOffside Headlamp aim too high (1.8)	



Tax & MOT check

✓ Taxed Tax due: 1 July 2024	MOT Expires: 14 March 2025
Tax status	Valid until 1 July
Days left	63
MOT expiry date	14 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

Extra KIA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

xxxxxxxx	

	More info >
Plate changes	
See in this check if this KIA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow



GU63HDV report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2014-02-14
Last registration	2024-03-12
Complete history	<u>See info</u>



Registration #1	2014-02-14	16 mi
Registration #2	2017-02-06	18.363 mi
Registration #3	2017-02-06	18.363 mi
Registration #4	2018-02-12	27.245 mi
Registration #5	2018-02-12	27.245 mi
Registration #6	2019-02-11	35.713 mi
Registration #7	2020-02-07	45.541 mi
Registration #8	2020-02-07	45.541 mi
Registration #9		11.777 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		

More info >





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
\$0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	86%
Pedestrian	39%
Safety systems	86%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	1785 mm
Height	1610 mm
Length	4120 mm
Wheel base	2550 mm
Kerb weight	1444 kg
Max. allowed weight	1790 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FBBH70236

D4FBBH702364