



PEUGEOT



YP54UJY

report date: 2024-03-28

General information

Make	PEUGEOT
Model	206 ZEST
Colour	Silver
Year of manufacture	-
Top speed	98 mph
0 - 60 mph	15.1 seconds
Gearbox	7 speed Manual

Engine & fuel consumption

Power	60 BHP
Max. torque	94 Nm at 2.700 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	56.5 mpg
Consumption combined	45.6 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-03
Pictures	17
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #20	2021-12-08 12:34
MOT test number	549630968505
Result	✓ Passed
Next expiry date	2022-12-27
Advice	Rear Rear suspension components slightly corroded
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))

MOT #19	2021-12-08 12:34
MOT test number	279955573327
Result	✗ Failed
Advice	Offside Side repeater slightly discoloured (4.4.3 (a))
Advice	Offside Rear Shock absorbers has a slightly worn bush (5.3.2 (c))
Pass with rectification	Rear Stop lamp(s) not working Offside & nearside (4.3.1 (a) (ii))
Pass with rectification	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Rear Rear suspension components slightly corroded
Pass with rectification	Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #18	2020-12-10 10:17
MOT test number	947745553720
Result	✓ Passed

**MOT #17**

2020-12-08 15:07

MOT test number

182664100846

Result**✗ Failed****Fail** Nearside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Rear Exhaust has a major leak of exhaust gases (6.1.2 (a))**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #16**

2019-12-14 11:23

MOT test number

640907875547

Result**✓ Passed****Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #15**

2018-12-22 10:24

MOT test number

106605129967

Result**✓ Passed****Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Nearside Rear Lower Shock absorbers has a slightly worn bush bush (5.3.2 (c))



MOT #14	2017-12-16 09:23
MOT test number	305379121856
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)

MOT #13	2017-12-16 09:23
MOT test number	828388748909
Result	✗ Failed
Pass with rectification	Nearside Front Front position lamp(s) not working (1.1.A.3b)
Pass with rectification	Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)
Advice	Offside Front Tyre worn close to the legal limit worn on inner edge (4.1.E.1)
Pass with rectification	Nearside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

MOT #12	2016-12-28 10:48
MOT test number	960868760143
Result	✓ Passed
Advice	Oil leak

MOT #11	2015-11-28 09:55
MOT test number	145510495019
Result	✓ Passed
Advice	Oil leaks on engine
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #10** 2015-11-28 09:55**MOT test number** 329243061286**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Oil leaks on engine**MOT #9** 2014-11-15 12:45**MOT test number** 589539714353**Result** ✓ Passed**Notice** Oil leak**MOT #8** 2014-11-15 10:58**MOT test number** 517989814321**Result** ✗ Failed**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Oil leak**Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #7** 2013-11-23 09:09**MOT test number** 886087423347**Result** ✓ Passed**Notice** Oil leak**Notice** Rear exhaust box crroded**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2012-12-03 13:01**MOT test number** 818268032396**Result** ✓ Passed**Notice** Exhaust system crroded**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2011-10-25 15:22**MOT test number** 456038891217**Result** ✓ Passed**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**Advice** Side repeater slightly discoloured (1.4.A.2f)**MOT #4** 2010-11-01 10:19**MOT test number** 440915300329**Result** ✓ Passed**MOT #3** 2009-11-09 12:09**MOT test number** 400223319334**Result** ✓ Passed**MOT #2** 2008-11-25 14:39**MOT test number** 762590238303**Result** ✓ Passed**MOT #1** 2007-11-16 14:54**MOT test number** 533320927398**Result** ✓ Passed



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	YP54UJY
Plate since	2019-03-28
Current registration	YP54UJY
Plate since	2019-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-11-26
Last registration	2021-12-08
Complete history	See info



Registration #1	2004-11-26	24 mi
Registration #2	2007-11-16	11.541 mi
Registration #3	2008-11-25	14.508 mi
Registration #4	2009-11-09	17.691 mi
Registration #5	2010-11-01	19.259 mi
Registration #6	2011-10-25	20.697 mi
Registration #7	2012-12-03	25.690 mi
Registration #8	2013-11-23	31.741 mi
Registration #9	2014-11-15	39.545 mi
Registration #10	2014-11-15	39.545 mi
Registration #11	2015-11-28	47.032 mi
Registration #12	2016-11-28	55.577 mi
Registration #13	2017-11-28	64.122 mi
Registration #14	2018-11-28	72.667 mi
Registration #15	2019-11-28	81.212 mi
Registration #16	2020-11-28	89.757 mi
Registration #17	2021-11-28	98.302 mi
Registration #18	2022-11-28	106.847 mi
Registration #19	2023-11-28	115.392 mi
Registration #20	2024-11-28	123.937 mi
Registration #21	2025-11-28	132.482 mi
Registration #22	2026-11-28	141.027 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1652 mm
Height	1433 mm
Length	3822 mm
Wheel base	2445 mm
Kerb weight	985 kg
Max. allowed weight	1405 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	5

Number of axles	2
Engine number	FP7N4595647