



report date: 2025-01-24

General information

Make	MINI
Model	COUNTRYMAN COOPER D ALL4 COOPER D ALL4
Colour	White
Year of manufacture	2011
Top speed	112 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption combined	64.2 mpg
CO2 emission	129 g/km
CO2 label	D






Internet history

Entry 1

Date	2023-01-22
Pictures	12
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-09-16
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	29
Total items failed	5

MOT #15	2024-09-17 16:03
MOT test number	275217169714
Result	✓ Passed
Next expiry date	2025-09-16

MOT #14	2023-09-28 09:00
MOT test number	499931497456
Result	✓ Passed
Advice	Under tray loose
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #13	2022-10-18 13:01
MOT test number	262967078458
Result	✓ Passed
Advice	Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #12 2022-10-18 12:01

MOT test number 341790122672

Result ✗ Failed

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #11 2021-11-22 13:47

MOT test number 817109162443

Result ✓ Passed

Advice Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))

Advice Nearside Front Tyre worn on inner edge

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Front Suspension arm corroded but not seriously weakened o/s & n/s (5.3.3 (b) (i))

Advice Offside Front Tyre worn on edges

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))



MOT #10 2021-11-16 12:48

MOT test number 681895338955

Result ✗ Failed

- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Front Tyre worn on edges
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Front Suspension arm corroded but not seriously weakened o/s & n/s (5.3.3 (b) (i))
- Advice** Nearside Front Tyre worn on inner edge
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))

MOT #9 2020-11-18 16:16

MOT test number 809218177410

Result ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Tyre slightly worn on inner edge
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))



MOT #8	2020-11-17 17:24
MOT test number	463968836948
Result	✗ Failed
Fail	Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
Advice	Offside Rear Mud flap loose
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Fail	Nearside Rear Anti-roll bar pin or bush excessively worn D-bush (5.3.4 (a) (i))
Advice	Brake disc worn, but not excessively Both Rear (1.1.14 (a) (i))
Advice	Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Offside Front Tyre slightly worn on inner edge
Advice	Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
Fail	Offside Rear Anti-roll bar pin or bush excessively worn D-bush (5.3.4 (a) (i))

MOT #7	2019-11-22 09:21
MOT test number	431218740930
Result	✓ Passed

MOT #6	2018-10-31 09:22
MOT test number	309973036909
Result	✓ Passed

MOT #5	2017-10-27 08:30
MOT test number	266363925341
Result	✓ Passed

MOT #4	2016-11-22 09:02
MOT test number	558059422701
Result	✓ Passed



MOT #3 2016-01-08 15:59

MOT test number 807667083234

Result ✓ Passed

MOT #2 2015-01-20 11:58

MOT test number 596780525049

Result ✓ Passed

MOT #1 2014-01-28 15:45

MOT test number 969188224029

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 January 2026

✓
MOT

Expires:
16 September 2025

Tax status Valid until 1 January

Days left 321

MOT expiry date 16 September 2025

Full MOT history [See MOT history](#)

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-




Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Due to strict data protection laws, we cannot and do not provide the personal details of a vehicle's owner. Download the full report [here](#).

Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End
Owner	Start	End

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	YD61USP
Plate since	2019-09-29
Current registration	YD61USP
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.


Finance company	REDACTED
Date of agreement	REDACTED
Agreement type	REDACTED
Agreement term	REDACTED
Agreement number	REDACTED
Contact info	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-09-15
Last registration	2024-09-17
Complete history	See info



Registration #1	2011-09-15	15 mi
Registration #2	2014-01-28	26.100 mi
Registration #3	2015-01-20	38.306 mi
Registration #4	2016-01-08	49.769 mi
Registration #5	2016-11-22	60.056 mi
Registration #6	2017-10-27	67.610 mi
Registration #7	2018-10-31	78.767 mi
Registration #8	2019-11-22	96.197 mi
Registration #9	2020-11-17	106.647 mi
Registration #10	2021-09-17	117.200 mi
Registration #11	2022-09-17	127.753 mi
Registration #12	2023-09-17	138.306 mi
Registration #13	2024-09-17	148.859 mi
Registration #14	2025-01-24	159.412 mi
Registration #15	2025-01-24	170.000 mi
Registration #16	2025-01-24	180.588 mi
Registration #17	2025-01-24	191.176 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1577 mm
Length	4097 mm
Kerb weight	1380 kg
Max. allowed weight	1850 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	71247709