





General information

Make	CITROEN
Model	C5 HDI VTR PLUS NAV
Colour	Grey
Year of manufacture	-
Top speed	127 mph
0 - 60 mph	10.6 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	140 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg





Internet history

Entry 2	
Date	2021-08-01
Pictures	17
Listing price	View report



source: autotrader.co.uk

Entry 1	
Date	2021-07-24
Pictures	18
Listing price	View report









source: cargurus.co.uk



MOT history

MOT #13	2021-08-06 15:32
MOT test number	460968269505
Result	✓ Passed
Next expiry date	2022-08-05
Minor Offside Windscreen damaged but not adversely affecting driver's view c	hip in screen (3.2 (a) (i))
Advice Rear Inner Brake disc worn, pitted or scored, but not seriously weakened both sides (1.1.14 (a) (ii))	

MOT #12		2020-09-15 11:54
MOT test	number	506362547068
Result		✓ Passed
Advice	Front Tyre worn close to legal limit/worn on edge Both (5.2.3 (e))	
Advice	Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))	

MOT #11	2019-09-17 15:34
MOT test number	466348233951
Result	✓ Passed

MOT #10	2019-09-16 15:56
MOT test number	221041250117
Result	🗙 Failed
Fail Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Fail Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	

MOT #9	2018-09-11 13:30
MOT test number	633956183679
Result	✓ Passed





МОТ #8	2017-09-25 08:15
MOT test number	898763999512
Result	✓ Passed
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' view of the road. (8.3.1a)	Not directly in drivers
MOT #7	2016-11-25 11:37
MOT test number	460240342548
Result	🗸 Passed
Advice Tyre worn close to the legal limit both fronts on inner edges (4.1.E.1)	
MOT #6	2016-11-25 11:37
MOT test number	758330040228
Result	🗙 Failed

Pass with rectification Front position lamp(s) not working both fronts (1.1.A.3b)

Advice Tyre worn close to the legal limit both fronts on inner edges (4.1.E.1)

Pass with rectificationNearside Registration plate lamp not working (1.1.C.1d)

2015-12-04 11:12
247862937879
✓ Passed
2014-12-05 09:51
908519634346
✓ Passed

MOT #3	2013-10-21 16:02
MOT test number	856904993201
Result	✓ Passed



F	G590ZW
	report date: 2024-03-29

MOT #2		2012-10-18 13:29
MOT test number		859932592202
Result		✓ Passed
Advice Front Brake pad	(s) wearing thin (3.5.1g)	
Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)		
MOT #1		2012-10-18 13:29
MOT test number		505252592254
Result		🗙 Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)
Advice Front Brake pad(s) wearing thin (3.5.1g)		
Pass with rectification	Offside Headlamp not working on dipped beam (1.	7 5 -)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)





Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Law P
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	 ₩.
Category	 AMPT
Туре	

Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-10-26
Last registration	2021-08-06
Complete history	See info



Registration #1	2009-10-26	25 mi
Registration #2	2012-10-18	47.665 mi
Registration #3	2013-10-21	62.601 mi
Registration #4	2014-12-05	76.305 mi
Registration #5	2015-12-04	89.682 mi
Registration #6	2016-11-25	102.023 mi
Registration #7	2016-11-25	102.023 mi
Registration #8	2017-09-25	109.836 mi
Registration #9		11.777 mi
Registration #10		11.117 esi
Registration #11		11.707 est
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 mi





Safety ratings		
NCAP rating	****	D
Video	see crash video	
Dimensions & weight		
Width		1853 mm
Height		1456 mm
Length		4779 mm
Wheel base		2815 mm
Kerb weight		1608 kg
Max. allowed weight		2155 kg
Additional information		
Fuel delivery		Direct Injection
Number of doors		4
Number of seats		5
Number of axles		2
Engine number		DYXH4043189