



report date: 2024-03-28

General information

Make	VOLVO
Model	C30 SPORT
Colour	Black
Year of manufacture	2008
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	150 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.4 mpg
CO2 emission	167 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-06-30
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-29
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	29
Total items failed	10

MOT #20	2024-03-28 16:00
MOT test number	845851939071
Result	✓ Passed
Next expiry date	2025-03-29
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #19	2024-03-28 16:00
MOT test number	766703057603
Result	✗ Failed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Pass with rectification	Nearside Front Position lamp not working (4.2.1 (a) (ii))

**MOT #18**

2023-03-20 14:47

MOT test number

530947773980

Result

✓ Passed

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Minor Nearside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))

MOT #17

2022-03-23 14:24

MOT test number

963263765021

Result

✓ Passed

MOT #16

2021-03-30 08:57

MOT test number

960005325073

Result

✓ Passed

MOT #15

2020-10-19 10:02

MOT test number

313421172967

Result

✓ Passed

Advice Offside Front Nail in tyre

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Exhaust system corroding

Advice Front Tyre worn close to legal limit/worn on edge Both front tyres wearing on edges and close to legal limit (5.2.3 (e))

Advice Sill covers fitted

**MOT #14** 2019-04-12 14:56**MOT test number** 351009784764**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #13** 2019-04-12 11:27**MOT test number** 897013979223**Result** ✗ Failed**Fail** Nearside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Fail** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #12** 2018-04-09 08:30**MOT test number** 183390698391**Result** ✓ Passed**Advice** Tyre worn close to the legal limit both front (4.1.E.1)**MOT #11** 2017-04-05 08:06**MOT test number** 656280277667**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**MOT #10** 2016-03-24 16:36**MOT test number** 246597731907**Result** ✓ Passed**Advice** Both front tyres worn heavily on inner edge (no cord visible)**MOT #9** 2016-03-24 10:32**MOT test number** 435641647785**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Both front tyres worn heavily on inner edge (no cord visible)**MOT #8** 2015-03-23 09:58**MOT test number** 197812385497**Result** ✓ Passed**MOT #7** 2014-03-13 09:42**MOT test number** 109502374478**Result** ✓ Passed**MOT #6** 2014-03-13 09:42**MOT test number** 477372474074**Result** ✗ Failed**Pass with rectification** Nearside Headlamp not working on dipped beam (1.7.5a)**MOT #5** 2013-03-25 12:40**MOT test number** 825394283042**Result** ✓ Passed

**MOT #4** 2012-04-11 14:53**MOT test number** 846742002122**Result** ✓ Passed**Notice** Offside rear tyre, cut in outer sidewall, no cord showing**Notice** Nearside indicator repeater lamp damaged**Notice** Offside rear tyre outer sidewall worn**Notice** Rear tyres wearing on inner edge**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Nearside rear tyre outer sidewall worn**MOT #3** 2011-09-22 09:54**MOT test number** 985545561286**Result** ✓ Passed**MOT #2** 2011-08-18 12:00**MOT test number** 648450931231**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #1** 2011-08-18 12:00**MOT test number** 277770731289**Result** ✗ Failed**Pass with rectification** Offside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
29 March 2025

Tax status	Valid until 1 December
Days left	216
MOT expiry date	29 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2008-09-11
Last registration	2024-03-28
Complete history	See info



Registration #1	2008-09-11	29 mi
Registration #2	2011-08-18	14.391 mi
Registration #3	2011-09-22	14.809 mi
Registration #4	2012-04-11	15.149 mi
Registration #5	2013-03-25	20.042 mi
Registration #6	2014-03-13	5.038 mi
Registration #7	2015-03-23	11.343 mi
Registration #8	2016-03-24	16.604 mi
Registration #9	2016-03-24	16.604 mi
Registration #10	2017-04-05	21.551 mi
Registration #11	2018-05-20	25.277 mi
Registration #12	2019-05-20	25.277 mi
Registration #13	2020-05-20	25.277 mi
Registration #14	2021-05-20	25.277 mi
Registration #15	2022-05-20	25.277 mi
Registration #16	2023-05-20	25.277 mi
Registration #17	2024-03-28	25.277 mi
Registration #18	2024-03-28	25.277 mi
Registration #19	2024-03-28	25.277 mi
Registration #20	2024-03-28	25.277 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4252 mm
Wheel base	2640 mm
Kerb weight	1289 kg
Max. allowed weight	1700 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	153102