



General information

Make	MINI
Model	COUNTRYMAN COOPER SD ALL4
Colour	Black
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	330 Nm at 1.750 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D






Internet history

Entry 1

Date	2022-02-11
Pictures	5
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2023-11-03
MOT pass rate	64 %
MOT passed	9
Failed MOT tests	5
Total advice items	14
Total items failed	17

MOT #14	2022-11-01 10:54
MOT test number	573997787084
Result	✓ Passed
Next expiry date	2023-11-03
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))
Advice	Offside Front head lamp mount 1 of 2 broken but head light not insecure

MOT #13	2022-11-01 10:54
MOT test number	588434258177
Result	✗ Failed
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))
Advice	Offside Front head lamp mount 1 of 2 broken but head light not insecure
Advice	Offside Front Seat belt slightly damaged (7.1.2 (b) (i))

MOT #12	2021-10-15 10:17
MOT test number	890900247375
Result	✓ Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2020-10-09 09:55**MOT test number** 992613560900**Result** ✓ Passed**Advice** Engine smoking from nearside possible breather**MOT #10** 2019-11-04 14:07**MOT test number** 956951896174**Result** ✓ Passed**MOT #9** 2018-10-16 16:35**MOT test number** 617983520230**Result** ✓ Passed**Advice** Advise wiper blades becoming smeary**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #8** 2018-10-16 08:06**MOT test number** 818492516743**Result** ✗ Failed**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Advise wiper blades becoming smeary**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Position lamp not working (4.2.1 (a))**Fail** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

**MOT #7** 2017-07-04 15:54**MOT test number** 200613570222**Result** ✓ Passed**Advice** Tyre pressure monitoring system warning lamp does not illuminate (4.1.D.4)**MOT #6** 2016-07-02 08:03**MOT test number** 875828230397**Result** ✓ Passed**MOT #5** 2016-06-30 12:59**MOT test number** 868234450996**Result** ✗ Failed**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure 2254518 runflat (4.1.D.1b)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**MOT #4** 2015-06-23 13:55**MOT test number** 897304175189**Result** ✓ Passed

**MOT #3**

2015-06-23 08:51

MOT test number

218234875499

Result**✗ Failed****Notice** Advise handbrake travel becoming long**Fail** Horn not working (1.6.2a)**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**Notice** Advise brake warning light on**Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #2**

2014-07-02 12:18

MOT test number

156933584145

Result**✓ Passed****MOT #1**

2014-07-01 10:19

MOT test number

626972384106

Result**✗ Failed****Fail** Offside Front position lamp(s) not working (1.1.A.3b)**Fail** Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Fail** Windscreen has a sticker or other obstruction encroaching into the swept area by more than 40mm outside zone 'A' (8.3.1e)



Tax & MOT check

✕
Untaxed

Tax expired:
31 January 2023

✕
MOT

Expired:
3 November 2023

Tax status	Expired at 31 January 2023
Days left	454 days too late
MOT expiry date	3 November 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-06-17
Last registration	2022-11-01
Complete history	See info



Registration #1	2011-06-17	27 mi
Registration #2	2014-07-01	41.734 mi
Registration #3	2014-07-02	41.734 mi
Registration #4	2015-06-23	59.359 mi
Registration #5	2015-06-23	59.359 mi
Registration #6	2016-06-30	78.508 mi
Registration #7	2016-07-02	78.608 mi
Registration #8	2017-07-04	94.507 mi
Registration #9	2019-06-20	151.277 mi
Registration #10	2019-06-20	151.277 mi
Registration #11	2019-06-20	151.277 mi
Registration #12	2019-06-20	151.277 mi
Registration #13	2019-06-20	151.277 mi
Registration #14	2019-06-20	151.277 mi
Registration #15	2019-06-20	151.277 mi
Registration #16	2022-11-01	215.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	2005 mm
Height	1557 mm
Length	4299 mm
Wheel base	2670 mm
Kerb weight	1365 kg
Max. allowed weight	1855 kg

Additional information

Fuel tank capacity	51 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	4

Engine number

71407850