



report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	POLO GT TSI DSG
Colour	Blue
Year of manufacture	2009
Top speed	137 mph
0 - 60 mph	8.0 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	160 BHP
Max. torque	240 Nm at 2.000 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-06-03
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-07-13
MOT pass rate	92 %
MOT passed	12
Failed MOT tests	1
Total advice items	26
Total items failed	2

MOT #13 2023-07-14 13:17

MOT test number 800993719253

Result ✓ Passed

Next expiry date 2024-07-13

Advice Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i))

Advice Suspension component corroded but not seriously weakened (5.3.3 (b) (i))

Advice Exhaust has a minor leak of exhaust gases back box (6.1.2 (a))

MOT #12 2022-05-26 08:35

MOT test number 779403259031

Result ✓ Passed

Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated small split but not letting dirt in (6.1.7 (g) (i))

Advice Exhaust silencer slightly loose rear box outer skin rusty and coming adrift (8.1.1 (b) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge at 2.2 mm centre tread (5.2.3 (e))

MOT #11 2021-06-10 07:19

MOT test number 722755700795

Result ✓ Passed

**MOT #10** 2020-12-19 11:22**MOT test number** 246056104626**Result** ✓ Passed**MOT #9** 2020-12-18 09:31**MOT test number** 381880371676**Result** ✗ Failed**Fail** Offside Front Headlamp aim too high (4.1.2 (a))**Fail** Nearside Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #8** 2019-12-07 10:35**MOT test number** 854850342429**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush split (5.3.4 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))**Advice** Offside Play in steering rack inner joint(s)**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #7** 2018-12-11 11:32**MOT test number** 315971190044**Result** ✓ Passed

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Advice** Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #6 2017-12-19 10:25**MOT test number** 759121112278**Result** ✓ Passed

- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

MOT #5 2016-12-23 10:27**MOT test number** 235424792697**Result** ✓ Passed**MOT #4** 2016-01-12 09:23**MOT test number** 149331053140**Result** ✓ Passed

- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)

MOT #3 2015-01-05 08:47**MOT test number** 125295305424**Result** ✓ Passed

- Notice** Under-trays fitted obscuring some underside components



MOT #2	2014-01-25 09:18
MOT test number	857935824001
Result	✓ Passed
Advice	Front Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Notice	All 4 tyres cracking

MOT #1	2012-10-31 11:07
MOT test number	515555002398
Result	✓ Passed
Notice	Thorn in N/S Rear Tyre
Advice	Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 July 2024

Tax status	Valid until 1 August
Days left	94
MOT expiry date	13 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	HW59KPZ
Plate since	2019-03-29
Current registration	HW59KPZ
Plate since	2019-03-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-12-30
Last registration	2023-07-14
Complete history	See info



Registration #1	2009-12-30	23 mi
Registration #2	2012-10-31	12.271 mi
Registration #3	2014-01-25	19.084 mi
Registration #4	2015-01-05	21.771 mi
Registration #5	2016-01-12	24.856 mi
Registration #6	2016-12-23	28.570 mi
Registration #7	2017-12-19	34.667 mi
Registration #8	2018-12-11	46.821 mi
Registration #9	2019-05-20	55.377 mi
Registration #10	2019-05-20	55.377 mi
Registration #11	2019-05-20	55.377 mi
Registration #12	2019-05-20	55.377 mi
Registration #13	2019-05-20	55.377 mi
Registration #14	2019-05-20	55.377 mi
Registration #15	2019-05-20	55.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	97%
Children	84%
Pedestrian	61%
Safety systems	71%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1786 mm
Height	1479 mm
Length	4199 mm
Wheel base	2578 mm
Kerb weight	1286 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	5
Number of axles	2
Engine number	CAV 129813