





report date: 2024-03-29

General information

| Make | MINI |
|---------------------|----------------|
| Model | ONE ONE D |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 118 mph |
| 0 - 60 mph | 11.0 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 94 BHP |
|-------------------------|---------------------|
| Max. torque | 220 Nm at 1.496 rpm |
| Engine capacity | 1.496 cc |
| Cylinders | 3 |
| Fuel type | Diesel |
| Consumption city | 72.4 mpg |
| Consumption extra urban | 91.1 mpg |
| Consumption combined | 83.1 mpg |
| CO2 emission | 89 g/km |
| CO2 label | Α |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-07-03


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2025-04-22 |
|--------------------|------------|
| MOT pass rate | 75 % |
| MOT passed | 6 |
| Failed MOT tests | 2 |
| Total advice items | 21 |
| Total items failed | 2 |

| MOT #8 | 2024-04-23 12:37 |
|------------------|------------------|
| MOT test number | 835893256283 |
| Result | ✓ Passed |
| Next expiry date | 2025-04-22 |

| MOT #7 | 2022-08-02 15:18 |
|---|---------------------|
| MOT test number | 924840355941 |
| Result | ✓ Passed |
| Minor Nearside Front Windscreen damaged but not adversely affecting driver's view s | stone chip (3.2 (a) |
| Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i)) | |
| Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

CarCheck.co.uk page 3/12



MOT #6 2022-08-02 15:18

MOT test number 973684724518

Result X Failed

Minor Nearside Front Windscreen damaged but not adversely affecting driver's view stone chip (3.2 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Minor Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Pass with rectification Front Headlamp aim too low both sides (4.1.2 (a))

MOT #5 2021-05-25 09:24

MOT test number 405688306545

Result \sqrt{Passed}

Advice Rear Tyre slightly damaged/cracking or perishing Both (5.2.3 (d) (ii))

MOT #4 2020-05-26 12:26

MOT test number 504481340070

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Lower possible boost leak from inter cooler system

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/12



Result

Result

CV15WKL report date: 2024-03-29

X Failed

Passed

 MOT #3
 2019-04-15 13:23

 MOT test number
 351151719584

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #2 2019-04-15 13:23

MOT test number 260181763707

Pass with rectification Nearside Headlamp aim too far to the right (4.1.2 (a))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1 2018-03-26 15:44

MOT test number 817359324394

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 August |
|------------------|----------------------|
| Days left | 94 |
| MOT expiry date | 22 April 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

| o mile motory | |
|--|-------------|
| For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report | |
| | |
| manuse and a second sec | |
| | |
| ************ | |
| | |
| ********* | |
| | |
| *************************************** | |
| | |
| | More info > |
| | |
| Plate changes | |
| See in this check if this MINI had different number plates. | |
| See in this check if this Mini had different humber plates. | |
| | |
| Number of plates | |
| | |
| Current registration | UK UK |
| Plate since | |
| | |
| Current registration | UK UK |
| Plate since | |
| | |
| | More info > |
| | |

CarCheck.co.uk page 9/12



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 10 |
| First mileage registration | 2015-04-18 |
| Last registration | 2024-04-23 |
| Complete history | See info |



| Registration #1 | 2015-04-18 | 24 mi |
|---------------------------------|------------|-------------------------------------|
| Registration #2 | 2018-03-26 | 44.461 mi |
| Registration #3 | 2019-04-15 | 50.020 mi |
| Registration #4 | 2019-04-15 | 50.020 mi |
| Registration #5 | 2020-05-26 | 55.895 mi |
| | | |
| Registration #6 | | 11.777 es |
| Registration #6 Registration #7 | | 11.777 es |
| | | 11.77 m |
| Registration #7 | | 11.777 ea 11.777 ea 11.777 ea |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 1727 mm |
|---------------------|---------|
| Height | 1414 mm |
| Length | 3821 mm |
| Wheel base | 2495 mm |
| Kerb weight | 1225 kg |
| Max. allowed weight | 1595 kg |

Additional information

| Fuel tank capacity | 44 |
|-----------------------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 12/12 |

Number of axles 2

Engine number 50209063