



RENAULT

UK

FLI6XYA

report date: 2024-03-29

General information

Make	RENAULT
Model	ZOE DYNAMIQUE NAV
Colour	White
Year of manufacture	2016
Top speed	84 mph
Gearbox	1 speed automatic

Engine & fuel consumption

Power	91 BHP
Max. torque	220 Nm at 2.500 rpm
Fuel type	Electricity



LABEL UNKNOWN



Internet history



Entry 2

Date	2022-01-19
Pictures	0
Listing price	View report

source: yesauto.com

Entry 1

Date	2021-10-20
Pictures	4
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2024-10-16
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	11
Total items failed	2

MOT #8	2023-10-17 13:40
MOT test number	962203693938
Result	✓ Passed
Next expiry date	2024-10-16
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Cracking on treads (5.2.3 (d) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Cracking on treads (5.2.3 (d) (ii))

MOT #7	2023-10-17 10:43
MOT test number	672129823909
Result	✗ Failed
Fail	Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords 2 cuts to tread and worn on inner edge close to required limits (5.2.3 (d) (i))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing Cracking on treads (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing Cracking on treads (5.2.3 (d) (ii))

MOT #6	2022-10-05 11:34
MOT test number	796726011111
Result	✓ Passed

**MOT #5** 2021-11-05 10:07**MOT test number** 200185796226**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing no edges (5.2.3 (d) (ii))**Advice** Nearside Front Anti-roll bar ball joint has slight play very slight (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing on edges (5.2.3 (d) (ii))**MOT #4** 2021-11-04 11:38**MOT test number** 318724301340**Result** ✗ Failed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing no edges (5.2.3 (d) (ii))**Fail** Offside Headlamp insecure (4.1.1 (c))**Advice** Nearside Front Anti-roll bar ball joint has slight play very slight (5.3.4 (a) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing on edges (5.2.3 (d) (ii))**MOT #3** 2020-11-16 16:37**MOT test number** 785438096453**Result** ✓ Passed**MOT #2** 2020-03-20 13:26**MOT test number** 265807424730**Result** ✓ Passed**MOT #1** 2019-03-20 12:35**MOT test number** 836436195939**Result** ✓ Passed**Advice** Under covers underneath restricting view



Tax & MOT check

×

Untaxed

Tax expired:
20 April 2024

✓

MOT

Expires:
16 October 2024

Tax status	Expired at 20 April 2024
Days left	10 days too late
MOT expiry date	16 October 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	FL16XYA
Plate since	2019-03-29
Current registration	FL16XYA
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2016-03-15
Last registration	2023-10-17
Complete history	See info



Registration #1	2016-03-15	9 mi
Registration #2	2019-03-20	6.903 mi
Registration #3	2020-03-20	11.801 mi
Registration #4	2020-11-16	12.679 mi
Registration #5	2020-03-20	11.801 mi
Registration #6	2021-11-04	14.304 mi
Registration #7	2020-03-20	11.801 mi
Registration #8	2020-03-20	11.801 mi
Registration #9	2020-03-20	11.801 mi
Registration #10	2020-03-20	11.801 mi
Registration #11	2020-03-20	11.801 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	89%
Children	80%
Pedestrian	66%
Safety systems	85%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1730 mm
Height	1562 mm
Length	4084 mm
Wheel base	2588 mm
Kerb weight	1468 kg
Max. allowed weight	1949 kg

Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

C019188