





report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS
Colour	Silver
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	165 Nm at 4.000 rpm
Engine capacity	1.798 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	Н



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 3

Date 2024-02-27

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date 2022-12-22

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date 2021-07-14

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT expiry date	2024-10-30
MOT pass rate	67 %
MOT passed	8
Failed MOT tests	4
Total advice items	13
Total items failed	8

MOT #12		2023-10-19 17:06
MOT test	number	568044054916
Result		✓ Passed
Next expi	ry date	2024-10-30
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii) Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))))


MOT #11	2023-10-18 10:34	
MOT test number	373203767738	
Result	X Failed	
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress		
of dirt (6.1.7 (g) (ii)) Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))		

MOT #10	2022-10-31 16:49
MOT test number	715924757979
Result	✓ Passed
Advice Covers Fitted	

CarCheck.co.uk page 3/12



report date: 2024-03-29



MOT test number

112956937591

Result

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

MOT #7	2018-10-17 14:31
MOT test number	996846477796
Result	✓ Passed

MOT #6	2018-10-17 08:50
MOT test number	270579619215
Result	X Failed
Fail Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))	
Fail Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i)))
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail Nearside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5		2017-11-09 09:49
MOT test	number	139479988523
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit 205/55/16 (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit 205/55/16 (4.1.E.1)	

MOT #4	2016-11-14 11:37
MOT test number	359196693629
Result	✓ Passed
MOT #3	2016-01-15 11:30
MOT test number	655661310632
Result	✓ Passed

MOT #2		2015-01-06 10:02
MOT test number		558696705081
Result		✓ Passed
MOT #1		2015-01-06 10:02
MOT test number		119806505030
Result		X Failed
Pass with rectification	Front Brake pad(s) less than 1.5 mm thick (3.5.1g)	

CarCheck.co.uk page 5/12



CA61FNM report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 April
Days left	337
MOT expiry date	30 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

CA61FNM

report date: 2024-03-29

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u> .	Α

Plate changes

See in this check if this MAZDA had different number plates.	
Number of plates	
Current registration	SIE (
Plate since	UN CONTRACTOR
Current registration	ZAIN UK
Plate since	mn.n.n

More info >

More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-01-27
Last registration	2023-10-19
Complete history	See info



Registration #1	2012-01-27	15 mi
Registration #2	2015-01-06	40.329 mi
Registration #3	2016-01-15	54.277 mi
Registration #4	2016-11-14	66.484 mi
Registration #5	2017-11-09	74.117 mi
Registration #6	2018-10-17	81.049 mi
Registration #7	2018-10-17	81.049 mi
Registration #8	2019-10-23	90.036 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		11.117 es

More info >

CarCheck.co.uk page 11/12



CA61FNM report date: 2024-03-29

Safety ratings

NCAP rating	***
-------------	-----

Video <u>see crash video</u>



Dimensions & weight

Width	1750 mm
Height	1615 mm
Length	4585 mm
Wheel base	2750 mm
Kerb weight	1470 kg
Max. allowed weight	2085 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	L8 10222567

CarCheck.co.uk page 12/12