





report date: 2024-03-29

General information

Make	MINI
Model	COUNTRYMAN COOPER S ALL4A COOPER S ALL4
Colour	Red
Year of manufacture	2011
Top speed	127 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	36.7 mpg
CO2 emission	180 g/km
CO2 label	I



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 3

Date 2021-09-22

Pictures 20

Listing price <u>View report</u>









source: cargurus.co.uk


Entry 2

Date 2021-09-20

Pictures 28

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 1

Date 2021-09-15


Pictures 8

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-31
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	10
Total items failed	8

MOT #16	2023-08-01 09:20
MOT test number	538253092023
Result	✓ Passed
Next expiry date	2024-07-31

MOT #15		2022-10-11 15:56
MOT test	number	570168532216
Result		✓ Passed
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	

MOT #14	2021-10-11 13:07
MOT test number	285338650523
Result	✓ Passed

MOT #13	2021-10-06 14:44
MOT test number	204936200761
Result	X Failed
Fail Oil leaking excessively from engine (8.4.1 (a) (i))	
Fail Emissions not tested (8.2.1.2 (d))	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12 2021-01-18 13:54

MOT test number 205654939238

MOT #11 2020-01-15 13:09

MOT test number 420881852277

Result Passed

Advice Rear wiper blade split

MOT #10 2020-01-14 10:41

MOT test number 314626702120

Result X Failed

Fail Nearside Headlamp aim too high (4.1.2 (a))

Advice Both rear tyres worn close to legal limit

Fail Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Both front tyres worn close to legal limit

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Rear wiper blade split

Fail Offside Rear Tyre has a bulge, caused by separation or partial failure of its structure bulging in tread (5.2.3 (d) (ii))

MOT #9 2019-01-16 10:36

MOT test number 875668397119

Result ✓ Passed

MOT #8 2018-01-24 15:41

MOT test number 847197434713

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7		2017-01-05 14:37
MOT test number		452011281264
Result		✓ Passed
MOT #6		2017-01-05 14:37
MOT test number		122592722424
Result		× Failed
Pass with rectification	Nearside Registration plate lamp not working (1.1.C.1d)	

MOI #5	2010-01-19 10:44
MOT test number	603847074229
Result	✓ Passed
MOT #4	2015-01-15 10:55
MOT test number	938065915046
Result	✓ Passed
MOT #3	2014-10-21 14:57

MOT #3	2014-10-21 14:57
MOT test number	457594794297
Result	✓ Passed
Notice Under-trays fitted obscuring some underside components Notice Engine covers fitted obscuring some components in the engine bay	

MOT #2	2014-01-17 11:21
MOT test number	909827114063
Result	✓ Passed
Notice Nail in nearside front tyre	

CarCheck.co.uk page 5/13



report date: 2024-03-29



CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	31 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I		e?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2011-01-19
Last registration	2023-08-01
Complete history	See info



Registration #1	2011-01-19	19 mi
Registration #2	2014-01-17	23.251 mi
Registration #3	2014-10-21	27.630 mi
Registration #4	2015-01-15	28.531 mi
Registration #5	2016-01-19	32.233 mi
Registration #6	2017-01-05	357.453 mi
Registration #7	2017-01-05	357.453 mi
Registration #8	2018-01-24	39.208 mi
Registration #9	2019-01-16	42.400 mi
Registration #10	2020-01-14	45.768 mi
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		91.777 esi
Registration #18		11.777 es
Registration #19		11.177 ms

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-29

Car features

S0225	Air conditionir
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4110 mm
Kerb weight	1405 kg
Max. allowed weight	1865 kg

Additional information

Fuel tank capacity	47 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles CarCheck.co.uk	2 page 13/13

Engine number

A738J098