




report date: 2024-03-29

General information

Make	VOLVO
Model	C30 D DRIVE R-DESIGN
Colour	Orange
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	240 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-12-21
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	27
Total items failed	5

MOT #15	2023-11-09 09:03
MOT test number	983221238543
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #14	2023-11-08 12:17
MOT test number	320117839264
Result	✗ Failed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm Tyres has inner side wall damage (5.2.3 (e))
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #13**

2022-11-04 13:10

MOT test number

618008290527

Result

✓ Passed

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))**MOT #12**

2022-11-04 13:10

MOT test number

991438349523

Result

✗ Failed

Advice Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))**MOT #11**

2021-10-20 15:10

MOT test number

811743543804

Result

✓ Passed

Advice Offside Front Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))

**MOT #10** 2021-10-15 16:09**MOT test number** 469189061286**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))**Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge BALD INNER EDGE (5.2.3 (e))**Fail** Nearside Headlamp light intensity severely reduced (4.1.4 (a))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9** 2020-10-09 15:40**MOT test number** 803714689813**Result** ✓ Passed**MOT #8** 2019-10-11 12:12**MOT test number** 758481198218**Result** ✓ Passed**MOT #7** 2018-09-22 17:14**MOT test number** 749227679061**Result** ✓ Passed**MOT #6** 2017-09-22 13:07**MOT test number** 919018149202**Result** ✓ Passed**Advice** Under tray fitted**Advice** Engine cover fitted

**MOT #5** 2017-09-22 09:06**MOT test number** 691835096379**Result** ✗ Failed**Fail** Offside Front Inner Tyre has ply or cords exposed edge (4.1.D.1b)**Advice** Under tray fitted**Advice** Engine cover fitted**Advice** Nearside Front Inner Tyre worn close to the legal limit edge (4.1.E.1)**MOT #4** 2016-10-19 14:32**MOT test number** 410705317974**Result** ✓ Passed**MOT #3** 2015-10-23 08:38**MOT test number** 973104168584**Result** ✓ Passed**MOT #2** 2014-10-20 09:36**MOT test number** 176053394253**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #1** 2013-10-28 16:40**MOT test number** 665601903389**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 January
Days left	246
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2010-11-19
Last registration	2023-11-09
Complete history	See info



Registration #1	2010-11-19	15 mi
Registration #2	2013-10-28	27.980 mi
Registration #3	2014-10-20	36.845 mi
Registration #4	2015-10-23	45.022 mi
Registration #5	2016-10-19	49.901 mi
Registration #6	2017-09-22	61.820 mi
Registration #7	2017-09-22	61.822 mi
Registration #8	2018-09-22	72.365 mi
Registration #9	2019-10-11	89.281 mi
Registration #10	2020-05-20	95.377 mi
Registration #11	2020-05-20	95.377 mi
Registration #12	2020-05-20	95.377 mi
Registration #13	2020-05-20	95.377 mi
Registration #14	2020-05-20	95.377 mi
Registration #15	2020-05-20	95.377 mi
Registration #16	2020-05-20	95.377 mi
Registration #17	2020-05-20	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1457 mm
Length	4522 mm
Wheel base	2640 mm
Kerb weight	1442 kg
Max. allowed weight	1900 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	957553