



report date: 2024-03-28

General information

Make	CITROEN
Model	DISPATCH 1200 L2H1 ENTERPRISE HDI
Colour	White
Year of manufacture	2015
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	126 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	44.1 mpg
CO2 emission	168 g/km
CO2 label	H





Internet history

Entry 1

Date	2022-01-06
Pictures	6
Listing price	View report

CLARENCE

£188.80

CLARENCE	
CASH PRICE	£1,700.00 + VAT
DEPOSIT	£1,344.00
TOTAL AMOUNT OF CREDIT	£16,800.00
TOTAL AMOUNT PAYABLE	£20,442.48
ADMINISTRATION FEE	£144.00
OPTION TO PURCHASE FEE	£11.00
FIXED INTEREST RATE	6.25% PA
REPRESENTATIVE APR	17% APR
DURATION OF AGREEMENT	48 MONTHS
INITIAL PAYMENT	£188.81
48 MONTHLY PAYMENTS	£188.80
FINAL PAYMENT	£188.80

JUST ARRIVED

PHOTOS COMING SOON

6M AA WARRANTY + 12M AA BREAK DOWN COVER

Click & Deliver

Complete your deal online or by phone.
Then arrange for the sanitised vehicle to be delivered to you.

Visit our website for more info

AA

You're in safe hands

This dealer has signed our Dealer Promise

source: cargurus.co.uk



MOT history

MOT expiry date	2024-11-08
MOT pass rate	60 %
MOT passed	6
Failed MOT tests	4
Total advice items	38
Total items failed	2

MOT #10	2023-11-07 15:51
MOT test number	976705615833
Result	✓ Passed
Next expiry date	2024-11-08
Advice	Nearside Front Inner v/c clip missing
Minor	Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
Advice	Nearside Rear Exhaust mounting defective (6.1.2 (a))
Minor	Rear Registration plate lamp inoperative in the case of multiple lamps or light sources both (4.7.1 (b) (i))

**MOT #9** 2023-11-07 10:45**MOT test number** 333165435575**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin both (1.1.13 (a) (ii))**Advice** Nearside Front Inner v/c clip missing**Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))**Advice** Nearside Rear Exhaust mounting defective (6.1.2 (a))**DANGEROUS** Offside Rear Parking (secondary brake) on a single line braking system has no recorded effort at a wheel (1.3.1 (a) (ii))**Advice** Offside Rear brake caliper defective**Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources both (4.7.1 (b) (i))**Advice** Front Brake fluid close to minimum mark (1.1.10 (d) (ii))**MAJOR** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**MOT #8** 2022-11-07 10:21**MOT test number** 896979797054**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2021-11-08 16:13**MOT test number** 830722557359**Result** ✓ Passed

**MOT #6** 2021-11-07 17:12**MOT test number** 394533370924**Result** ✗ Failed**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a) (ii))**MAJOR** Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**Pass with rectification** Nearside Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MOT #5** 2020-11-02 10:31**MOT test number** 436296983774**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4** 2020-10-28 10:17**MOT test number** 677696222276**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MAJOR** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))**MAJOR** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**MAJOR** Offside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**MOT #3** 2019-10-23 15:32**MOT test number** 191365272945**Result** ✓ Passed



MOT #2	2018-11-09 15:09
MOT test number	232192779075
Result	✓ Passed
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #1	2018-11-05 13:01
MOT test number	985029760927
Result	✗ Failed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Front Registration plate insecure but not likely to fall off (0.1 (a))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
MAJOR	Brake pedal anti-slip provision missing (1.1.2 (c))
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
MAJOR	Nearside Front Position lamp not working (4.2.1 (a))
MAJOR	Nearside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
MAJOR	Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
MAJOR	Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
MAJOR	Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
MAJOR	Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
8 November 2024

Tax status	Valid until 1 August
Days left	95
MOT expiry date	8 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	LD65VRP
Plate since	2019-09-29
Current registration	LD65VRP
Plate since	2019-09-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2015-12-10
Last registration	2023-11-07
Complete history	See info



Registration #1	2015-12-10	23 mi
Registration #2	2018-11-05	78.647 mi
Registration #3	2018-11-09	78.647 mi
Registration #4	2019-10-23	93.713 mi
Registration #5	2020-10-28	110.780 mi
Registration #6	2020-11-02	110.780 mi
Registration #7	2020-11-02	110.780 mi
Registration #8	2020-11-02	110.780 mi
Registration #9	2020-11-02	110.780 mi
Registration #10	2020-11-02	110.780 mi
Registration #11	2020-11-02	110.780 mi
Registration #12	2020-11-02	110.780 mi

More info >



Dimensions & weight

Width	1895 mm
Height	1942 mm
Length	5135 mm
Kerb weight	1732 kg
Max. allowed weight	2932 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Number of axles	2
Engine number	DYZG4158506