





General information

| Make | VOLVO |
|---------------------|--------------------|
| Model | XC90 D5 ACTIVE AWD |
| Colour | Grey |
| Year of manufacture | 2010 |
| Top speed | 121 mph |
| 0 - 60 mph | 10.3 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 185 BHP |
|-------------------------|---------------------|
| Power | TOD PHP |
| Max. torque | 400 Nm at 2.000 rpm |
| Engine capacity | 2.400 cc |
| Cylinders | 5 |
| Fuel type | Diesel |
| Consumption city | 26.4 mpg |
| Consumption extra urban | 40.9 mpg |
| Consumption combined | 34.0 mpg |
| CO2 emission | 219 g/km |
| CO2 label | К |





MOT history

| MOT expiry date | 2025-03-22 |
|--------------------|------------|
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 0 |
| Total items failed | 2 |

| MOT #13 | 2024-03-11 09:20 |
|------------------|------------------|
| MOT test number | 133186307794 |
| Result | ✓ Passed |
| Next expiry date | 2025-03-22 |

| MOT #12 | 2024-03-11 09:20 |
|-------------------------|---|
| MOT test number | 467512395893 |
| Result | × Failed |
| Pass with rectification | Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c)) |

| MOT #11 | 2023-02-23 09:28 |
|-----------------|------------------|
| MOT test number | 754329415431 |
| Result | ✓ Passed |
| | |

| MOT #10 | 2022-03-04 09:45 |
|-----------------|------------------|
| MOT test number | 583389019756 |
| Result | ✓ Passed |

| MOT #9 | 2021-03-23 11:34 |
|-----------------|------------------|
| MOT test number | 142321806131 |
| Result | ✓ Passed |





| MOT #8 | 2020-01-06 14:12 |
|-----------------|------------------|
| MOT test number | 541299594176 |
| Result | ✓ Passed |
| | |
| MOT #7 | 2019-01-11 16:32 |
| MOT test number | 992500568620 |
| Result | ✓ Passed |
| | |

| МОТ #6 | 2019-01-11 14:43 |
|--|------------------|
| MOT test number | 120335080271 |
| Result | 🗙 Failed |
| Fail Nearside Seat belt buckle not functioning as intended centre row outer (7.1.2 (d)) | |

| MOT #5 | 2018-01-12 11:32 |
|-----------------|------------------|
| MOT test number | 478062164204 |
| Result | ✓ Passed |

| МОТ #4 | 2017-01-12 17:38 |
|-----------------|------------------|
| MOT test number | 343632490228 |
| Result | ✓ Passed |

| MOT #3 | 2015-12-22 14:02 |
|-----------------|------------------|
| MOT test number | 724171732044 |
| Result | ✓ Passed |

| MOT #2 | 2015-01-09 13:22 |
|-----------------|------------------|
| MOT test number | 219329005065 |
| Result | ✓ Passed |





| MOT #1 | 2014-01-10 15:46 |
|-----------------|------------------|
| MOT test number | 367910314000 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ | √ |
|------------------|---------------------|
| Taxed | мот |
| Tax due: | Expires: |
| 1 April 2025 | 22 March 2025 |
| Tax status | Valid until 1 April |
| Days left | 336 |
| MOT expiry date | 22 March 2025 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | К |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|----------|
| Date | FEIDO |
| Category | 4. ARMPE |
| Туре | |
| Damage 2 | AMPL |
| | F Stores |
| Date | 1.E |
| Category | ante |
| Туре | |

Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4.00.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ******* | |
| ********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this VOLVO had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Current registration | |
| Plate since | |
| | |





Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 14 |
| First mileage registration | 2010-12-31 |
| Last registration | 2024-03-11 |
| Complete history | See info |



| Registration #1 | 2010-12-31 | 11 mi |
|---|------------|--|
| Registration #2 | 2014-01-10 | 9.063 mi |
| Registration #3 | 2015-01-09 | 11.652 mi |
| Registration #4 | 2015-12-22 | 13.114 mi |
| Registration #5 | 2017-01-12 | 14.762 mi |
| Registration #6 | 2018-01-12 | 16.455 mi |
| Registration #7 | 2019-01-11 | 18.181 mi |
| Deviaturation #0 | | |
| Registration #8 | | |
| Registration #9 | | 11.227 mi |
| | | 10.000 est |
| Registration #9 | | 10.000 est 10.000 est 10.000 est |
| Registration #9 Registration #10 | | 00.000 est 00.000 est 00.000 est 00.000 est |
| Registration #9 Registration #10 Registration #11 | | 00.000 est 00.000 est 00.000 est 00.000 est 00.000 est |





Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

NCAP rating

Video

**** see crash video



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1898 mm |
| Height | 1784 mm |
| Length | 4798 mm |
| Wheel base | 2857 mm |
| Kerb weight | 2114 kg |
| Max. allowed weight | 2740 kg |
| Additional information | |
| Fuel tank capacity | 68 I |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 7 page 11/11 |

| Number of axles | 2 |
|-----------------|--------|
| Engine number | 839292 |