




report date: 2024-03-29

General information

| | |
|---------------------|---------------------------|
| Make | LAND ROVER |
| Model | FREELANDER SD4 HSE LUXURY |
| Colour | Black |
| Year of manufacture | 2013 |
| Top speed | 118 mph |
| 0 - 100 km/h | 11.2 seconds |
| 0 - 60 mph | 8.7 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------------|
| Power | 110 kW / 150 HP / 190 BHP |
| Max. torque | 420 Nm at 1.750 rpm |
| Engine capacity | 2.179 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 32.5 mpg |
| Consumption extra urban | 49.6 mpg |
| Consumption combined | 40.4 mpg |
| CO2 emission | 185 g/km |
| CO2 label | I |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-12-24 |
| Pictures | 43 |
| Listing price | View report |



source: [autotrader.co.uk](#)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-03 |
| MOT pass rate | 69 % |
| MOT passed | 9 |
| Failed MOT tests | 4 |
| Total advice items | 26 |
| Total items failed | 5 |

| | |
|------------------|------------------|
| MOT #13 | 2023-12-04 15:38 |
| MOT test number | 479546886247 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-03 |

| | |
|-----------------|---|
| MOT #12 | 2023-01-17 10:54 |
| MOT test number | 507402116824 |
| Result | ✓ Passed |
| Advice | Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i)) |

| | |
|-----------------|------------------|
| MOT #11 | 2022-01-18 16:41 |
| MOT test number | 624923081838 |
| Result | ✓ Passed |

| | |
|-----------------|---|
| MOT #10 | 2022-01-14 09:52 |
| MOT test number | 938477947905 |
| Result | ✗ Failed |
| Advice | Offside Front Steering rack has slight free play detected at steering wheel Tie rod (2.3 (a) (i)) |
| Fail | Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |

**MOT #9** 2021-11-10 16:04**MOT test number** 288568126181**Result** ✓ Passed

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Towball/hitch not fitted at time of test
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #8 2021-11-10 13:14**MOT test number** 761423687099**Result** ✗ Failed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Towball/hitch not fitted at time of test
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #7** 2020-11-17 13:38**MOT test number** 529282681166**Result** ✓ Passed**Minor** Offside Front Windscreen wiper blade defective slight split (3.4 (b) (i))**Advice** Offside Front Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #6** 2019-11-06 16:41**MOT test number** 390669733112**Result** ✓ Passed**Advice** Towball/hitch not fitted at time of test**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #5** 2019-11-01 10:20**MOT test number** 304736757224**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**Advice** Central Stop lamp(s) not working**Advice** Towball/hitch not fitted at time of test**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Offside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #4** 2018-11-07 15:09**MOT test number** 970287854079**Result** ✓ Passed



| | |
|---|------------------|
| MOT #3 | 2017-11-16 12:23 |
| MOT test number | 524725585236 |
| Result | ✓ Passed |
| MOT #2 | 2016-11-16 16:24 |
| MOT test number | 375206847705 |
| Result | ✓ Passed |
| MOT #1 | 2016-11-16 12:50 |
| MOT test number | 535544576491 |
| Result | ✗ Failed |
| <div><div>Advice</div> Front Brake pad(s) wearing thin (3.5.1g)</div> <div><div>Fail</div> Central Rear Stop lamp not working (1.2.1b)</div> <div><div>Advice</div> Rear Brake pad(s) wearing thin (3.5.1g)</div> | |



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
3 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 December |
| Days left | 215 |
| MOT expiry date | 3 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 49 |
| Band | I |
| Single payment (12 months) | £ 320,00,- |
| Single six month payment | £ 176,00,- |
| Total payable by 12 monthly instalments | £ 336,00,- |




Damage history

Check the damage history for this LAND ROVER. See if, where and when this LAND ROVER had damage and the car repair costs. We also check if this LAND ROVER was scrapped. Download the premium report [here](#) for the results.


Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra LAND ROVER salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this LAND ROVER in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this LAND ROVER? How many owners did this LAND ROVER have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|------------|
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |
| Owner | Start date |

More info >

Plate changes

See in this check if this LAND ROVER had different number plates.

| | |
|----------------------|----------------|
| Number of plates | 1 |
| Current registration | OV63VYK |
| Plate since | 2024-03-29 |
| Current registration | OV63VYK |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this LAND ROVER is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this LAND ROVER has been settled.

If not, and you buy this LAND ROVER then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this LAND ROVER is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 15 |
| First mileage registration | 2013-11-19 |
| Last registration | 2023-12-04 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2013-11-19 | 28 mi |
| Registration #2 | 2016-11-16 | 30.834 mi |
| Registration #3 | 2016-11-16 | 30.834 mi |
| Registration #4 | 2017-11-16 | 38.524 mi |
| Registration #5 | 2018-11-07 | 44.828 mi |
| Registration #6 | 2019-11-01 | 49.971 mi |
| Registration #7 | 2019-11-06 | 50.082 mi |
| Registration #8 | 2020-11-17 | 54.202 mi |
| Registration #9 | 2020-11-17 | 54.202 mi |
| Registration #10 | 2020-11-17 | 54.202 mi |
| Registration #11 | 2020-11-17 | 54.202 mi |
| Registration #12 | 2020-11-17 | 54.202 mi |
| Registration #13 | 2020-11-17 | 54.202 mi |
| Registration #14 | 2020-11-17 | 54.202 mi |
| Registration #15 | 2020-11-17 | 54.202 mi |

More info >



Safety ratings

| | |
|-------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 2180 mm |
| Height | 1740 mm |
| Length | 4500 mm |
| Wheel base | 2660 mm |
| Kerb weight | 1770 kg |
| Max. allowed weight | 2505 kg |

Additional information

| | |
|--------------------|------------------|
| Fuel tank capacity | 68 l |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | DZ784152302224DT |