





General information

Make	VOLKSWAGEN	
Model	CC GT TDI BLUEMOTION TECHNOLOGY DSG	
Colour	Blue	
Year of manufacture	2015	
Top speed	132 mph	
0 - 60 mph	9.8 seconds	
Gearbox	6 speed Semi Auto	

Engine & fuel consumption

Power	138 BHP
Max. torque	320 Nm at 1.750 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.1 mpg
Consumption extra urban	60.1 mpg
Consumption combined	53.3 mpg
CO2 emission	131 g/km
CO2 label	E







Internet history


Entry 1

Date Pictures 2021-11-06

20

Listing price

View report









source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-03
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	11
Total items failed	0

MOT #8	2024-01-20 10:58	
MOT test number	604496047217	
Result	🗸 Passed	
Next expiry date	2025-02-03	
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))		

MOT #7	2023-02-01 17:03
MOT test number	218160468480
Result	✓ Passed

МОТ #6	2022-02-01 12:30
MOT test number	214862014846
Result	✓ Passed

MOT #5		2021-02-04 09:25
MOT test	number	278917536097
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	





MOT #4		2020-01-23 10:15
MOT test numbe	er	342357444792
Result		✓ Passed
MOT #3		2019-01-30 14:51
MOT test numbe	er	433620528412
Result		✓ Passed
MOT #2		2019-01-30 11:03
MOT test numbe	er	335756296417
Result		🗙 Failed
MAJOR Offsic	de Headlamp aim too high (4.1.2 (a))	
DANGEROUS	Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
DANGEROUS	Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MAJOR Nears	side Headlamp aim too high (4.1.2 (a))	
DANGEROUS	Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))	
DANGEROUS	Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

MOT #1	2018-01-31 15:36
MOT test number	151188587918
Result	✓ Passed



Tax & MOT check

√ Taxed	✓ МОТ
Tax due: 1 January 2025	Expires: 3 February 2025
Tax status	Valid until 1 January
Days left	247
MOT expiry date	3 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-





Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDER
Category	Lamp
Туре	
Damage 2	AMPLE
Damage 2	E CONTROL ON
Date	S.
Category	AMPY
Туре	

Extra VOLKSWAGEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.700
Auction value	4 10.000
Average private trade value	4 10 700

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Format maintration	
Carrient registration	
Parla since	





Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info \rightarrow





Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-01-15
Last registration	2024-01-20
Complete history	See info



Registration #1	2015-01-15	19 mi
Registration #2	2018-01-31	28.874 mi
Registration #3	2019-01-30	39.311 mi
Registration #4	2019-01-30	39.311 mi
Registration #5	2020-01-23	48.926 mi
Registration #6		11.777 est
Registration #7		11.777 mi
Registration #8		11.777 esi
Registration #9		11.777 mi
Registration #10		00.000 and

More info >





Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	85%
Children	87%
Pedestrian	66%
Safety systems	76%
Overall rating	80%
Video	see crash video



Dimensions & weight		
Width	2090 mm	
Height	1421 mm	
Length	4902 mm	
Wheel base	2710 mm	
Kerb weight	1564 kg	
Max. allowed weight	2070 kg	
Additional information		
Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	4	
CarCheck.co.uk		page 11/11

Number of seats	5
Number of axles	2
Engine number	CFFBL40298