





report date: 2024-03-28

# General information

Make	MERCEDES-BENZ
Model	GLA GLA 220 D 4MATIC AMG LINE
Colour	Black
Year of manufacture	2016
Top speed	135 mph
0 - 100 km/h	7.7 seconds
0 - 60 mph	7.7 seconds
Gearbox	7 speed automatic

# Engine & fuel consumption

Power	130 kW / 177 HP / 174 BHP
Max. torque	350 Nm at 1.400 rpm
Engine capacity	2.143 cc
Cylinders	4
Fuel type	Diesel
Consumption city	47.9 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	130 g/km
CO2 label	D



CarCheck.co.uk page 1/12



report date: 2024-03-28

# Internet history

# Entry 3

Date 2023-05-15

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

# Entry 2

Date	2023-04-13
Pictures	5

Listing price <u>View report</u>










source: cargurus.co.uk

Entry 1

Date 2021-02-02

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT	histor	v
		,

MOT expiry date	2025-01-22
MOT pass rate	67 %
MOT passed	6
Failed MOT tests	3
Total advice items	11
Total items failed	4

MOT #9	2024-01-23 08:43
MOT test number	436725144291
Result	✓ Passed
Next expiry date	2025-01-22
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.	1.14 (a) (ii))

MOT #8	2024-01-22 16:36
MOT test number	245332147702
Result	<b>×</b> Failed
Fail Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))  Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (	ii))

MOT #7	2023-05-10 09:53
MOT test number	516749066060
Result	✓ Passed
MOT #6	2023-05-10 09:53
MOT test number	569446560063
Result	<b>×</b> Failed
Pass with rectification Headlamp aim too high (4.1.2 (a))	

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT test number

622095492346

Result

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #4** 2021-10-05 13:02 **MOT** test number 380071699753 Result ✓ Passed **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice Central Rear Brake pad(s) wearing thin (1.1.13 (a) (ii)) Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Advice Dpf fitted emissions to low to read Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #3
 2020-10-05 13:42

 MOT test number
 515042472691

 Result
 ✓ Passed

MOT #2 2020-09-28 16:53

MOT test number 236562136385

Result X Failed

Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

**Fail** Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/12



MOT #1 2019-09-13 14:54

**MOT test number** 293859745732

**Result** ✓ Passed

CarCheck.co.uk page 5/12



# Tax & MOT check



Tax status	Valid until 1 January
Days left	248
MOT expiry date	22 January 2025
Full MOT history	See MOT history

# Tax calculation

Vehicle class	49
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

# Damage history

Check the damage history for this MERCEDES-BENZ. See if, where and when this MERCEDES-BENZ had damage and the car repair costs. We also check if this MERCEDES-BENZ was scrapped. Download the premium report <a href="here">here</a> for the results.

#### Damage 1

Date	
Category	
Туре	
Damage 2	
Date	
Category	



#### Extra MERCEDES-BENZ salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

## Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES-BENZ in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

AO66GAA

report date: 2024-03-28

# For how long did the current and previous owner(s) have this MERCEDES-BENZ? How many owners did this MERCEDES-BENZ have? Check it in the premium report and see all owner registrations. Download the full report <a href="https://example.com/here">here</a>. More info >

# Plate changes

See in this check if this MERCEDES-BENZ had different number plates.

More info >

CarCheck.co.uk page 9/12



## Finance check

Check if this MERCEDES-BENZ is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES-BENZ has been settled.

If not, and you buy this MERCEDES-BENZ then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES-BENZ is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

**Contact info** 

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-09-29
Last registration	2024-01-23
Complete history	See info



Registration #1	2016-09-29	18 mi
Registration #2	2019-09-13	62.132 mi
Registration #3	2020-09-28	75.126 mi
Registration #4	2020-10-05	75.131 mi
Registration #5		91.777 es
Registration #6	2021-10-05	77.150 mi
Registration #7	2022-10-01	86.253 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		91.777 esi
Registration #12		11.777 es
Registration #13		D.377 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

# Car features

50225	Air conditionir
50295	
60482	
0501	
0566	
0567	
60569	

# Safety ratings

NCAP rating	****
Adult	93%
Children	81%
Pedestrian	67%
Safety systems	86%
Overall rating	85%
Video	see crash video



# Dimensions & weight

Width	1804 mm
Height	1494 mm
Length	4417 mm
Wheel base	2699 mm
Kerb weight	1595 kg
Max. allowed weight	2075 kg

# Additional information

Fuel tank capacity	56 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 12/12

CarCheck.co.uk page 12/12

Number of seats	5
Number of axles	2
Engine number	65193033688471