





report date: 2024-03-28

General information

Make	ТОҮОТА
Model	COROLLA VERSO VVT-I SR
Colour	Grey
Year of manufacture	2008
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	127 BHP
Max. torque	170 Nm at 4.200 rpm
Engine capacity	1.794 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	43.5 mpg
Consumption combined	36.7 mpg
CO2 emission	184 g/km
CO2 label	I



CarCheck.co.uk page 1/12



report date: 2024-03-28


Internet history


Entry 1

Date 2022-04-07

Pictures 54

Listing price <u>View report</u>









source: yesauto.com

CarCheck.co.uk page 2/12



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2025-04-21
MOT pass rate	88 %
MOT passed	14
Failed MOT tests	2
Total advice items	7
Total items failed	5

MOT #16	2024-04-22 12:44
MOT test number	203394129005
Result	✓ Passed
Next expiry date	2025-04-21

MOT #15	2024-04-22 11:16	
MOT test number	219222276838	
Result	★ Failed	
Fail Offside Front Position lamp not working (4.2.1 (a) (ii))		
Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))		
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))		

MOT #14	2023-01-26 11:21
MOT test number	648647888843
Result	✓ Passed
MOT #13	2022-01-17 16:47
MOT test number	655699470511
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #12 2021-01-19 11:26 110489304204 **MOT** test number Result ✓ Passed

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #11 2020-01-15 10:55 **MOT** test number 445295034765 Result ✓ Passed **Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10 2019-01-29 15:31 **MOT** test number 569862706492 Result ✓ Passed **Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a)) **Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #9 2018-01-10 15:54 979050672133 **MOT** test number Result Passed

MOT #8 2018-01-10 15:26 **MOT** test number 273658029426 Result × Failed

Fail Offside Front Outer Tyre has ply or cords exposed (4.1.D.1b) Fail

Nearside Front Outer Tyre has ply or cords exposed (4.1.D.1b)

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #7	2017-02-01 11:29
MOT test number	738645702864
Result	✓ Passed
MOT #6	2016-02-09 11:41
MOT test number	930428148791
Result	✓ Passed
MOT #5	2015-02-13 15:37
MOT test number	226754445038
Result	✓ Passed
MOT #4	2014-01-07 12:57
MOT test number	598637104012
Result	✓ Passed
MOT #3	2013-01-10 15:57
MOT test number	386060113002
Result	✓ Passed

MOT #2	2012-01-04 15:06
MOT test number	575784902061
Result	✓ Passed
NOT #3	2011 02 11 11 10
MOT #1	2011-03-11 11:16
MOT test number	115660771417
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 April
Days left	336
MOT expiry date	21 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 6/12



DY08FGZ report date: 2024-03-28

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full		ΓΑ

	More info	>
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	NK NK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



DY08FGZ report date: 2024-03-28

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2008-03-15
Last registration	2024-04-22
Complete history	See info



Registration #1	2008-03-15	17 mi
Registration #2	2011-03-11	43.045 mi
Registration #3	2012-01-04	52.506 mi
Registration #4	2013-01-10	55.195 mi
Registration #5	2014-01-07	58.020 mi
Registration #6	2015-02-13	60.843 mi
Registration #7	2016-02-09	64.385 mi
Registration #8	2017-02-01	68.391 mi
Registration #9	2018-01-10	72.005 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es

More info >

CarCheck.co.uk page 11/12



DY08FGZ report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1770 mm
Height	1620 mm
Length	4360 mm
Wheel base	2750 mm
Kerb weight	1365 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 12/12

Number of axles 2

Engine number 1ZZV035065