



report date: 2024-03-28

General information

Make	VOLVO
Model	V90 D4 INSCRIPTION
Colour	Grey
Year of manufacture	2018
Top speed	140 mph
0 - 60 mph	8.2 seconds
Gearbox	8 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	400 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C






Internet history

Entry 2

Date	2021-06-25
Pictures	2
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-06-23
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2024-05-30
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #5 2023-05-19 12:34

MOT test number 914249712870

Result ✓ Passed

Next expiry date 2024-05-30

Minor Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))

Advice Nearside Rear Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))

Advice Front Brake pad(s) wearing thin getting low (1.1.13 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge- outer side wall perished and cracking (5.2.3 (e))

MOT #4 2023-05-19 08:24

MOT test number 173840403444

Result ✗ Failed

Advice Nearside Front Outer Tyre slightly damaged/cracking or perishing side wall (5.2.3 (d) (ii))

Fail Nearside Front Outer Tyre has a bulge, caused by separation or partial failure of its structure side wall (5.2.3 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view chip (3.2 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge wearing inner edge- outer side wall perished and cracking (5.2.3 (e))

Advice Front Brake pad(s) wearing thin getting low (1.1.13 (a) (ii))

Advice Nearside Rear Outer Tyre slightly damaged side wall (5.2.3 (d) (ii))



MOT #3	2022-05-23 11:57
MOT test number	140235577541
Result	✓ Passed
MOT #2	2021-05-19 09:41
MOT test number	889046040896
Result	✓ Passed
MOT #1	2021-05-19 08:23
MOT test number	974747339944
Result	✗ Failed
Fail	Nearside Rear Tyre tread depth below requirements of 1.6mm Flat Spot on tyre (5.2.3 (e))
Fail	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))



Tax & MOT check

✓
Taxed

Tax due:
1 July 2024

✓
MOT

Expires:
30 May 2024

Tax status	Valid until 1 July
Days left	63
MOT expiry date	30 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	NA18BYN
Plate since	2019-03-28
Current registration	NA18BYN
Plate since	2019-03-28

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-05-31
Last registration	2023-05-19
Complete history	See info



Registration #1	2018-05-31	28 mi
Registration #2	2021-05-19	56.357 mi
Registration #3	2021-05-19	56.357 mi
Registration #4	2023-05-19	56.357 mi
Registration #5	2023-05-19	56.357 mi
Registration #6	2023-05-19	56.357 mi
Registration #7	2023-05-19	56.357 mi
Registration #8	2023-05-19	56.357 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight

Width	1895 mm
Height	1475 mm
Length	4936 mm
Wheel base	2941 mm
Kerb weight	1696 kg
Max. allowed weight	2310 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	2363154