



report date: 2024-03-29

General information

Make	VOLVO
Model	C30 R-DESIGN
Colour	White
Year of manufacture	2012
Top speed	130 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	185 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.2 mpg
Consumption extra urban	48.7 mpg
Consumption combined	37.2 mpg
CO2 emission	177 g/km
CO2 label	I





Internet history

Entry 1

Date	2021-10-09
Pictures	20
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-12-09
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	20
Total items failed	6

MOT #15	2023-11-23 15:07
MOT test number	932777866319
Result	✓ Passed
Next expiry date	2024-12-09
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Oil leak, but not excessive Gearbox oil seal leaking (8.4.1 (a) (i))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #14	2023-11-14 10:48
MOT test number	885222522554
Result	✗ Failed
Fail	Front Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Front Oil leak, but not excessive Gearbox oil seal leaking (8.4.1 (a) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #13** 2022-12-02 14:55**MOT test number** 179675452240**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing outer wall (5.2.3 (d) (ii))**MOT #12** 2021-12-10 09:40**MOT test number** 311399903028**Result** ✓ Passed**MOT #11** 2021-12-08 13:08**MOT test number** 343460734396**Result** ✗ Failed**Fail** Brake lever pivot has excessive wear or free play brake pedal to much travel before brakes engage (1.1.1 (b))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))**MOT #10** 2021-08-09 15:43**MOT test number** 397834441423**Result** ✓ Passed**MOT #9** 2020-08-26 15:45**MOT test number** 726954252804**Result** ✓ Passed

**MOT #8** 2020-08-25 08:47**MOT test number** 299152104931**Result** ✓ Passed**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #7** 2020-08-25 08:47**MOT test number** 208518143305**Result** ✗ Failed**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Pass with rectification** Nearside Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #6** 2019-08-08 08:15**MOT test number** 486314089139**Result** ✓ Passed**MOT #5** 2018-08-07 12:39**MOT test number** 945984514751**Result** ✓ Passed

**MOT #4** 2017-08-10 09:27**MOT test number** 656059365500**Result** ✓ Passed**MOT #3** 2016-08-16 10:57**MOT test number** 945244072829**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #2** 2015-08-19 15:10**MOT test number** 624936929646**Result** ✓ Passed**MOT #1** 2015-08-19 15:10**MOT test number** 410134822915**Result** ✗ Failed**Pass with rectification** Nearside Front Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 December 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	9 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	YX62OLW
Plate since	2019-03-29
Current registration	YX62OLW
Plate since	2019-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-09-03
Last registration	2023-11-23
Complete history	See info



Registration #1	2012-09-03	13 mi
Registration #2	2015-08-19	34.792 mi
Registration #3	2015-08-19	34.792 mi
Registration #4	2016-08-16	45.491 mi
Registration #5	2017-08-10	57.776 mi
Registration #6	2018-08-07	69.903 mi
Registration #7	2019-08-08	79.678 mi
Registration #8	2020-08-25	90.613 mi
Registration #9	2020-08-25	90.613 mi
Registration #10	2020-08-25	90.613 mi
Registration #11	2020-08-25	90.613 mi
Registration #12	2020-08-25	90.613 mi
Registration #13	2020-08-25	90.613 mi
Registration #14	2020-08-25	90.613 mi
Registration #15	2020-08-25	90.613 mi
Registration #16	2020-08-25	90.613 mi
Registration #17	2020-08-25	90.613 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1329 kg
Max. allowed weight	1750 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1100553