



report date: 2024-03-29

General information

Make	VAUXHALL
Model	ANTARA SE CDTI
Colour	White
Year of manufacture	2012
Top speed	113 mph
0 - 60 mph	12.0 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.4 mpg
Consumption extra urban	44.1 mpg
Consumption combined	36.2 mpg
CO2 emission	205 g/km
CO2 label	K



**Internet history****Entry 2**

Date 2022-02-14

Pictures 3

Listing price [View report](#)source: [autoonline.co.uk](https://www.autoonline.co.uk)**Entry 1**

Date 2021-09-10

Pictures 2

Listing price [View report](#)source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2022-01-04
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	30
Total items failed	10

MOT #11	2021-01-05 15:27
MOT test number	487864305078
Result	✓ Passed
Next expiry date	2022-01-04

MOT #10	2020-04-24 08:56
MOT test number	689313971865
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

MOT #9	2019-04-29 13:56
MOT test number	965133251148
Result	✓ Passed
Advice	Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Front brake discs lipped
Advice	Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #8**

2019-04-29 09:56

MOT test number

166754986514

Result**✗ Failed****Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**Advice** Front brake discs lipped**MOT #7**

2019-04-25 08:07

MOT test number

742838842149

Result**✗ Failed****Fail** Front Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Fail** Rear Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #6**

2018-04-13 14:16

MOT test number

986850582025

Result**✓ Passed****Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Engine light on**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #5** 2017-04-03 11:15**MOT test number** 855259260356**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit and worn badly on inner edge (4.1.E.1)**Advice** Engine light on**Advice** Nearside Rear Nail in tyre**Advice** Oil leak**MOT #4** 2017-04-03 11:15**MOT test number** 615042347493**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit and worn badly on inner edge (4.1.E.1)**Advice** Engine light on**Pass with rectification** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Nearside Rear Nail in tyre**Advice** Oil leak**Pass with rectification** Central Stop lamp not working (1.2.1b)**MOT #3** 2016-04-26 13:47**MOT test number** 175991063368**Result** ✓ Passed**Advice** Oil leaks**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Engine light on**Advice** Front Brake pad(s) wearing thin (3.5.1g)



MOT #2	2016-04-26 13:47
MOT test number	535438144920
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too high (1.8)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Engine light on
Pass with rectification	Nearside Headlamp aim too high (1.8)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Oil leaks

MOT #1	2015-04-09 13:28
MOT test number	626189895002
Result	✓ Passed
Notice	Nail in nearside rear tyre



Tax & MOT check

✕
Untaxed

Tax expired:
5 September 2021

✕
MOT

Expired:
4 January 2022

Tax status	Expired at 5 September
Days left	968 days too late
MOT expiry date	4 January 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	FG12YXN
Plate since	2019-03-29
Current registration	FG12YXN
Plate since	2019-03-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-04-11
Last registration	2021-01-05
Complete history	See info



Registration #1	2012-04-11	28 mi
Registration #2	2015-04-09	22.581 mi
Registration #3	2016-04-26	30.426 mi
Registration #4	2016-04-26	30.426 mi
Registration #5	2017-04-03	39.385 mi
Registration #6	2017-04-03	39.385 mi
Registration #7	2018-04-13	48.600 mi
Registration #8	2019-04-03	55.277 mi
Registration #9	2019-04-03	55.277 mi
Registration #10	2019-04-03	55.277 mi
Registration #11	2019-04-03	55.277 mi
Registration #12	2019-04-03	55.277 mi
Registration #13	2019-04-03	55.277 mi
Registration #14	2019-04-03	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	2085 mm
Height	1747 mm
Length	4576 mm
Wheel base	2707 mm
Kerb weight	1921 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Engine number	113063K