



EA08JZP

report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI (125PS)
Colour	Silver
Year of manufacture	2008
Top speed	116 mph
0 - 60 mph	11.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	123 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.3 mpg
Consumption extra urban	53.3 mpg
Consumption combined	44.8 mpg
CO2 emission	166 g/km
CO2 label	H







Internet history

Entry 1

Date	2022-01-04
Pictures	15
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT expiry date	2025-02-16
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	51
Total items failed	12

MOT #20 2024-02-17 12:54

MOT test number 630545819063

Result ✓ Passed

Next expiry date 2025-02-16

**Advice** Offside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

**Minor** Nearside Front Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

MOT #19 2023-02-15 16:59

MOT test number 973875500192

Result ✓ Passed

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge both worn on edges (5.2.3 (e))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

**Advice** Oil leak

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**MOT #18**

2023-02-14 13:01

**MOT test number**

973632874005

**Result****✗ Failed**

**Minor** Nearside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))

**Fail** Nearside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))

**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt

**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

**Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**Advice** Front Tyre worn close to legal limit/worn on edge both worn on edges (5.2.3 (e))

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm front bush (5.3.4 (a) (i))

**Advice** Rear Coil spring corroded both (5.3.1 (b) (i))

**Minor** Nearside Rear reflector defective or damaged by up to 50% of the reflecting surface (4.8.1 (a) (i))

**Advice** Oil leak

**MOT #17**

2022-01-19 13:38

**MOT test number**

393757892713

**Result****✓ Passed**

**Advice** Rear Tyre worn close to legal limit/worn on edge Nearside & Offside (5.2.3 (e))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Front Nail in tyre

**MOT #16**

2021-02-10 12:53

**MOT test number**

131742164838

**Result**

✓ Passed

**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))**MOT #15**

2021-02-08 09:36

**MOT test number**

930338077523

**Result**

✗ Failed

**Fail** Exhaust fumes entering cabin (6.1.2 (b) (i))**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Minor** Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))**Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Fail** Exhaust has a major leak of exhaust gases (6.1.2 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))**Advice** Rear Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #14**

2020-02-05 11:44

**MOT test number**

853440256032

**Result**

✓ Passed

**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Sub-frame pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))**MOT #13**

2020-02-05 11:43

**MOT test number**

170562211364

**Result**

✗ Failed

**Fail** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))**Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))**Pass with rectification** Offside Rear Outer Position lamp not working (4.2.1 (a) (ii))**Advice** Sub-frame pin or bush worn but not resulting in excessive movement both rear (5.3.4 (a) (i))**MOT #12**

2019-02-04 12:29

**MOT test number**

116249623954

**Result**

✓ Passed

**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Engine covers and under trays fitted

**MOT #11** 2019-02-04 09:35**MOT test number** 766487243186**Result** ✗ Failed

**Advice** Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Engine covers and under trays fitted

**Fail** Offside Front Position lamp not working (4.2.1 (a))

**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

**MOT #10** 2018-02-16 12:24**MOT test number** 158788185784**Result** ✓ Passed**MOT #9** 2017-04-04 15:25**MOT test number** 491127258832**Result** ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Advice** Front tyres worn on inner/outer edges-not to cords at present

**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)

**Advice** Front tyres on 3mm tread depth

**MOT #8** 2016-02-10 17:00**MOT test number** 919819392777**Result** ✓ Passed

**MOT #7** 2016-02-09 16:34**MOT test number** 462999255704**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**MOT #6** 2015-04-11 07:58**MOT test number** 278401605436**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #5** 2014-05-10 07:46**MOT test number** 348000934188**Result** ✓ Passed**MOT #4** 2013-05-04 07:41**MOT test number** 306004323124**Result** ✓ Passed**MOT #3** 2012-04-23 10:31**MOT test number** 479854812127**Result** ✓ Passed**MOT #2** 2011-05-13 15:28**MOT test number** 908413131183**Result** ✓ Passed**MOT #1** 2011-05-13 10:12**MOT test number** 947443231119**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
16 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	16 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-05-12
Last registration	2024-02-17
Complete history	<a href="#">See info</a>



Registration #1	2008-05-12	27 mi
Registration #2	2011-05-13	29.145 mi
Registration #3	2011-05-13	29.149 mi
Registration #4	2012-04-23	41.700 mi
Registration #5	2013-05-04	53.764 mi
Registration #6	2014-05-10	65.901 mi
Registration #7	2015-04-11	76.120 mi
Registration #8	2016-02-09	81.396 mi
Registration #9	2016-02-10	81.396 mi
Registration #10	2017-04-04	97.340 mi
Registration #11	2018-02-16	106.520 mi
Registration #12	2019-05-20	115.557 mi
Registration #13	2020-05-20	125.557 mi
Registration #14	2021-05-20	135.557 mi
Registration #15	2022-05-20	145.557 mi
Registration #16	2023-05-20	155.557 mi
Registration #17	2024-05-20	165.557 mi
Registration #18	2025-05-20	175.557 mi
Registration #19	2026-05-20	185.557 mi
Registration #20	2027-05-20	195.557 mi
Registration #21	2028-05-20	205.557 mi
Registration #22	2029-05-20	215.557 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1807 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

Engine number	8K54165
---------------	---------