





### General information

| Make                | ΤΟΥΟΤΑ           |
|---------------------|------------------|
| Model               | VERSO D-4D TREND |
| Colour              | Black            |
| Year of manufacture | 2014             |
| Top speed           | 112 mph          |
| 0 - 60 mph          | 12.7 seconds     |
| Gearbox             | 6 speed Manual   |

## Engine & fuel consumption

| Power                   | 110 BHP             |
|-------------------------|---------------------|
| Max. torque             | 270 Nm at 1.750 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 51.4 mpg            |
| Consumption extra urban | 72.4 mpg            |
| Consumption combined    | 62.8 mpg            |
| CO2 emission            | 119 g/km            |
| CO2 label               | С                   |







| 2021-10-13  |
|-------------|
| 1           |
| View report |
|             |



source: autotrader.co.uk



### MOT history

| MOT expiry date    | 2024-10-17 |
|--------------------|------------|
| MOT pass rate      | 80 %       |
| MOT passed         | 8          |
| Failed MOT tests   | 2          |
| Total advice items | 20         |
| Total items failed | 3          |

| MOT #10                |   | 2023-10-17 19:43        |
|------------------------|---|-------------------------|
| MOT test               | number  | 264681317875            |
| Result                 |   | 🗸 Passed                |
| Next expi              | ry date   | 2024-10-17              |
| Advice                 | Nearside Rear Nail in tyre  |                         |
| Advice<br>(i))         | Offside Front Suspension arm pin or bush worn but not resulting in excess | ive movement (5.3.4 (a) |
| <b>Advice</b> (a) (i)) | Nearside Front Suspension arm pin or bush worn but not resulting in exces | ssive movement (5.3.4   |

| MOT #9   |  | 2022-10-04 09:33 |
|----------|--|------------------|
| MOT test | number   | 504213363982     |
| Result   |  | ✓ Passed         |
| Advice   | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Advice   | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |



| <b>WU64YOO</b>          |
|-------------------------|
| report date: 2024-03-29 |

| MOT #8  | 2022-10-03 15:09 |
|---|------------------|
| MOT test number   | 342905733613     |
| Result  | 🗙 Failed         |
| Fail Nearside Rear Brake pipe excessively damaged (1.1.11 (c))                |                  |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))  |                  |
| Fail Nearside Front Brake pipe excessively corroded (1.1.11 (c))              |                  |
| Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |                  |

| MOT #7                            | 2021-10-18 08:08  |
|-----------------------------------|---|
| <b>MOT test number</b> 8811190727 |   |
| Result                            | ✓ Passed  |
| Advice                            | Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))  |
| Advice                            | Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |

| МОТ #6  | 2020-08-25 09:50          |
|---|---------------------------|
| MOT test number   | 706055426203              |
| Result  | Passed                    |
| <b>Advice</b> Offside Rear Tyre slightly damaged/cracking or perishing should be k replaced. Also TPM sensor may be insecure inside tyre . (5.2.3 (d) (ii)) | ept under observation or  |
| <b>Advice</b> Nearside Rear Tyre slightly damaged/cracking or perishing should be replaced. (5.2.3 (d) (ii))  | kept under observation or |

| MOT #5          | 20  | )19-08-15 15:57 |
|-----------------|---|-----------------|
| MOT test number | r   | 528930025475    |
| Result          |   | ✓ Passed        |
|                 | e Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d)<br>rake disc worn, pitted or scored, but not seriously weakened both o/s and n/s |                 |





| MOT #4          | 2019-08-15 10:39  |
|-----------------|---|
| MOT test        | <b>number</b> 653592723226  |
| Result          | × Failed  |
| <b>Fail</b> C   | offside Rear Passenger's seat backrest cannot be secured in the upright position. (6.2.6 (a) (i)) |
| Advice          | Nearside Front Tyre worn close to legal limit/worn on edge Slight cuts on sidewall (5.2.3 (e))    |
| Advice<br>(ii)) | Rear Brake disc worn, pitted or scored, but not seriously weakened both o/s and n/s (1.1.14 (a)   |
| Advice          | Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))         |
| Advice          | Offside Front Tyre worn close to legal limit/worn on edge slight cuts on sidewall (5.2.3 (e))     |

| MOT #3          |   | 2018-08-24 12:16      |
|-----------------|---|-----------------------|
| MOT test        | number  | 505239162485          |
| Result          |   | ✓ Passed              |
| Advice          | Nearside Rear Nail in tyre  |                       |
| Advice<br>(ii)) | Front Brake disc worn, pitted or scored, but not seriously weakened both o/ | s and n/s (1.1.14 (a) |

| MOT #2          | 2018-04-03 15:28 |
|-----------------|------------------|
| MOT test number | 259197548215     |
| Result          | ✓ Passed         |

| MOT #1   | 2017-08-29 08:36 |
|--|------------------|
| MOT test number                                    | 639196208763     |
| Result   | ✓ Passed         |
| Advice There is quite a lot of travel in handbrake |                  |



WU64YO0 report date: 2024-03-29

## Tax & MOT check

| √<br>Taxed                        | ✓<br>MOT                           |  |
|-----------------------------------|------------------------------------|--|
| <b>Tax due:</b><br>1 October 2024 | <b>Expires:</b><br>17 October 2024 |  |
| Tax status                        | Valid until 1 October              |  |
| Days left                         | 154                                |  |
| MOT expiry date                   | 17 October 2024                    |  |
| Full MOT history                  | See MOT history                    |  |

### Tax calculation

| Vehicle class                           | 49             |
|---|----------------|
| Band                                    | С              |
| Single payment (12 months)              | £ 35,00,-      |
| Single six month payment                | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,-      |





### Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |   |                                       |
|----------|---|---------------------------------------|
| Date     | F | ET                                    |
| Category |   | LAMP                                  |
| Туре     |   |                                       |
| Damage 2 |   | AMPL                                  |
|          | F | A A A A A A A A A A A A A A A A A A A |
| Date     |   | 1º                                    |
| Category |   | SMT.                                  |
| Туре     |   |                                       |

#### Extra TOYOTA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value          | 4 10.700 |
|-----------------------------|----------|
| Auction value               | 4 10.000 |
| Average private trade value | 4 10.200 |





## Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| ******  |             |
|---|-------------|
| ***********   |             |
| *******   |             |
| *******   |             |
| ***********   |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this TOYOTA had different number plates. |             |
| Number of plates  | ,           |
| Current registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   | More info > |





#### Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |





## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 12         |
| First mileage registration | 2014-09-01 |
| Last registration          | 2023-10-17 |
| Complete history           | See info   |



| Registration #1                    | 2014-09-01 | 8 mi  |
|------------------------------------|------------|---|
| Registration #2                    | 2017-08-29 | 21.290 mi   |
| Registration #3                    | 2018-04-03 | 23.447 mi   |
| Registration #4                    | 2018-08-24 | 24.986 mi   |
| Registration #5                    | 2019-08-15 | 28.545 mi   |
| Registration #6                    | 2019-08-15 | 28.548 mi   |
|                                    |            |   |
| Registration #7                    |            | 10.317 est  |
| Registration #7<br>Registration #8 |            | 11.777 es   |
|                                    |            | 11,117 es   |
| Registration #8                    |            | 01,000 est<br>01,000 est<br>01,000 est<br>01,000 est          |
| Registration #8<br>Registration #9 |            | 01,000 46<br>01,000 46<br>01,000 46<br>01,000 46<br>01,000 46 |





## Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 89%             |
| Children       | 75%             |
| Pedestrian     | 69%             |
| Safety systems | 86%             |
| Overall rating | 82%             |
| Video          | see crash video |



| Dimensions & weight               |                  |
|-----------------------------------|------------------|
| Width                             | 1790 mm          |
| Height                            | 1630 mm          |
| Length                            | 4460 mm          |
| Wheel base                        | 2780 mm          |
| Kerb weight                       | 1620 kg          |
| Max. allowed weight               | 2260 kg          |
| Additional information            |                  |
| Fuel tank capacity                | 55 I             |
| Fuel delivery                     | Direct Injection |
| Number of doors                   | 5                |
| Number of seats<br>CarCheck.co.uk | 7 page 12/12     |

| Number of axles | 2           |
|-----------------|-------------|
| Engine number   | N4776408778 |