



A064WVE

report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L3H2 ENTERPRISE HDI
Colour	White
Year of manufacture	-
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	44.8 mpg
Consumption combined	38.2 mpg




LABEL UNKNOWN



Internet history

Entry 2


Date	2021-07-20
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-06-18
Pictures	13
Listing price	View report



source: [autotrader.co.uk](#)

**MOT history**

MOT #9	2021-08-12 16:29
MOT test number	941880131450
Result	✓ Passed
Next expiry date	2022-08-11

MOT #8	2020-11-19 14:37
MOT test number	804140484876
Result	✓ Passed
Advice	REAR BUMP STOPS MISSING

MOT #7	2020-10-14 12:17
MOT test number	125691900351
Result	✓ Passed
Advice	Rear Suspension rod pin or bush worn but not resulting in excessive movement BUMP STOPS X2 (5.3.4 (a) (i))
Advice	Exhaust emits black smoke during acceleration BURNING OIL (8.2.1.2 (g))

MOT #6	2020-02-01 10:07
MOT test number	512616996483
Result	✓ Passed

**MOT #5** 2020-01-21 16:55**MOT test number** 221190362136**Result** ✗ Failed

- Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Parking brake efficiency below requirements (1.4.2 (a) (i))
- Fail** Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
- Fail** Horn not working (7.7 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Parking brake efficiency below requirements (1.4.2 (a) (i))
- Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))

MOT #4 2018-10-29 17:18**MOT test number** 404050697052**Result** ✓ Passed

- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

**MOT #3**

2018-10-24 11:30

MOT test number

662554151278

Result**✗ Failed**

- Minor** Nearside Rear Direction indicator lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Nearside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
- Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Nail in tyre x5
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Minor** Offside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Fail** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear tyre very close to limit
- Advice** Nearside Play in steering rack inner joint(s)
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))

MOT #2

2017-10-26 08:18

MOT test number

688822996079

Result**✓ Passed**

- Advice** Nearside Rear Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #1

2017-10-19 15:38

MOT test number

590683192577

Result

✗ Failed

- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Nearside Rear Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Fail

Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail

Nearside Front wheel bearing rough when rotated (2.5.A.2)
- Fail

Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)
- Advice

Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)
- Fail

Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail

Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)
- Fail

Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2014-11-26
Last registration	2021-08-12
Complete history	See info



Registration #1	2014-11-26	8 mi
Registration #2	2017-10-19	81.774 mi
Registration #3	2017-10-26	82.079 mi
Registration #4	2018-10-24	106.955 mi
Registration #5	2018-10-29	106.955 mi
Registration #6	2020-01-21	125.609 mi
Registration #7	2020-05-20	151.277 mi
Registration #8	2020-05-20	151.277 mi
Registration #9	2020-05-20	151.277 mi
Registration #10	2020-05-20	151.277 mi
Registration #11	2020-05-20	151.277 mi
Registration #12	2020-05-20	151.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	TRJA0777566