





### General information

Make	CITROEN
Model	C3 BLUEHDI SELECTION PICASSO
Colour	Black
Year of manufacture	2015
Top speed	111 mph
0 - 60 mph	13.3 seconds
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	98 BHP
Max. torque	254 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	80.7 mpg
Consumption combined	72.4 mpg
CO2 emission	101 g/km
CO2 label	В





## MOT history

MOT expiry date	2024-10-26
MOT pass rate	86 %
MOT passed	6
Failed MOT tests	1
Total advice items	17
Total items failed	5

MOT #7		2023-10-26 14:05
MOT test	number	265734981755
Result		Passed
Next exp	iry date	2024-10-26
Minor	Nearside Front Outer Drive shaft joint constant velocity boot severely deteriora	ated (6.1.7 (g) (i))
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	



<b>NA65</b>	EFU
report date:	2024-03-28

МОТ #6	2023-10-17 14:15
MOT test number	526576635559
Result	🗙 Failed
<b>Fail</b> Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Front Exhaust has a major leak of exhaust gases flexy (6.1.2 (a))	
Advice Central Exhaust mounting defective (6.1.2 (a))	
Fail         Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Offside Front Wheel bearing has slight play (5.1.3 (a) (i))	
Advice Rear Exhaust mounting defective (6.1.2 (a))	
Minor Nearside Front Outer Drive shaft joint constant velocity boot severely deterio	orated (6.1.7 (g) (i))
<b>Fail</b> Emissions unable to be completed due to exhaust leak (8.2.2.2 (e))	
Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Fail         Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))	

MOT #5		2022-10-26 16:19
MOT test i	number	267660560734
Result		✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Rear Exhaust mounting defective (6.1.2 (a))	
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)	)





MOT #4		2021-10-14 09:45
MOT test	number	115687190077
Result		✓ Passed
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Emissions too low to obtain reading	
Advice	Central Front Registration plate deteriorated but not likely to be misread cracke	ed (0.1 (b))
Advice	Under trays and engine covers fitted obscuring view of certain testable compor	nents

MOT #3	2020-10-23 10:02	
MOT test number	830855024144	
Result	✓ Passed	
Minor       Windscreen wiper blade defective both (3.4 (b) (i))         Advice       Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		

MOT #2	2019-10-25 08:56
MOT test number	480299819266
Result	✓ Passed

MOT #1	2018-10-17 16:33
MOT test number	702636239936
Result	✓ Passed



Tax & MOT check

✓ Taxed Tax due: 1 November 2024	✓ MOT Expires: 26 October 2024
Tax status	Valid until 1 November
Days left	185
MOT expiry date	26 October 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	В
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-





### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	 Law P
Туре	
Damage 2	AMPLE
Damage 2	E CAT D
Date	 ₩.
Category	 AMPT
Туре	

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





## Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this CITROEN had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2015-10-27
Last registration	2023-10-26
Complete history	<u>See info</u>



Registration #1	2015-10-27	8 mi
Registration #2	2018-10-17	69.975 mi
Registration #3	2019-10-25	91.209 mi
Registration #4	2020-10-23	111.926 mi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.117 esi





# Safety ratings

NCAP rating	****
Adult	83%
Children	74%
Pedestrian	33%
Safety systems	40%
Overall rating	67%
Video	see crash video



Dimensions & weight	
Width	1766 mm
Height	1631 mm
Length	4078 mm
Wheel base	2540 mm
Kerb weight	1240 kg
Max. allowed weight	1800 kg
Additional information	
Additional information Fuel tank capacity	50 I
	50 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5