



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI GO
Colour	Black
Year of manufacture	2014
Top speed	108 mph
0 - 60 mph	12.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 1.250 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.8 mpg
Consumption extra urban	56.5 mpg
Consumption combined	50.4 mpg
CO2 emission	147 g/km
CO2 label	F





Internet history

Entry 1

Date	2021-07-19
Pictures	29
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-08-03
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	23
Total items failed	2

MOT #11 2023-07-12 13:16

MOT test number 615571466210

Result ✓ Passed

Next expiry date 2024-08-03

- Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10 2022-07-18 15:22

MOT test number 141799258857

Result ✓ Passed

MOT #9 2022-07-18 14:32

MOT test number 336599863794

Result ✗ Failed

- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**MOT #8**

2021-08-04 16:25

MOT test number

336784504048

Result

✓ Passed

Advice Rear Tyre slightly damaged/cracking or perishing Both side rear (NSR&OSR)cracking (5.2.3 (d) (ii))**Advice** Tyre worn close to legal limit/worn on edge All four (NSF&OSF&NSR&OSR)worn close to legal limit (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively Both side front (NSF&OSF) (1.1.14 (a) (i))**MOT #7**

2021-08-04 14:11

MOT test number

172715678170

Result

✗ Failed

Advice Rear Tyre slightly damaged/cracking or perishing Both side rear (NSR&OSR)cracking (5.2.3 (d) (ii))**MAJOR** Offside Front Outer Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Tyre worn close to legal limit/worn on edge All four (NSF&OSF&NSR&OSR)worn close to legal limit (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively Both side front (NSF&OSF) (1.1.14 (a) (i))**MOT #6**

2020-10-15 13:05

MOT test number

309023825806

Result

✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Front Nail in tyre**Advice** Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #5** 2019-10-14 15:45**MOT test number** 100163879704**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #4** 2019-10-14 10:25**MOT test number** 859519622166**Result** ✗ Failed**MAJOR** Rear Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #3** 2018-09-06 11:46**MOT test number** 743127111287**Result** ✓ Passed**MOT #2** 2018-09-06 11:46**MOT test number** 668524544545**Result** ✗ Failed**Pass with rectification** Windscreen washer not working (3.5 (a))**Pass with rectification** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MOT #1** 2017-06-02 09:12**MOT test number** 172513519332**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
3 August 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	3 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	KW14LJX
Plate since	2019-09-29
Current registration	KW14LJX
Plate since	2019-09-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2014-06-30
Last registration	2023-07-12
Complete history	See info



Registration #1	2014-06-30	9 mi
Registration #2	2017-06-02	47.034 mi
Registration #3	2018-09-06	60.790 mi
Registration #4	2018-09-06	60.790 mi
Registration #5	2019-10-14	73.672 mi
Registration #6	2019-10-14	73.672 mi
Registration #7	2020-10-15	81.584 mi
Registration #8	2020-10-15	81.584 mi
Registration #9	2020-10-15	81.584 mi
Registration #10	2020-10-15	81.584 mi
Registration #11	2020-10-15	81.584 mi
Registration #12	2020-10-15	81.584 mi
Registration #13	2020-10-15	81.584 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1820 mm
Height	1665 mm
Length	4410 mm
Wheel base	2640 mm
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D4FDEZ280515