



report date: 2024-03-28

General information

Make	FORD
Model	TRANSIT CONNECT TDCI T230 LX LWB P/V 110
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	109 BHP
Max. torque	250 Nm at 3.200 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-04-09
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	31
Total items failed	6

MOT #18	2024-03-18 17:12
MOT test number	933963210945
Result	✓ Passed
Next expiry date	2025-04-09
Minor	Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both slightly faded (4.1.4 (b))

MOT #17	2024-03-18 17:12
MOT test number	439264599340
Result	✗ Failed
Advice	Front Headlamp has a product on the lens but not seriously reducing light output both slightly faded (4.1.4 (b))
Minor	Nearside Front Lower Suspension component ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Pass with rectification	Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #16**

2023-03-17 15:12

MOT test number

838078017297

Result

✓ Passed

- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Central Front Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Lower Brake pipe corroded, covered in grease or other material advise replacement (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Lower Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Nearside Rear Upper Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Rear Lower suspension has surface rust

MOT #15

2023-03-06 17:08

MOT test number

678933560702

Result

✗ Failed

- Advice** Rear Lower suspension has surface rust
- Advice** Central Front Brake pedal wearing smooth (1.1.2 (c))
- Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Rear Lower Subframe mounting prescribed area excessively corroded significantly reducing structural strength outer sill marked (5.3.6 (a) (i))
- Advice** Nearside Rear Upper Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Lower Subframe mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))
- Advice** Offside Rear Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Lower Brake pipe corroded, covered in grease or other material advise replacement (1.1.11 (c))

**MOT #14** 2022-03-28 14:59**MOT test number** 436326839033**Result** ✓ Passed**Advice** Front Brake pipe corroded, covered in grease or other material To rear (1.1.11 (c))**Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #13** 2021-04-10 11:57**MOT test number** 339466222489**Result** ✓ Passed**MOT #12** 2021-03-30 13:38**MOT test number** 379544463380**Result** ✗ Failed**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Fail** Stop lamp(s) all not working (4.3.1 (a) (iii))**MOT #11** 2020-02-27 10:58**MOT test number** 222798165071**Result** ✓ Passed**MOT #10** 2019-02-15 10:38**MOT test number** 158506983102**Result** ✓ Passed**MOT #9** 2018-03-08 11:26**MOT test number** 676218622257**Result** ✓ Passed

**MOT #8** 2017-03-06 12:08**MOT test number** 189682477325**Result** ✓ Passed**MOT #7** 2016-03-08 09:07**MOT test number** 940306701103**Result** ✓ Passed**MOT #6** 2016-03-08 09:07**MOT test number** 239283061158**Result** ✗ Failed**Pass with rectification** Centre Stop lamp not working (1.2.1b)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #5** 2015-02-26 12:01**MOT test number** 495527555090**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2014-02-26 11:22**MOT test number** 688817954060**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Emissions too clean for tester.**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #3	2013-03-08 16:09
MOT test number	787717963045
Result	✓ Passed

MOT #2	2013-03-08 12:46
MOT test number	186227663078
Result	✗ Failed
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #1	2012-03-06 11:44
MOT test number	549496362008
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 April 2025

Tax status		Valid until 1 April
Days left		337
MOT expiry date		9 April 2025
Full MOT history		See MOT history



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-03-10
Last registration	2024-03-18
Complete history	See info



Registration #1	2009-03-10	20 mi
Registration #2	2012-03-06	15.705 mi
Registration #3	2013-03-08	19.672 mi
Registration #4	2013-03-08	19.672 mi
Registration #5	2014-02-26	24.877 mi
Registration #6	2015-02-26	30.096 mi
Registration #7	2016-03-08	35.525 mi
Registration #8	2016-03-08	35.525 mi
Registration #9	2017-03-06	36.210 mi
Registration #10	2018-03-08	39.001 mi
Registration #11	2019-03-08	39.001 mi
Registration #12	2019-03-08	39.001 mi
Registration #13	2019-03-08	39.001 mi
Registration #14	2019-03-08	39.001 mi
Registration #15	2019-03-08	39.001 mi
Registration #16	2019-03-08	39.001 mi
Registration #17	2019-03-08	39.001 mi
Registration #18	2019-03-08	39.001 mi
Registration #19	2019-03-08	39.001 mi
Registration #20	2019-03-08	39.001 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2044 mm
Height	601 mm
Length	4525 mm
Max. allowed weight	2340 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	2
Engine number	9J61491