






report date: 2024-03-29

### General information

| Make                | FIAT           |
|---------------------|----------------|
| Model               | PUNTO EASY     |
| Colour              | White          |
| Year of manufacture | 2012           |
| Top speed           | 97 mph         |
| 0 - 60 mph          | 14.4 seconds   |
| Gearbox             | 5 speed Manual |

## Engine & fuel consumption

| Power                   | 69 BHP   |
|-------------------------|----------|
| Engine capacity         | 1.242 cc |
| Cylinders               | 4        |
| Fuel type               | Petrol   |
| Consumption city        | 39.2 mpg |
| Consumption extra urban | 64.2 mpg |
| Consumption combined    | 52.3 mpg |
| CO2 emission            | 126 g/km |
| CO2 label               | D        |



CarCheck.co.uk page 1/13



report date: 2024-03-29

### Internet history

#### Entry 2

Date 2024-04-27

Pictures 4

Listing price <u>View report</u>










source: cargurus.co.uk


#### Entry 1

| Date     | 2021-07-31 |
|----------|------------|
| Pictures | 19         |

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

| MOT history | М | OT | h | is | to | rv |
|-------------|---|----|---|----|----|----|
|-------------|---|----|---|----|----|----|

| MOT expiry date    | 2024-06-16 |
|--------------------|------------|
| MOT pass rate      | 69 %       |
| MOT passed         | 9          |
| Failed MOT tests   | 4          |
| Total advice items | 16         |
| Total items failed | 8          |

| MOT #13          | 2023-06-16 12:01 |
|------------------|------------------|
| MOT test number  | 920625981127     |
| Result           | ✓ Passed         |
| Next expiry date | 2024-06-16       |

| MOT #12                 |  | 2023-06-14 12:43 |
|-------------------------|--|------------------|
| MOT test number         |  | 586865379779     |
| Result                  |  | <b>X</b> Failed  |
| Pass with rectification | Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) |                  |
| Fail Nearside Rear Posi | tion lamp not working (4.2.1 (a) (ii))             |                  |

| MOT #11                                   | 2022-06-17 08:17 |
|---|------------------|
| MOT test number                           | 887926042301     |
| Result                                    | <b>✓</b> Passed  |
| Advice Front tyres in very poor condition |                  |

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT test number
726978435339

Result

Pass with rectification
Offside Headlamp aim too high (4.1.2 (a))

Advice Front tyres in very poor condition

Pass with rectification
Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MOT #9

MOT test number

Result

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

| MOT #8   | 2020-06-17 11:00   | 0 |
|----------|--|---|
| MOT test | number 302118990238  | 3 |
| Result   | ✓ Passed   | b |
| Advice   | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                                      |   |
| Advice   | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |   |
| Advice   | Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                                     |   |
| Advice   | Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))                     |   |
| Advice   | Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))  |   |

CarCheck.co.uk page 4/13



**Pass with rectification** 

FG62GKC

report date: 2024-03-29

**MOT #7** 2020-06-17 11:00 **MOT** test number 482004783435 Result × Failed Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) **Advice** Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii)) **Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Advice **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

 MOT #6
 2019-06-12 10:51

 MOT test number
 916663485093

 Result
 ✓ Passed

 MOT #5
 2019-06-12 10:51

 MOT test number
 379885321639

 Result
 X Failed

Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #4

MOT test number

Result

Advice Nearside Rear tyre cracking

Advice Front both tyres cracking

CarCheck.co.uk page 5/13



report date: 2024-03-29

| MOT #3          | 2017-06-17 12:11 |
|-----------------|------------------|
| MOT test number | 441286226924     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #2          | 2016-10-07 12:26 |
| MOT test number | 987724094451     |
| Result          | ✓ Passed         |
|                 |                  |
| MOT #1          | 2015-10-09 15:44 |
| MOT test number | 872519752268     |
| Result          | ✓ Passed         |

CarCheck.co.uk page 6/13



report date: 2024-03-29

### Tax & MOT check





| Tax status       | Expired at 19 March 2024 |
|------------------|--------------------------|
| Days left        | 42 days too late         |
| MOT expiry date  | 16 June 2024             |
| Full MOT history | See MOT history          |

### Tax calculation

| Vehicle class                           | 48         |
|---|------------|
| Band                                    | D          |
| Single payment (12 months)              | £ 150,00,- |
| Single six month payment                | £ 82,50,-  |
| Total payable by 12 monthly instalments | £ 157,50,- |

CarCheck.co.uk page 7/13



report date: 2024-03-29

### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

### Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

# Owner history

| o mile mesery  |             |
|--|-------------|
| For how long did the current and previous owner(s) have this FIAT? How many owners di<br>Check it in the premium report and see all owner registrations. Download the full report  |             |
|  |             |
|  |             |
| ***************************************  |             |
| THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDR |             |
|  |             |
| ***************************************  |             |
|  | More info > |
| Plate changes  |             |
| See in this check if this FIAT had different number plates.  |             |
| Number of plates   |             |
| Current registration   | OK SIN      |
| Plate since  |             |
| Current registration   | OK SING     |
| Plate since  |             |
|  | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-29

### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

# Mileage check

Registration #16

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 16         |
| First mileage registration | 2012-10-10 |
| Last registration          | 2023-06-16 |
| Complete history           | See info   |



| Registration #1  | 2012-10-10 | 25 mi     |
|------------------|------------|-----------|
| Registration #2  | 2015-10-09 | 32.924 mi |
| Registration #3  | 2016-10-07 | 39.176 mi |
| Registration #4  | 2017-06-17 | 40.389 mi |
| Registration #5  | 2018-06-06 | 47.412 mi |
| Registration #6  | 2019-06-12 | 53.608 mi |
| Registration #7  | 2019-06-12 | 53.608 mi |
| Registration #8  | 2020-06-17 | 59.401 mi |
| Registration #9  |            | 11.777 es |
| Registration #10 |            | 11.777 es |
| Registration #11 |            | 11.777 es |
| Registration #12 |            | 11.777 es |
| Registration #13 |            | 11.777 es |
| Registration #14 |            | 11.177 es |
| Registration #15 |            | 11.777 es |
|                  |            |           |

7070.70.70

More info >

77. 777 mg

CarCheck.co.uk page 12/13



report date: 2024-03-29

### Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 |                  |
| 50482 |                  |
| 50501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

# Safety ratings

| NCAP rating | ****            |
|-------------|-----------------|
| Video       | see crash video |



# Dimensions & weight

| Width               | 1687 mm |
|---------------------|---------|
| Height              | 1490 mm |
| Length              | 4065 mm |
| Wheel base          | 2510 mm |
| Kerb weight         | 1030 kg |
| Max. allowed weight | 1590 kg |

# Additional information

| Fuel delivery                   | Multi-Point Injection |            |
|---------------------------------|-----------------------|------------|
| Number of doors                 | 5                     |            |
| Number of seats                 | 5                     |            |
| Engine number<br>Carcheck.co.uk | 0207966               | page 13/13 |