



report date: 2024-03-29

General information

Make	MAZDA
Model	5 TS2
Colour	Black
Year of manufacture	2011
Top speed	134 mph
0 - 60 mph	10.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	155 BHP
Max. torque	193 Nm at 4.500 rpm
Engine capacity	1.999 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.4 mpg
Consumption extra urban	53.3 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G





Internet history

Entry 1

Date	2022-06-07
Pictures	14
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-12
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	58
Total items failed	6

MOT #13	2023-06-09 15:03
MOT test number	123499932422
Result	✓ Passed
Next expiry date	2024-06-12
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Minor	Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
Advice	Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
Advice	Offside Front Shock absorbers has a reduced damping effect (5.3.2 (d))

MOT #12	2022-06-13 10:35
MOT test number	667906268042
Result	✓ Passed

**MOT #11**

2021-12-06 13:48

MOT test number

421708051099

Result

✓ Passed

- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #10

2021-12-01 09:51

MOT test number

882186160859

Result

✗ Failed

- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge out of round (5.2.3 (e))
- Advice** Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))
- MAJOR** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))
- Advice** Nearside Rear Nail in tyre
- MAJOR** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))
- Advice** Offside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))

**MOT #9** 2020-11-30 10:07**MOT test number** 861636929745**Result** ✓ Passed

- Advice** Central Rear Passenger seat(s) missing at time of test
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))
- Advice** Rear Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))

MOT #8 2020-11-30 08:56**MOT test number** 860665985995**Result** ✗ Failed

- Advice** Brake disc worn, pitted or scored, but not seriously weakened front and rear (1.1.14 (a) (ii))
- Advice** Central Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Central Rear Passenger seat(s) missing at time of test
- DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Rear Anti-roll bar linkage ball joint has slight play both (5.3.4 (a) (i))

MOT #7 2019-05-20 10:48**MOT test number** 339688798179**Result** ✓ Passed

- Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))



MOT #6

2018-06-19 14:38

MOT test number

490389880692

Result		✓ Passed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Engine cover fitted can not check for leaks	
Advice	Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner bush deteriorated (5.3.4 (a) (i))	
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice	Under body trims fitted can not check for corrosion	
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement inner bush deteriorated (5.3.4 (a) (i))	

**MOT #5** 2018-06-19 10:18**MOT test number** 552196783727**Result** ✗ Failed

- Advice** Engine cover fitted can not check for leaks
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
inner bush deteriorated (5.3.4 (a) (i))
- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement
inner bush deteriorated (5.3.4 (a) (i))
- Advice** Under body trims fitted can not check for corrosion
- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- MAJOR** Nearside Front Outer Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))

MOT #4 2017-06-16 08:27**MOT test number** 622166503090**Result** ✓ Passed**MOT #3** 2016-06-15 08:08**MOT test number** 915465266279**Result** ✓ Passed



MOT #2	2015-06-18 16:48
MOT test number	156349965190
Result	✓ Passed
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2015-06-18 15:20
MOT test number	416419765148
Result	✗ Failed
Fail	Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Nail in offside rear tyre
Fail	Nearside Front Tyre has ply or cords exposed (4.1.D.1b)
Notice	Engine covers fitted obscuring some components in the engine bay
Fail	Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
Notice	Under-trays fitted obscuring some underside components
Fail	Offside Front Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)
Fail	Offside Rear Tyre has a tear, caused by separation or partial failure of its structure (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
12 June 2024

Tax status	Valid until 1 June
Days left	32
MOT expiry date	12 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-06-29
Current registration	*****
Plate since	2019-06-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2011-06-17
Last registration	2023-06-09
Complete history	See info



Registration #1	2011-06-17	10 mi
Registration #2	2015-06-18	59.213 mi
Registration #3	2015-06-18	59.213 mi
Registration #4	2016-06-15	67.146 mi
Registration #5	2017-06-16	76.734 mi
Registration #6	2018-06-19	82.473 mi
Registration #7	2018-06-19	82.473 mi
Registration #8	2019-05-20	88.190 mi
Registration #9	2019-05-20	88.190 mi
Registration #10	2019-05-20	88.190 mi
Registration #11	2019-05-20	88.190 mi
Registration #12	2019-05-20	88.190 mi
Registration #13	2019-05-20	88.190 mi
Registration #14	2019-05-20	88.190 mi
Registration #15	2019-05-20	88.190 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	77%
Children	81%
Pedestrian	49%
Safety systems	71%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1795 mm
Height	1440 mm
Length	4755 mm
Wheel base	2725 mm
Kerb weight	1435 kg
Max. allowed weight	1955 kg

Additional information

Fuel tank capacity	64 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	LF 20408957