



HYUNDAI

ROIOSSZ

report date: 2024-03-29

General information

Make	HYUNDAI
Model	I30 COMFORT ISG
Colour	Black
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	11.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	108 BHP
Max. torque	137 Nm at 5.000 rpm
Engine capacity	1.396 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	46.3 mpg
CO2 emission	142 g/km
CO2 label	F





MOT history

MOT expiry date	2025-03-20
MOT pass rate	57 %
MOT passed	12
Failed MOT tests	9
Total advice items	27
Total items failed	25

MOT #21	2024-03-21 16:06
MOT test number	769615863913
Result	✓ Passed
Next expiry date	2025-03-20
Advice	Rear coil springs corroded
Advice	Front and rear brake discs slightly corroded
Advice	Both front tyres edges worn, offside front tyre inner edge worn low on legal limit
Advice	Rear suspension arms corroded
Advice	Nearside rear tyre perished
Advice	Engine and gearbox damp with oil
Advice	Nearside front shock damp

**MOT #20**

2023-03-03 09:33

**MOT test number**

813931165258

**Result**

✓ Passed

**Advice**

Offside Rear Tyre worn close to legal limit/worn on edge Bald Inner Edge (5.2.3 (e))

**Advice**

Front Registration plate deteriorated but not likely to be misread Slight / Starting To (0.1 (b))

**Advice**

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice**

Front Brake pad(s) wearing thin Both Nearside &amp; Offside (1.1.13 (a) (ii))

**Advice**

Oil leak, but not excessive Rear Engine (8.4.1 (a) (i))

**MOT #19**

2022-02-18 16:33

**MOT test number**

627171410452

**Result**

✓ Passed

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Minor**

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #18**

2022-02-18 16:33

**MOT test number**

686074409215

**Result**

✗ Failed

**Advice**

Front Registration plate deteriorated but not likely to be misread (0.1 (b))

**Minor**

Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Pass with rectification**

Stop lamp(s) all not working (4.3.1 (a) (iii))

**MOT #17**

2021-02-27 13:14

**MOT test number**

210474428190

**Result**

✓ Passed

**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Minor** Offside Registration plate lamp insecure (4.7.1 (c) (i))

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16**

2021-01-29 10:44

**MOT test number**

591131709921

**Result**

✗ Failed

**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))

**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Offside Front Inner Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Minor** Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))

**MOT #15**

2020-03-10 10:03

**MOT test number**

645963682542

**Result**

✓ Passed

**MOT #14**

2020-03-04 12:45

**MOT test number**

885685908904

**Result**

✗ Failed

- Fail** Offside Registration plate lamp likely to become detached (4.7.1 (c) (ii))
- Fail** Nearside Front Lower Suspension component ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Fail** Nearside Registration plate lamp likely to become detached (4.7.1 (c) (ii))
- Fail** Nearside Rear Other passenger door cannot be opened from outside the vehicle (6.2.3 (a))
- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**MOT #13**

2019-03-02 12:51

**MOT test number**

179330563573

**Result**

✓ Passed

**MOT #12**

2019-03-02 12:51

**MOT test number**

671951904415

**Result**

✗ Failed

- Pass with rectification** Battery insecure and likely to fall from carrier (4.13 (a) (ii))
- Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))

**MOT #11**

2018-03-07 15:17

**MOT test number**

214389934775

**Result**

✓ Passed

**MOT #10** 2018-03-05 08:58**MOT test number** 969706225651**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**MOT #9** 2017-03-04 09:19**MOT test number** 689622578100**Result** ✓ Passed**MOT #8** 2017-03-04 08:58**MOT test number** 358556091138**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**MOT #7** 2016-03-09 10:27**MOT test number** 776248347583**Result** ✓ Passed

**MOT #6** 2016-03-08 14:57**MOT test number** 564067670287**Result** ✗ Failed

- Fail** Nearside Rear Stop lamp not working (1.2.1b)
- Fail** Nearside Front Lower Front suspension ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt Joint (2.4.G.2)
- Fail** Offside Front Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #5** 2015-03-03 14:52**MOT test number** 139992565429**Result** ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #4** 2015-03-03 14:52**MOT test number** 399022365067**Result** ✗ Failed

- Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #3** 2014-07-30 09:16**MOT test number** 946691014244**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #2** 2013-07-17 10:03**MOT test number** 219648093422**Result** ✓ Passed



MOT #1	2013-07-17 10:03
MOT test number	428068493116
Result	✗ Failed
Pass with rectification	Offside Registration plate lamp insecure (1.1.C.1c)
Pass with rectification	Offside Headlamp aim too low (1.8)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
20 March 2025

<b>Tax status</b>	Valid until 1 September
<b>Days left</b>	126
<b>MOT expiry date</b>	20 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>Single payment (12 months)</b>	£ 200,00,-
<b>Single six month payment</b>	£ 110,00,-
<b>Total payable by 12 monthly instalments</b>	£ 210,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	<b>RO10SSZ</b>
Plate since	2024-03-29
Current registration	<b>RO10SSZ</b>
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-07-20
Last registration	2024-03-21
Complete history	<a href="#">See info</a>



Registration #1	2010-07-20	13 mi
Registration #2	2013-07-17	15.730 mi
Registration #3	2014-07-30	22.070 mi
Registration #4	2015-03-03	27.849 mi
Registration #5	2016-03-08	36.583 mi
Registration #6	2016-03-09	36.583 mi
Registration #7	2017-03-04	45.422 mi
Registration #8	2017-03-04	45.422 mi
Registration #9	2018-03-05	52.390 mi
Registration #10	2018-03-07	52.390 mi
Registration #11	2019-03-20	55.357 mi
Registration #12	2019-03-20	55.357 mi
Registration #13	2019-03-20	55.357 mi
Registration #14	2019-03-20	55.357 mi
Registration #15	2019-03-20	55.357 mi
Registration #16	2019-03-20	55.357 mi
Registration #17	2019-03-20	55.357 mi
Registration #18	2019-03-20	55.357 mi
Registration #19	2019-03-20	55.357 mi
Registration #20	2019-03-20	55.357 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1760 mm
Height	1480 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1293 kg
Max. allowed weight	1720 kg

Additional information

Fuel tank capacity	53 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4FAAZ240775