



ET03FGD

report date: 2024-03-28

General information

| | |
|---------------------|-------------------|
| Make | JAGUAR |
| Model | XJR V8 R |
| Colour | Silver |
| Year of manufacture | 2003 |
| Top speed | 155 mph |
| 0 - 60 mph | 5.0 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 400 BHP |
| Max. torque | 552 Nm at 3.500 rpm |
| Engine capacity | 4.196 cc |
| Cylinders | 8 |
| Fuel type | Petrol |
| Consumption city | 15.2 mpg |
| Consumption extra urban | 31.4 mpg |
| Consumption combined | 23.0 mpg |
| CO2 emission | 299 g/km |
| CO2 label | M |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2021-09-14 |
| Pictures | 20 |
| Listing price | View report |



source: autotrader.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-08-03 |
| Pictures | 20 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-12-05 |
| MOT pass rate | 71 % |
| MOT passed | 15 |
| Failed MOT tests | 6 |
| Total advice items | 48 |
| Total items failed | 6 |

| | |
|------------------|--|
| MOT #21 | 2023-12-06 12:03 |
| MOT test number | 355772890945 |
| Result | ✓ Passed |
| Next expiry date | 2024-12-05 |
| Advice | Nearside Rear Brake pad(s) wearing thin hand brake (1.1.13 (a) (ii)) |

| | |
|-----------------|---|
| MOT #20 | 2023-12-04 09:33 |
| MOT test number | 526288980884 |
| Result | ✗ Failed |
| Advice | Nearside Rear Brake pad(s) wearing thin hand brake (1.1.13 (a) (ii)) |
| MAJOR | Offside Front Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |
| MAJOR | Offside Rear Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |
| MAJOR | Nearside Front Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |
| MAJOR | Nearside Rear Outer Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii)) |
| MAJOR | Front Windscreen washer provides insufficient washer liquid (3.5 (a)) |

**MOT #19**

2022-09-12 13:30

MOT test number

676047845319

Result

✓ Passed

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #18**

2022-09-09 10:03

MOT test number

577460899843

Result

✗ Failed

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Offside Rear Anti-roll bar ball joint dust cover missing (5.3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Offside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MAJOR** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MAJOR** Nearside Rear Anti-roll bar linkage ball joint dust cover missing (5.3.4 (b) (ii))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MAJOR** Nearside Front Inner Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #17** 2021-09-01 13:33**MOT test number** 286420710033**Result** ✓ Passed**Minor** Offside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Minor** Nearside Rear Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**MOT #16** 2019-10-25 08:02**MOT test number** 638139070290**Result** ✓ Passed**MOT #15** 2019-10-24 07:55**MOT test number** 712425001370**Result** ✗ Failed**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MAJOR** Offside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Offside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**MAJOR** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MOT #14** 2018-10-08 15:48**MOT test number** 257218090905**Result** ✓ Passed**MOT #13** 2018-10-08 11:15**MOT test number** 371863409166**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MOT #12** 2017-09-05 09:34**MOT test number** 515076159885**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Engine warning light remains on**Advice** Rear Brake pad(s) wearing thin footbrake pads (3.5.1g)**Advice** Rear Brake pad(s) wearing thin parking brake pads (3.5.1g)**MOT #11** 2016-07-07 11:57**MOT test number** 458348602372**Result** ✓ Passed**MOT #10** 2015-04-30 12:16**MOT test number** 656720925196**Result** ✓ Passed**Notice** Engine warning light remains on**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2014-02-21 10:22**MOT test number** 956222254038**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #8** 2012-07-12 17:29**MOT test number** 377924792136**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**MOT #7** 2012-07-12 11:01**MOT test number** 865864292110**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Inner Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Offside Rear fog lamp not working (1.3.2b)**Fail** Brakes imbalanced across an axle (3.7.B.5b)**MOT #6** 2011-06-23 10:18**MOT test number** 856444671199**Result** ✓ Passed**MOT #5** 2009-07-04 10:38**MOT test number** 384205889104**Result** ✓ Passed**Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)



| | |
|-----------------|---|
| MOT #4 | 2008-06-18 11:09 |
| MOT test number | 460460878146 |
| Result | ✓ Passed |
| MOT #3 | 2008-06-17 11:42 |
| MOT test number | 742579068114 |
| Result | ✗ Failed |
| Fail | Rear registration plate character(s) incorrectly spaced (6.3.4a) |
| Fail | Front registration plate character(s) incorrectly spaced (6.3.4a) |
| MOT #2 | 2007-07-02 17:58 |
| MOT test number | 200563287144 |
| Result | ✓ Passed |
| MOT #1 | 2006-06-30 11:47 |
| MOT test number | 883921686102 |
| Result | ✓ Passed |



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
5 December 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 December |
| Days left | 216 |
| MOT expiry date | 5 December 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | K |
| Single payment (12 months) | £ 395,00,- |
| Single six month payment | £ 217,25,- |
| Total payable by 12 monthly instalments | £ 414,75,- |



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-28 |
| Current registration | |
| Plate since | 2024-03-28 |

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

| | | |
|-------------------|------------|------|
| Finance company | XXXXXXXXXX | XXXX |
| Date of agreement | XXXXXXXXXX | XXXX |
| Agreement type | XXXXXXXXXX | XXXX |
| Agreement term | XXXXXXXXXX | XXXX |
| Agreement number | XXXXXXXXXX | XXXX |
| Contact info | XXXXXXXXXX | XXXX |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 24 |
| First mileage registration | 2003-06-28 |
| Last registration | 2023-12-06 |
| Complete history | See info |



| | | |
|------------------|------------|------------|
| Registration #1 | 2003-06-28 | 28 mi |
| Registration #2 | 2006-06-30 | 65.539 mi |
| Registration #3 | 2007-07-02 | 73.944 mi |
| Registration #4 | 2008-06-17 | 78.446 mi |
| Registration #5 | 2008-06-18 | 78.450 mi |
| Registration #6 | 2009-07-04 | 82.296 mi |
| Registration #7 | 2011-06-23 | 89.079 mi |
| Registration #8 | 2012-07-12 | 92.637 mi |
| Registration #9 | 2012-07-12 | 92.637 mi |
| Registration #10 | 2014-02-21 | 97.365 mi |
| Registration #11 | 2015-04-30 | 101.006 mi |
| Registration #12 | 2016-07-07 | 104.585 mi |
| Registration #13 | 2016-07-07 | 104.585 mi |
| Registration #14 | 2016-07-07 | 104.585 mi |
| Registration #15 | 2016-07-07 | 104.585 mi |
| Registration #16 | 2016-07-07 | 104.585 mi |
| Registration #17 | 2016-07-07 | 104.585 mi |
| Registration #18 | 2016-07-07 | 104.585 mi |
| Registration #19 | 2016-07-07 | 104.585 mi |
| Registration #20 | 2016-07-07 | 104.585 mi |
| Registration #21 | 2016-07-07 | 104.585 mi |
| Registration #22 | 2016-07-07 | 104.585 mi |
| Registration #23 | 2016-07-07 | 104.585 mi |
| Registration #24 | 2016-07-07 | 104.585 mi |

More info >



Dimensions & weight

| | |
|-------------|---------|
| Width | 2108 mm |
| Height | 1448 mm |
| Length | 5090 mm |
| Wheel base | 3034 mm |
| Kerb weight | 1671 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 85 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 4 |
| Number of axles | 2 |
| Engine number | 0306042006TB |