



RENAULT

YF54HZD

report date: 2024-03-29

General information

Make	RENAULT
Model	MASTER CCLL35 DCI 120 C/C
Colour	White
Year of manufacture	2005
Gearbox	5 speed Manual

Engine & fuel consumption

Power	115 BHP
Engine capacity	2.463 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-02
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-06-27
MOT pass rate	52 %
MOT passed	16
Failed MOT tests	15
Total advice items	44
Total items failed	89

MOT #31	2023-06-28 07:55
MOT test number	268672812990
Result	✓ Passed
Next expiry date	2024-06-27

MOT #30	2023-06-27 12:11
MOT test number	571327851887
Result	✗ Failed
Fail	Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
Fail	Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
Fail	Offside Outline marker lamp not working middle (4.2.1 (a) (ii))

MOT #29	2022-06-15 11:27
MOT test number	532594785017
Result	✓ Passed
Advice	Injector leak

**MOT #28**

2022-06-13 09:59

MOT test number

509386872765

Result**✗ Failed****Fail** Offside Rear Wheel bearing rough when rotated (5.1.3 (b) (i))**Advice** Injector leak**Fail** Offside Rear Anti-roll bar pin or bush excessively worn Missing (5.3.4 (a) (i))**Fail** Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #27**

2021-06-25 12:20

MOT test number

283501994539

Result**✓ Passed****Advice** Nearside Front Upper top bearing noisy**Advice** Both front dropside hinges missing**Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**MOT #26**

2021-06-24 12:35

MOT test number

119102127730

Result**✗ Failed****Minor** Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))**Fail** Nearside Front Brake pipe excessively corroded (1.1.11 (c))**Advice** Nearside Front Upper top bearing noisy**Advice** Both front dropside hinges missing

**MOT #25**

2021-06-16 15:10

MOT test number

144573761855

Result**✗ Failed****Fail**

Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

Fail

Nearside Front Brake pipe excessively corroded (1.1.11 (c))

Fail

Front Exhaust has a major leak of exhaust gases flexy joint broken (6.1.2 (a))

Advice

Nearside Front Upper top bearing noisy

Advice

Rear Brake pad(s) wearing thin both inner pads (1.1.13 (a) (ii))

Fail

Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Advice

Both front dropside hinges missing

Minor

Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Fail

Rear Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #24

2020-08-06 09:24

MOT test number

945976083836

Result**✓ Passed****MOT #23**

2019-08-08 15:05

MOT test number

723004048789

Result**✓ Passed**

**MOT #22**

2019-08-08 15:05

MOT test number

547588213254

Result

✗ Failed

- Pass with rectification** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (4.4.3 (a))
- Pass with rectification** Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))
- Pass with rectification** Offside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Pass with rectification** Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))
- Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Pass with rectification** Nearside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))
- Pass with rectification** Offside Front Upper Suspension arm ball joint dust cover no longer prevents the ingress of dirt split (5.3.4 (b) (ii))
- Pass with rectification** Hazard warning switch inoperative (4.4.2 (a) (ii))

MOT #21

2018-07-25 13:06

MOT test number

471266551812

Result

✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #20

2017-07-03 16:50

MOT test number

841854283779

Result

✓ Passed



MOT #19	2017-07-03 09:53
MOT test number	381974605458
Result	✗ Failed
Fail	Nearside Rear Direction indicator adversely affected by the operation of another lamp (1.4.A.2h)
Fail	Nearside Registration plate lamp not working (1.1.C.1d)
Fail	Exhaust system not adequately supported (7.1.1)
Fail	Nearside Headlamp not working on dipped beam (1.7.5a)
Fail	Offside Rear Direction indicator incorrect colour (1.4.A.2f)
Fail	Central Front Brake cable has wires broken and is significantly weakened (3.5.1b)

MOT #18	2016-06-14 16:38
MOT test number	298149204122
Result	✓ Passed

**MOT #17**

2016-06-13 08:56

MOT test number

268661139385

Result**✗ Failed****Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Stop lamp emits other than a steady red light (1.2.1e)**Fail** Brake pipe excessively corroded front to rear (3.6.B.2c)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Fail** Nearside Rear Parking brake lever has no reserve travel (3.1.6b)**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Fail** Offside Rear Stop lamp not working (1.2.1b)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #16**

2015-06-22 08:32

MOT test number

407743775101

Result**✓ Passed****Advice** Front Exhaust has a minor leak of exhaust gases (7.1.2)

**MOT #15**

2015-06-17 15:34

MOT test number

799818765169

Result**✗ Failed****Fail**

Offside Front Lower Ball joint has excessive play (2.2.B.1f)

Advice

Front Exhaust has a minor leak of exhaust gases (7.1.2)

Fail

Front registration plate insecure (6.3.1b)

Fail

Nearside Front Lower Ball joint has excessive play (2.2.B.1f)

Fail

Rear Exhaust system not adequately supported (7.1.1)

MOT #14

2014-09-13 11:06

MOT test number

209396254220

Result**✓ Passed****Notice**

Both front and rear N/S side body marker lights inop

Notice

N/S wiper arm linkage worn

Advice

Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Notice

Clutch pedal rubber split

Notice

N/S/R lamp lens cracked

**MOT #13**

2014-09-11 09:49

MOT test number

228144954223

Result**✗ Failed****Fail** Front passenger door catch deteriorated so the door cannot be readily opened or closed (6.2.B.2)**Notice** Aux drive belt deteriorated**Advice** Nearside Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)**Notice** Nail in offside front tyre**Fail** Horn not working (1.6.2a)**Notice** Both front and rear N/S side body marker lights inop**Fail** Nearside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Driver's door catch deteriorated so the door cannot be readily opened or closed (6.2.B.2)**Notice** N/S wiper arm linkage worn**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Fail** Rear fog lamp emits a light other than red (1.3.2e)**Notice** 1 x rear body bolt loose N/S/R**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Notice** Nail in offside rear tyre**Notice** Clutch pedal rubber split**Fail** Offside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Nearside Windscreen wiper blade insecure (8.2.2)**Notice** N/S/R lamp lens cracked**Fail** Offside Front Suspension arm ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)



MOT #12	2013-07-18 10:55
MOT test number	727439293154
Result	✓ Passed

MOT #11	2012-07-04 14:44
MOT test number	659366382192
Result	✓ Passed

Advice Driver's door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)

Advice Front passenger door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)



MOT #10 2012-07-02 14:45

MOT test number 768984082196

Result ✗ Failed

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice Driver's door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)

Fail Nearside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

Fail Nearside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

Fail Windscreen washer provides insufficient washer liquid (8.2.3)

Fail Parking brake: efficiency below requirements (3.7.C.1b)

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Fail Offside Front constant velocity joint gaiter deteriorated to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Advice Front passenger door catch deteriorated but the door can still be readily opened and closed (6.2.B.2)

Fail Offside Rear Anti-roll bar has excessive play in a pin/bush (2.4.G.2)

Fail Offside Rear Anti-roll bar linkage has excessive play in a pin/bush (2.4.G.2)

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #9 2011-06-17 12:46

MOT test number 329058761104

Result ✓ Passed

**MOT #8** 2011-06-02 14:51**MOT test number** 967143051158**Result** ✗ Failed

- Fail** Offside Upper Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Lower Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Registration plate lamp not working (1.1.C.1d)
- Fail** Offside Rear position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Upper Front position lamp(s) not working (1.1.A.3b)
- Fail** Offside Lower Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)

MOT #7 2010-01-26 17:09**MOT test number** 121536420037**Result** ✓ Passed

**MOT #6** 2010-01-25 16:57**MOT test number** 590255120041**Result** ✗ Failed

- Fail** All position lamps not working (1.1.A.3b)
- Fail** Offside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Rear fog lamp not working (1.3.2b)
- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Rear Anti-roll bar rubber bush deteriorated resulting in excessive movement (2.4.G.2)
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Fail** Offside Stop lamp not working (1.2.1b)

MOT #5 2010-01-25 15:52**MOT test number** 204135020076**Result** ✗ Failed

- Fail** Parking brake: efficiency below requirements (3.7.B.7)
- Fail** Service brake: efficiency below requirements (3.7.B.7)

MOT #4 2009-02-27 12:20**MOT test number** 362378159086**Result** ✓ Passed

**MOT #3**

2009-02-24 18:04

MOT test number

191105759424

Result**✗ Failed****Fail** Nearside All position lamps not working (1.1.A.3b)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Fail** Offside All position lamps not working (1.1.A.3b)**MOT #2**

2008-01-23 09:57

MOT test number

213703228055

Result**✓ Passed****Advice** Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #1**

2008-01-23 09:57

MOT test number

351753828075

Result**✗ Failed****Advice** Front Lower Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Pass with rectification** Nearside Headlamp aim too high (1.8)



Tax & MOT check

✕
Untaxed

Tax expired:
26 April 2024

✓
MOT

Expires:
27 June 2024

Tax status	Expired at 26 April 2024
Days left	4 days too late
MOT expiry date	27 June 2024
Full MOT history	See MOT history



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	31
First mileage registration	2005-01-24
Last registration	2023-06-28
Complete history	See info



Registration #1	2005-01-24	24 mi
Registration #2	2008-01-23	54.821 mi
Registration #3	2009-02-24	72.600 mi
Registration #4	2009-02-27	726.006 mi
Registration #5	2010-01-25	92.524 mi
Registration #6	2010-01-26	92.524 mi
Registration #7	2011-06-02	107.338 mi
Registration #8	2011-06-17	107.349 mi
Registration #9	2012-07-02	128.461 mi
Registration #10	2012-07-04	128.470 mi
Registration #11	2013-07-18	149.371 mi
Registration #12	2014-09-11	170.161 mi
Registration #13	2014-09-13	170.170 mi
Registration #14	2015-06-17	174.261 mi
Registration #15	2015-06-22	174.270 mi
Registration #16	2016-06-13	179.976 mi
Registration #17	2016-06-20	181.377 mi
Registration #18	2016-06-21	181.377 mi
Registration #19	2016-06-22	181.377 mi
Registration #20	2016-06-23	181.377 mi
Registration #21	2016-06-24	181.377 mi
Registration #22	2016-06-25	181.377 mi
Registration #23	2016-06-26	181.377 mi
Registration #24	2016-06-27	181.377 mi
Registration #25	2016-06-28	181.377 mi
Registration #26	2016-06-29	181.377 mi

Registration #27	2025-25-25	25,252,442
Registration #28	2025-25-25	25,252,442
Registration #29	2025-25-25	25,252,442
Registration #30	2025-25-25	25,252,442
Registration #31	2025-25-25	25,252,442

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1990 mm
Max. allowed weight	3500 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	C094203