



report date: 2024-03-28

General information

Make	VOLVO
Model	XC90 D5 SE LUX AWD
Colour	Silver
Year of manufacture	2011
Top speed	127 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	200 BHP
Max. torque	420 Nm at 2.000 rpm
Engine capacity	2.400 cc
Cylinders	5
Fuel type	Diesel
Consumption city	25.7 mpg
Consumption extra urban	41.5 mpg
Consumption combined	34.0 mpg
CO2 emission	219 g/km
CO2 label	K





Internet history

Entry 2

Date	2023-09-16
Pictures	18
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](https://www.cargurus.co.uk)

Entry 1

Date	2021-02-06
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

MOT expiry date	2024-09-12
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	45
Total items failed	3

## MOT #15 2023-09-13 15:00

MOT test number 609855316140

Result ✓ Passed

Next expiry date 2024-09-12

- Advice** Offside Rear Lower Suspension arm pin or bush worn but not resulting in excessive movement inner bush (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement outter bush (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement outter bush (5.3.4 (a) (i))
- Advice** General underbody wear

## MOT #14 2022-10-18 08:10

MOT test number 347601850561

Result ✓ Passed

- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

## MOT #13 2021-09-30 11:26

MOT test number 623508695293

Result ✓ Passed

- Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #12** 2021-09-27 09:02**MOT test number** 221409728238**Result** ✗ Failed**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #11** 2020-09-28 16:50**MOT test number** 628118654290**Result** ✓ Passed**Advice** Coil spring corroded Both front (5.3.1 (b) (i))**MOT #10** 2019-03-02 09:42**MOT test number** 415738808848**Result** ✓ Passed**MOT #9** 2019-02-27 08:51**MOT test number** 863496497415**Result** ✗ Failed**MAJOR** Nearside Rear Seat belt damaged Rear Seat Belt (7.1.2 (b) (i))**MAJOR** Parking brake efficiency below requirements (1.4.2 (a) (i))**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Offside Rear Service brake excessively binding (1.2.1 (f))

**MOT #8**

2018-04-10 13:25

**MOT test number**

544376008030

**Result**

✓ Passed

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #7**

2018-04-10 13:25

**MOT test number**

543448997643

**Result**

✗ Failed

**Pass with rectification** Offside Rear Registration plate lamp not working (1.1.C.1d)

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Front Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Nearside Front Direction indicator slightly discoloured (1.4.A.2f)

**MOT #6**

2017-04-07 11:18

**MOT test number**

667772424674

**Result**

✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)



MOT #5	2016-04-11 10:22
MOT test number	255254711266
Result	✓ Passed
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)

MOT #4	2015-04-10 11:41
MOT test number	386860105146
Result	✓ Passed

MOT #3	2015-03-26 10:03
MOT test number	915305885060
Result	✓ Passed
Advice	Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Engine covers fitted obscuring some components in the engine bay
Advice	Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Under-trays fitted obscuring some underside components
Notice	Brake pipes covered in a protective wax

**MOT #2** 2014-04-10 15:41**MOT test number** 938740304161**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2014-04-10 15:41**MOT test number** 336860904146**Result** ✗ Failed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 December 2024

✓  
**MOT**  
**Expires:**  
12 September 2024

<b>Tax status</b>	Valid until 1 December
<b>Days left</b>	216
<b>MOT expiry date</b>	12 September 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-





Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-04-14
Last registration	2023-09-13
Complete history	<a href="#">See info</a>



Registration #1	2011-04-14	19 mi
Registration #2	2014-04-10	40.363 mi
Registration #3	2015-03-26	50.824 mi
Registration #4	2015-04-10	51.226 mi
Registration #5	2016-04-11	62.443 mi
Registration #6	2017-04-07	72.263 mi
Registration #7	2018-04-10	83.845 mi
Registration #8	2018-04-10	83.845 mi
Registration #9	2019-02-27	89.104 mi
Registration #10	2019-05-29	95.377 mi
Registration #11	2019-05-29	95.377 mi
Registration #12	2019-05-29	95.377 mi
Registration #13	2019-05-29	95.377 mi
Registration #14	2019-05-29	95.377 mi
Registration #15	2019-05-29	95.377 mi
Registration #16	2019-05-29	95.377 mi
Registration #17	2019-05-29	95.377 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1898 mm
Height	1784 mm
Length	4807 mm
Wheel base	2857 mm
Kerb weight	2158 kg
Max. allowed weight	2750 kg

Additional information

Fuel tank capacity	68 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7

<b>Number of axles</b>	2
<b>Engine number</b>	1044305