




report date: 2024-03-29

## General information

Make	VAUXHALL
Model	MOVANO
Colour	Blue
Year of manufacture	2017
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	128 BHP
Max. torque	330 Nm
Engine capacity	2.299 cc
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	39.2 mpg
Consumption combined	35.8 mpg
CO2 emission	207 g/km
CO2 label	K





## Internet history

### Entry 2

Date	2021-11-03
Pictures	14
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)

### Entry 1

Date	2021-08-24
Pictures	14
Listing price	<a href="#">View report</a>



source: [cargurus.co.uk](http://cargurus.co.uk)



MOT history

MOT expiry date	2024-08-11
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	22
Total items failed	7

MOT #82023-08-11 11:47

MOT test number967940181193

Result✓ Passed

Next expiry date2024-08-11

- Advice

Near side Front Bonnet Dented
- Minor

Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))
- Advice

Near Side Front Wheel Arch Slightly Damage
- Minor

Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))
- Advice

Offside Front Bumper Slightly Damage
- Minor

Offside Front Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #7** 2023-08-11 11:47**MOT test number** 657421620263**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))**Pass with rectification** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Offside Front Bumper Slightly Damage**Minor** Offside Front Obligatory mirror slightly loose (3.3 (b) (i))**Pass with rectification** Rear Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))**Advice** Near side Front Bonnet Dented**Minor** Nearside Front Obligatory mirror slightly loose (3.3 (b) (i))**Pass with rectification** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Near Side Front Wheel Arch Slightly Damage**Minor** Offside Front Obligatory mirror slightly damaged (3.3 (b) (i))**MOT #6** 2022-08-12 14:54**MOT test number** 307963064451**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2022-08-12 14:54**MOT test number** 322630260514**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**MOT #4** 2021-07-08 15:35**MOT test number** 253472114593**Result** ✓ Passed**MOT #3** 2021-07-08 08:41**MOT test number** 378582111585**Result** ✗ Failed**Fail** Offside Front Obligatory mirror seriously damaged, affecting the rear view (3.3 (b) (ii))**MOT #2** 2020-07-29 13:10**MOT test number** 711336490927**Result** ✓ Passed**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Outline marker lamp incorrect colour (4.2.3 (a) (i))**MOT #1** 2020-07-28 10:58**MOT test number** 425775229913**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Outline marker lamp incorrect colour (4.2.3 (a) (i))**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Minor** Offside Obligatory mirror slightly damaged (3.3 (b) (i))**Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
11 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	11 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	39
<b>Standard rate (12 months)</b>	£ 320,00,-
<b>Standard rate (6 months)</b>	£ 176,00,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	LL17PXF
Plate since	2019-06-29
Current registration	LL17PXF
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2017-08-18
Last registration	2023-08-11
Complete history	<a href="#">See info</a>



Registration #1	2017-08-18	10 mi
Registration #2	2020-07-28	38.060 mi
Registration #3	2020-07-29	38.060 mi
Registration #4	2021-07-08	48.445 mi
Registration #5	2021-07-08	48.455 mi
Registration #6	2023-08-11	55.277 mi
Registration #7	2023-08-11	55.277 mi
Registration #8	2023-08-11	55.277 mi
Registration #9	2023-08-11	55.277 mi
Registration #10	2023-08-11	55.277 mi
Registration #11	2023-08-11	55.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	96%
Children	90%
Pedestrian	67%
Safety systems	100%
Overall rating	89%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2470 mm
Height	2500 mm
Length	6198 mm
Kerb weight	1984 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	M9T -C058600 L0B