



General information

Make	MINI
Model	MINI COOPER
Colour	White
Year of manufacture	2013
Top speed	113 mph
0 - 60 mph	11.6 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	122 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	39.2 mpg
CO2 emission	168 g/km
CO2 label	H






Internet history

Entry 2

Date	2021-09-14
Pictures	12
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-09-14
Pictures	33
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-02-01
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	6
Total items failed	4

MOT #11 2024-01-17 14:37

MOT test number 323434066012

Result ✓ Passed

Next expiry date 2025-02-01

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Front Sub-frame corroded but not seriously weakened (5.3.3 (b) (i))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #10 2023-01-31 15:16

MOT test number 906595212436

Result ✓ Passed

MOT #9 2022-01-28 15:56

MOT test number 917618023876

Result ✓ Passed

MOT #8 2021-02-02 10:06

MOT test number 736541843311

Result ✓ Passed

Advice Engine covers and under trays fitted obscuring some testable items

**MOT #7** 2020-01-21 09:26**MOT test number** 305366918025**Result** ✓ Passed**MOT #6** 2019-01-23 17:34**MOT test number** 851538062422**Result** ✓ Passed**MOT #5** 2019-01-23 09:48**MOT test number** 571154011030**Result** ✗ Failed**Fail** Nearside Rear Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #4** 2018-01-05 10:36**MOT test number** 986937482110**Result** ✓ Passed**Advice** Eml**MOT #3** 2017-01-12 14:06**MOT test number** 652892690557**Result** ✓ Passed**MOT #2** 2016-01-06 10:27**MOT test number** 497150620721**Result** ✓ Passed



MOT #1	2016-01-05 10:38
MOT test number	841403390044
Result	✗ Failed
<div><div>Fail</div>Offside Front Tyre has ply or cords exposed (4.1.D.1b)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 February 2025

Tax status	Valid until 1 September
Days left	126
MOT expiry date	1 February 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2013-01-31
Last registration	2024-01-17
Complete history	See info



Registration #1	2013-01-31	14 mi
Registration #2	2016-01-05	28.529 mi
Registration #3	2016-01-06	28.542 mi
Registration #4	2017-01-12	35.487 mi
Registration #5	2018-01-05	39.653 mi
Registration #6	2019-01-23	50.463 mi
Registration #7	2019-01-23	50.465 mi
Registration #8	2019-01-23	50.465 mi
Registration #9	2019-01-23	50.465 mi
Registration #10	2019-01-23	50.465 mi
Registration #11	2019-01-23	50.465 mi
Registration #12	2019-01-23	50.465 mi
Registration #13	2019-01-23	50.465 mi
Registration #14	2019-01-23	50.465 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	84%
Children	83%
Pedestrian	63%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1295 kg
Max. allowed weight	1805 kg

Additional information

Fuel tank capacity	47 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	A708j575