





General information

| Make | NISSAN |
|---------------------|---------------------|
| Model | PULSAR ACENTA DIG-T |
| Colour | Black |
| Year of manufacture | 2015 |
| Top speed | 118 mph |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 115 BHP | 0 < 101 A |
|-------------------------|---------------------|-----------|
| Max. torque | 190 Nm at 2.000 rpm | 101 - 120 |
| Engine capacity | 1.198 cc | 121 - 140 |
| Cylinders | 4 | 141 - 165 |
| Fuel type | Petrol | 166 - 185 |
| Consumption city | 44.8 mpg | 186 - 225 |
| Consumption extra urban | 65.7 mpg | 225+ |
| Consumption combined | 56.5 mpg | |
| CO2 emission | 117 g/km | |
| CO2 label | С | |





Internet history

| Entry | 2 |
|-------|---|
| | |


Date Pictures 2021-07-25

£99 + VAT

Listing price

View report

6



source: cargurus.co.uk

Entry 1

Date

Pictures

Listing price

2021-07-24 6

View report

source: autotrader.co.uk







MOT history

| MOT expiry date | 2024-07-29 |
|--------------------|------------|
| MOT pass rate | 88 % |
| MOT passed | 7 |
| Failed MOT tests | 1 |
| Total advice items | 10 |
| Total items failed | 5 |

| MOT #8 | 2023-07-19 09:19 |
|--|------------------|
| MOT test number | 141753215715 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-29 |
| Advice Rear Brake pipe corroded, covered in grease or other material | l (1.1.11 (c)) |
| Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 | 3 (e)) |
| Advice Front Suspension arm ball joint has slight play both (5.3.4 (a) (| (i)) |

| MOT #7 | 2022-07-28 14:08 |
|---|------------------|
| MOT test number | 128159307363 |
| Result | ✓ Passed |
| Advice Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |





| MOT # | 6 | 2022-07-26 13:51 |
|--------|--|------------------|
| MOT te | est number | 389781411648 |
| Result | | 🗙 Failed |
| Advid | Offside Front Track rod end ball joint has slight play (2.1.3 (b) (i)) | |
| Fail | Nearside Rear Parking brake inoperative on one side (1.4.1 (a)) | |
| Fail | Nearside Front Outer Tyre tread depth below requirements of 1.6mm (5.2.3 (e)) | |
| Fail | Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i)) | |
| Fail | Parking brake efficiency below requirements (1.4.2 (a) (i)) | |
| Fail | Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h) |) |

| MOT #5 | 2021-07-30 08:15 |
|-----------------|------------------|
| MOT test number | 705778913364 |
| Result | ✓ Passed |

| MOT #4 | | 2020-08-27 09:06 |
|----------|---|------------------|
| MOT test | number | 285335777397 |
| Result | | ✓ Passed |
| Advice | Offside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Items removed from driver's view prior to test items removed from mirror | |

| MOT #3 | | 2019-09-05 11:13 |
|----------|--|------------------|
| MOT test | number | 530594095970 |
| Result | | ✓ Passed |
| Advice | Front Brake disc worn, but not excessively lipped (1.1.14 (a) (i)) | |
| Advice | Offside Front Nail in tyre | |
| Advice | Slight ticking/rattle noise from timing cover area of engine | |





| MOT #2 | 2018-08-31 16:04 |
|-----------------|------------------|
| MOT test number | 702310179019 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2017-09-07 17:19 |
| MOT test number | 349441809031 |
| Result | ✓ Passed |



Tax & MOT check

| Tax due: 1 August 2024 | ✓ Taxed | Expires: 29 July 2024 | ✓ МОТ |
|----------------------------------|------------|---------------------------------|----------------------|
| Tax status | | | Valid until 1 August |
| Days left | | | 94 |
| MOT expiry date | | | 29 July 2024 |
| Full MOT history | | | See MOT history |
| Tax calculation | | | |
| | | 40 | |

| Vehicle class | 48 |
|---|----------------|
| Band | С |
| Single payment (12 months) | £ 35,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | £ 36,75,- |





Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|-----------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPL |
| Date | · · · |
| Category | AMPL |
| Туре | |

Extra NISSAN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |





Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this NISSAN had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | |





Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this NISSAN is financed.


| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 11 |
| First mileage registration | 2015-03-01 |
| Last registration | 2023-07-19 |
| Complete history | <u>See info</u> |



| Registration #1 | 2015-03-01 | 11 mi |
|------------------|------------|------------|
| Registration #2 | 2017-09-07 | 21.409 mi |
| Registration #3 | 2018-08-31 | 32.297 mi |
| Registration #4 | 2019-09-05 | 41.543 mi |
| Registration #5 | 2020-08-27 | 49.204 mi |
| Registration #6 | | 11.777 est |
| Registration #7 | | 11.777 mi |
| Registration #8 | | 11.777 mi |
| Registration #9 | | 11.777 mi |
| Registration #10 | | 11.777 esi |
| Registration #11 | | 11.777 mi |





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| 50501 | |
| \$0566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 84% |
| Children | 81% |
| Pedestrian | 75% |
| Safety systems | 68% |
| Overall rating | 78% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|------------------|
| Width | 1768 mm |
| Height | 1520 mm |
| Length | 4385 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1304 kg |
| Max. allowed weight | 1750 kg |
| Additional information | |
| Fuel tank capacity | 46 |
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 12/12 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 115280A |