



report date: 2024-03-28

General information

Make	CITROEN
Model	RELAY 35 L3H2 ENTERPRISE BLUEHDI
Colour	White
Year of manufacture	2017
Top speed	92 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	130 BHP
Max. torque	350 Nm at 1.750 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	47.9 mpg
Consumption combined	45.6 mpg
CO2 emission	163 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-01-29
Pictures	1
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-02-04
MOT pass rate	50 %
MOT passed	4
Failed MOT tests	4
Total advice items	17
Total items failed	11

MOT #8 2024-02-05 15:40

MOT test number 889557732958

Result ✓ Passed

Next expiry date 2025-02-04

- Advice** Body damage n/s no sharp edges
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** O/s mirror damaged
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #7 2024-01-24 11:37

MOT test number 976611055411

Result ✗ Failed

- Fail** Nearside Stop lamp(s) emits other than a steady red light (4.3.3 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** O/s mirror damaged
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Body damage n/s no sharp edges

**MOT #6**

2022-09-29 08:08

MOT test number

417140469129

Result

✓ Passed

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Windscreen wiper blade defective both (3.4 (b) (i))**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Advice** Nearside Front Daytime running light not working**MOT #5**

2022-09-26 10:28

MOT test number

812769025361

Result

✗ Failed

Fail Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Advice** Nearside Front Daytime running light not working**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Nearside Rear Tyre(s) with different aspect ratios are fitted on the same axle. (5.2.3 (b))**Minor** Windscreen wiper blade defective both (3.4 (b) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Advice** Nearside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))**Fail** Headlamp aim not tested (4.1.2 (b))**MOT #4**

2021-09-16 12:04

MOT test number

762608698084

Result

✓ Passed

Advice Offside Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

**MOT #3** 2021-09-16 09:54**MOT test number** 291233487865**Result** ✗ Failed**Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #2** 2020-09-24 13:05**MOT test number** 159563286089**Result** ✓ Passed**MOT #1** 2020-09-24 13:05**MOT test number** 505658839317**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (3.5 (a))**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
4 February 2025

Tax status	Valid until 1 March
Days left	306
MOT expiry date	4 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 320,00,-
Standard rate (6 months)	£ 176,00,-



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-09-29
Last registration	2024-02-05
Complete history	See info



Registration #1	2017-09-29	18 mi
Registration #2	2020-09-24	65.007 mi
Registration #3	2020-09-24	65.007 mi
Registration #4	2020-09-24	65.007 mi
Registration #5	2021-09-16	83.867 mi
Registration #6	2020-09-24	65.007 mi
Registration #7	2020-09-24	65.007 mi
Registration #8	2020-09-24	65.007 mi
Registration #9	2020-09-24	65.007 mi
Registration #10	2020-09-24	65.007 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	59%
Children	86%
Pedestrian	26%
Safety systems	26%
Overall rating	54%
Video	see crash video



Dimensions & weight

Width	2508 mm
Height	2524 mm
Length	5998 mm
Kerb weight	1975 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	3
Engine number	DYZZ4006301