



RE09YJT


report date: 2024-03-28

General information

Make	AUDI
Model	A3 TDI DPF S LINE
Colour	Black
Year of manufacture	2009
Top speed	143 mph
0 - 60 mph	8.3 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	170 BHP
Max. torque	350 Nm at 2.500 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	40.4 mpg
Consumption extra urban	64.2 mpg
Consumption combined	53.3 mpg
CO2 emission	134 g/km
CO2 label	E





MOT history

MOT expiry date	2025-03-13
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	25
Total items failed	3

MOT #16	2024-03-14 12:28
MOT test number	298558813605
Result	✓ Passed
Next expiry date	2025-03-13

MOT #15	2022-12-21 11:50
MOT test number	126495559895
Result	✓ Passed

MOT #14	2022-12-21 11:50
MOT test number	928265553438
Result	✗ Failed

- Pass with rectification** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))
- Pass with rectification** Nearside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

MOT #13	2021-07-27 10:37
MOT test number	357251464609
Result	✓ Passed

- Advice** Items removed from driver's view prior to test air freshener
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

**MOT #12** 2021-07-27 10:37**MOT test number** 205832432708**Result** ✗ Failed**Advice** Items removed from driver's view prior to test air freshener**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #11** 2020-06-13 09:14**MOT test number** 332035272557**Result** ✓ Passed**Advice** Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))**Advice** Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2019-06-18 12:44**MOT test number** 769523113395**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9** 2019-06-07 14:43**MOT test number** 136725342001**Result** ✗ Failed**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #8** 2018-10-18 13:37**MOT test number** 461569974014**Result** ✓ Passed**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #7** 2018-10-10 10:33**MOT test number** 765901857202**Result** ✗ Failed**MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))**MOT #6** 2017-10-26 15:20**MOT test number** 105933292389**Result** ✓ Passed

**MOT #5** 2016-07-07 14:33**MOT test number** 998208774891**Result** ✓ Passed**Advice** Engine management light is on indicating a fault**MOT #4** 2015-07-08 12:52**MOT test number** 409919785194**Result** ✓ Passed**MOT #3** 2014-07-09 12:33**MOT test number** 239210494493**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** Nail in offside rear tyre**MOT #2** 2013-07-01 11:46**MOT test number** 895662783103**Result** ✓ Passed**MOT #1** 2012-07-04 16:43**MOT test number** 217386682401**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 December 2024

✓
MOT
Expires:
13 March 2025

Tax status	Valid until 1 December
Days left	216
MOT expiry date	13 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-




Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	RE09YJT
Plate since	2024-03-28
Current registration	RE09YJT
Plate since	2024-03-28

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-06-08
Last registration	2024-03-14
Complete history	See info



Registration #1	2009-06-08	14 mi
Registration #2	2012-07-04	53.398 mi
Registration #3	2013-07-01	62.585 mi
Registration #4	2014-07-09	74.611 mi
Registration #5	2015-07-08	86.683 mi
Registration #6	2016-07-07	103.766 mi
Registration #7	2017-10-26	122.538 mi
Registration #8	2018-10-10	132.910 mi
Registration #9	2018-10-18	133.115 mi
Registration #10	2019-06-20	151.377 mi
Registration #11	2019-06-20	151.377 mi
Registration #12	2019-06-20	151.377 mi
Registration #13	2019-06-20	151.377 mi
Registration #14	2019-06-20	151.377 mi
Registration #15	2019-06-20	151.377 mi
Registration #16	2019-06-20	151.377 mi
Registration #17	2019-06-20	151.377 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	84%
Pedestrian	39%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1826 mm
Height	1427 mm
Length	4703 mm
Wheel base	2808 mm
Kerb weight	1460 kg
Max. allowed weight	2015 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5

Number of axles	2
Engine number	CAH 074045