



N4IIKGF

report date: 2024-03-28

General information

Make	SUZUKI
Model	VITARA JLX SE SOFT TOP
Colour	Black
Year of manufacture	1995
Gearbox	-automatic

Engine & fuel consumption

Engine capacity	1.590 cc
Fuel type	Petrol



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-25
Pictures	15
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-18
MOT pass rate	61 %
MOT passed	17
Failed MOT tests	11
Total advice items	47
Total items failed	26

MOT #28	2023-10-19 11:48
MOT test number	661512075072
Result	✓ Passed
Next expiry date	2024-10-18
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #27	2023-09-26 13:56
MOT test number	210986619817
Result	✗ Failed
Fail	Offside Rear Service brake excessively fluctuating (1.2.1 (e))
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Fail	Nearside Rear Parking brake inoperative on one side (1.4.1 (a))
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #26	2022-09-26 12:17
MOT test number	841332732584
Result	✓ Passed
Advice	Nearside Rear Service brake fluctuating, but not excessively (1.2.1 (e))
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Nearside Front screw in tyre

**MOT #25** 2022-09-20 10:30**MOT test number** 652128568681**Result** ✗ Failed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Brake fluid close to minimum mark light on (1.1.10 (d) (ii))
- Advice** Nearside Front screw in tyre
- Fail** Offside Rear Service brake excessively fluctuating (1.2.1 (e))
- Minor** Brake fluid warning lamp illuminated (1.1.10 (f))
- Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Fail** Nearside Rear Service brake excessively fluctuating (1.2.1 (e))
- Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #24 2021-09-06 08:45**MOT test number** 189682809913**Result** ✓ Passed**MOT #23** 2021-09-06 08:45**MOT test number** 233775498244**Result** ✗ Failed

- Pass with rectification** Front Windscreen washer not working (3.5 (a))

**MOT #22**

2020-09-14 11:31

MOT test number

991619406757

Result

✓ Passed

- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Rear Nail in tyre
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Nail in tyre
- Advice** Fuel Pipe/s corroded
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #21

2020-09-12 08:19

MOT test number

193342011602

Result

✗ Failed

- Advice** Nearside Front Nail in tyre
- Fail** Windscreen washer not working (3.5 (a))
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Fuel Pipe/s corroded
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Nail in tyre
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Tyre has ply or cords exposed 195/15 IN TREAD (5.2.3 (d) (ii))

**MOT #20**

2019-04-03 16:55

MOT test number

985700191000

Result

✓ Passed

- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19

2018-03-19 10:30

MOT test number

790538958587

Result

✓ Passed

- Advice** Steering system has slight free play detected at steering wheel (2.2.A.1a)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #18

2018-03-19 10:30

MOT test number

856910740794

Result

✗ Failed

- Advice** Steering system has slight free play detected at steering wheel (2.2.A.1a)
- Advice** Child Seat fitted not allowing full inspection of adult belt
- Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #17** 2017-03-31 16:48**MOT test number** 380985104426**Result** ✓ Passed**MOT #16** 2016-03-30 09:55**MOT test number** 702018830409**Result** ✓ Passed**Advice** Clutch pedal anti-slip provision missing**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #15** 2016-03-30 09:55**MOT test number** 832315584113**Result** ✗ Failed**Advice** Clutch pedal anti-slip provision missing**Pass with rectification** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #14** 2014-12-05 15:18**MOT test number** 816649534365**Result** ✓ Passed**MOT #13** 2014-11-28 13:05**MOT test number** 178282434382**Result** ✗ Failed**Fail** Offside Rear Direction indicator excessively damaged so that it is not visible from a reasonable distance (1.4.A.2e)**Fail** Nearside Inner Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)**Fail** Emissions not tested (7.3.A.1)

**MOT #12** 2013-11-28 09:29**MOT test number** 405562833433**Result** ✓ Passed**Advice** Nearside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)**Notice** Oil leak**MOT #11** 2012-12-01 13:44**MOT test number** 789916232339**Result** ✓ Passed**Notice** Coolant leak**Notice** Oil leak**MOT #10** 2011-12-01 16:32**MOT test number** 515855731396**Result** ✓ Passed**MOT #9** 2011-12-01 13:24**MOT test number** 395525631328**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Fail** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

**MOT #8** 2010-11-27 13:38**MOT test number** 332641830358**Result** ✓ Passed**Advice** Rear Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)**MOT #7** 2009-11-30 10:12**MOT test number** 294924739335**Result** ✓ Passed**MOT #6** 2009-11-28 14:37**MOT test number** 832562239363**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Offside rear parking brake recording little or no effort (3.7.B.6a)**MOT #5** 2008-11-27 17:14**MOT test number** 410082938421**Result** ✓ Passed**MOT #4** 2008-11-27 16:27**MOT test number** 454082738494**Result** ✗ Failed**Fail** Offside Obligatory mirror insecure (8.1.1)**MOT #3** 2007-11-26 16:03**MOT test number** 904470337320**Result** ✓ Passed



MOT #2	2007-11-24 12:30
MOT test number	484338227454
Result	✗ Failed
Fail	Nearside Windscreen washer provides insufficient washer liquid (8.2.3)
Fail	Offside Rear Wheel nut(s) missing (4.2.A.1e)
Fail	Offside Registration plate lamp not working (1.1.5c)
Fail	Offside Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1	2006-11-25 13:11
MOT test number	391529026328
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
18 October 2024

Tax status		Valid until 1 June
Days left		34
MOT expiry date		18 October 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	30
First mileage registration	1995-12-22
Last registration	2023-10-19
Complete history	See info



Registration #1	1995-12-22	6 mi
Registration #2	2006-11-25	39.057 mi
Registration #3	2007-11-24	40.424 mi
Registration #4	2007-11-26	40.425 mi
Registration #5	2008-11-27	41.750 mi
Registration #6	2008-11-27	41.750 mi
Registration #7	2009-11-28	45.203 mi
Registration #8	2009-11-30	45.203 mi
Registration #9	2010-11-27	48.001 mi
Registration #10	2011-12-01	51.481 mi
Registration #11	2011-12-01	51.481 mi
Registration #12	2012-12-01	53.416 mi
Registration #13	2013-11-28	53.984 mi
Registration #14	2014-11-28	55.708 mi
Registration #15	2014-12-05	55.708 mi
Registration #16	2015-12-01	56.277 mi
Registration #17	2016-12-01	56.277 mi
Registration #18	2017-12-01	56.277 mi
Registration #19	2018-12-01	56.277 mi
Registration #20	2019-12-01	56.277 mi
Registration #21	2020-12-01	56.277 mi
Registration #22	2021-12-01	56.277 mi
Registration #23	2022-12-01	56.277 mi
Registration #24	2023-12-01	56.277 mi
Registration #25	2024-03-28	56.277 mi
Registration #26	2024-03-28	56.277 mi

Registration #27	2025-25-25	25,252 442
Registration #28	2025-25-25	25,252 442
Registration #29	2025-25-25	25,252 442
Registration #30	2025-25-25	25,252 442

More info >



Additional information

Number of axles	2
Engine number	G16A310751