



HONDA



GFIOYWG

report date: 2024-03-29

General information

Make	HONDA
Model	CR-Z I-VTEC IMA SPORT
Colour	Silver
Year of manufacture	2010
Top speed	124 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	145 Nm at 4.800 rpm
Engine capacity	1.497 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	46.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	56.5 mpg
CO2 emission	117 g/km
CO2 label	C







Internet history

Entry 1

Date	2022-02-07
Pictures	19
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-25
MOT pass rate	69 %
MOT passed	11
Failed MOT tests	5
Total advice items	16
Total items failed	9

MOT #16	2024-01-16 12:32
MOT test number	461759208873
Result	✓ Passed
Next expiry date	2025-01-25

MOT #15	2023-01-17 13:29
MOT test number	279879657561
Result	✓ Passed

MOT #14	2023-01-17 12:17
MOT test number	247726026194
Result	✗ Failed
Fail Nearside Front Service brake excessively binding (1.2.1 (f))	

MOT #13	2022-01-26 15:11
MOT test number	756619722322
Result	✓ Passed

**MOT #12**

2022-01-25 12:51

MOT test number

443653885976

Result**✗ Failed**

- Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Nearside Side repeater not working (4.4.1 (a) (ii))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #11

2022-01-21 16:46

MOT test number

100053196847

Result**✗ Failed**

- Fail** Nearside Front Side repeater not working Fitted on mirror (4.4.1 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Tyre worn close to legal limit/worn on edge Both sides (5.2.3 (e))
- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #10

2021-01-23 12:46

MOT test number

503890733420

Result**✓ Passed**

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing Worn close to legal limit 3mm (5.2.3 (d) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing Worn close to legal limit 3 mm (5.2.3 (d) (ii))
- Advice** Offside Front Items removed from driver's view prior to test

**MOT #9** 2019-07-25 11:55**MOT test number** 760357370624**Result** ✓ Passed**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #8** 2018-07-26 12:41**MOT test number** 843316696013**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #7** 2018-07-26 10:20**MOT test number** 147672460690**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Nail in tyre**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #6** 2017-07-25 08:24**MOT test number** 231609229448**Result** ✓ Passed**Advice** Rear brake disc worn, pitted or scored, but not seriously weakened both rear discs are grooved (3.5.1i)

**MOT #5** 2016-06-30 10:51**MOT test number** 325827922815**Result** ✓ Passed**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**MOT #4** 2015-07-22 16:51**MOT test number** 295583305208**Result** ✓ Passed**MOT #3** 2014-07-01 14:45**MOT test number** 406962884195**Result** ✓ Passed**MOT #2** 2014-06-25 15:45**MOT test number** 616486674190**Result** ✗ Failed**Fail** Nearside Side repeater not working (1.4.A.2c)**MOT #1** 2013-06-27 15:41**MOT test number** 779908773142**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2024

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 May
Days left	1
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	C
Single payment (12 months)	£ 25,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 26,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-29
Last registration	2024-01-16
Complete history	See info



Registration #1	2010-06-29	26 mi
Registration #2	2013-06-27	3.779 mi
Registration #3	2014-06-25	4.540 mi
Registration #4	2014-07-01	4.540 mi
Registration #5	2015-07-22	6.142 mi
Registration #6	2016-06-30	14.629 mi
Registration #7	2017-07-25	22.354 mi
Registration #8	2018-07-26	29.717 mi
Registration #9	2018-07-26	29.717 mi
Registration #10	2019-06-29	35.377 mi
Registration #11	2019-06-29	35.377 mi
Registration #12	2019-06-29	35.377 mi
Registration #13	2019-06-29	35.377 mi
Registration #14	2019-06-29	35.377 mi
Registration #15	2019-06-29	35.377 mi
Registration #16	2019-06-29	35.377 mi
Registration #17	2019-06-29	35.377 mi
Registration #18	2019-06-29	35.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	93%
Children	80%
Pedestrian	71%
Safety systems	86%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	2014 mm
Height	1395 mm
Length	4080 mm
Wheel base	2425 mm
Kerb weight	1198 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2
Engine number	LEA1 1016382