





report date: 2024-03-29

General information

Mala	MEDGEDEG
Make	MERCEDES
Model	R-Class R500 SE
Colour	Black
Year of manufacture	2006
Top speed	149 mph
0 - 60 mph	6.9 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	306 BHP
Max. torque	460 Nm at 2.700 rpm
Engine capacity	4.966 cc
Cylinders	8
Fuel type	Petrol
Consumption city	15.2 mpg
Consumption extra urban	28.0 mpg
Consumption combined	21.2 mpg
CO2 emission	317 g/km
CO2 label	М



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-01-17

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-09-18
MOT pass rate	94 %
MOT passed	15
Failed MOT tests	1
Total advice items	17
Total items failed	4

MOT #16		2023-09-19 11:22
MOT test	number	205378150089
Result		✓ Passed
Next expi	ry date	2024-09-18
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Tyre worn close to legal limit/worn on edge both rear tyres close to limit (5.2.3 (e))
Advice	Tyre worn close to legal limit/worn on edge both front tyres close to limit (5.2.3 (e))

MOT #15	2022-09-12 11:09
MOT test number	301748660872
Result	✓ Passed

MOT #14	2021-11-17 11:31
MOT test number	475512924726
Result	✓ Passed

MOT #13	2020-11-14 10:18
MOT test	number 535684580497
Result	✓ Passed
Advice	Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
Advice	Nearside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #12		2019-11-19 14:59
MOT test	number	901060998389
Result		✓ Passed
Advice	Offside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	
Advice	Nearside Front Brake hose slightly deteriorated (1.1.12 (b) (ii))	

MOT #11	2018-11-15 09:38
MOT test number	622939538214
Result	✓ Passed
Advice All tyres worn close to legal limit	

MOT #10	2017-11-18 09:16
MOT test number	899570979225
Result	✓ Passed

MOT #9	2016-11-19 11:15
MOT test number	959845803498
Result	✓ Passed

MOT #8	2015-11-07 09:24
MOT test number	503776687920
Result	✓ Passed

MOT #7	2014-11-21 14:17
MOT test number	288035024385
Result	✓ Passed
Notice All tyres worn close to limit 225/55/18 109v	

CarCheck.co.uk page 4/13



report date: 2024-03-29

Passed

MOT #6

MOT test number

Result

Notice Front and rear brake pads low and discs lipped

2013-10-22 12:20

378745493428

✓ Passed

 MOT #5
 2012-10-29 15:27

 MOT test number
 449483502357

 Result
 ✓ Passed

 MOT #4
 2012-10-29 11:38

 MOT test number
 688523202334

 Result
 X Failed

Notice Both front brake discs surface corrosion

Fail Nearside Headlamp not working on dipped beam (1.7.5a)

Notice Plastic floor covers

Fail Nearside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

Fail Nearside Front position lamp(s) not working (1.1.A.3b)

Notice Plastic sill covers

Fail

Result

Offside Rear Stop lamp adversely affected by the operation of another lamp (1.2.1f)

MOT #3 2011-05-31 13:26
MOT test number 295681951442

Result ✓ Passed

MOT #2 2010-06-04 10:31

MOT test number 770945450197

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #1		2009-05-22 12:19
MOT test	number	463662849105
Result		✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Brake pad(s) wearing thin (3.5.1g)	
Advice	Nearside Rear Brake pad(s) wearing thin (3.5.1g)	

CarCheck.co.uk page 6/13



report date: 2024-03-29

Tax & MOT check





Expires: 18 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	18 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	М
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

Plate changes	More info >
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	OK STE
Plate since	
Current registration	UK SIR
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 11/13



BK06YSG report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2006-05-26
Last registration	2023-09-19
Complete history	See info



Registration #1	2006-05-26	27 mi
Registration #2	2009-05-22	24.257 mi
Registration #3	2010-06-04	29.166 mi
Registration #4	2011-05-31	32.472 mi
Registration #5	2012-10-29	34.325 mi
Registration #6	2012-10-29	34.325 mi
Registration #7	2013-10-22	38.749 mi
Registration #8	2014-11-21	49.079 mi
Registration #9	2015-11-07	55.535 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		111,7177 esp

More info >

CarCheck.co.uk page 12/13



BK06YSG report date: 2024-03-29

Safety ratings

NCAP rating	****
-------------	------

Video <u>see crash video</u>



Dimensions & weight

Width	2168 mm
Height	1661 mm
Length	4930 mm
Wheel base	2980 mm
Kerb weight	2185 kg
Max. allowed weight	2865 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	6
Number of axles	2
Engine number	11397130716681

CarCheck.co.uk page 13/13