



HYUNDAI




report date: 2024-03-29

General information

Make	HYUNDAI
Model	I40 CRDI SE NAV BLUE DRIVE
Colour	White
Year of manufacture	2017
Top speed	124 mph
0 - 60 mph	10.5 seconds
Gearbox	7 speed Semi-Automatic

Engine & fuel consumption

Power	139 BHP
Max. torque	340 Nm at 1.700 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	64.2 mpg
Consumption combined	60.1 mpg
CO2 emission	123 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-12-10
Pictures	12
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-11-09
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	13
Total items failed	1

MOT #5	2023-11-10 17:29
MOT test number	457888812980
Result	✓ Passed
Next expiry date	2024-11-09

MOT #4	2023-11-09 15:42
MOT test number	427299763283
Result	✗ Failed
Fail	Offside Front Outer Tyre has a cut in excess of the requirements deep enough to reach the ply or cords Sidewall cut to cords. 225/45R18 95W. Landsail. (5.2.3 (d) (i))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Tyre on 4mm + worn inner edge - Advise tracking. 225/45R18 95W. Landsail. (5.2.3 (e))

MOT #3	2022-11-07 12:47
MOT test number	947705152774
Result	✓ Passed
Advice	Offside Front Outer Tyre has a cut but not deep enough to reach the ply or cords sidewall (5.2.3 (d) (i))
Advice	Nearside Rear Outer Tyre slightly damaged sidewall (5.2.3 (d) (ii))

**MOT #2**

2021-11-02 10:44

**MOT test number**

709334394118

**Result**

✓ Passed

- Advice** Rear Brake pad(s) wearing thin pads at 3mm (1.1.13 (a) (ii))
- Advice** N. s .f and two rear tyres edges low
- Advice** Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Front Brake pad(s) wearing thin pads at 3mm (1.1.13 (a) (ii))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Tpms light on
- Advice** Two rear tyres slightly cracking
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

**MOT #1**

2020-11-03 09:14

**MOT test number**

141184977181

**Result**

✓ Passed

- Advice** Unable to test centre rear seat belt due to covers on seat



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 January 2025

✓  
**MOT**  
**Expires:**  
9 November 2024

<b>Tax status</b>	Valid until 1 January
<b>Days left</b>	246
<b>MOT expiry date</b>	9 November 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	G
<b>First licence fee (12 months)</b>	£ 210,00,-
<b>First licence fee diesel non RDE2 tested (12 months)</b>	£ 255,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2017-11-01
Last registration	2023-11-10
Complete history	<a href="#">See info</a>



Registration #1	2017-11-01	23 mi
Registration #2	2020-11-03	25.090 mi
Registration #3	2021-11-02	30.276 mi
Registration #4	2022-11-02	35.462 mi
Registration #5	2023-11-02	40.648 mi
Registration #6	2023-11-02	45.834 mi
Registration #7	2023-11-10	51.020 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	92%
Children	86%
Pedestrian	43%
Safety systems	86%
Overall rating	80%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1815 mm
Height	1470 mm
Length	4775 mm
Wheel base	2770 mm
Kerb weight	1659 kg
Max. allowed weight	2150 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	D4FDHU729963