





report date: 2024-03-28

General information

Make	HYUNDAI
Model	I30 CRDI COMFORT
Colour	Red
Year of manufacture	2011
Top speed	117 mph
0 - 60 mph	11.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	115 BHP
Max. torque	260 Nm at 1.900 rpm
Engine capacity	1.582 сс
Cylinders	4
Fuel type	Diesel
Consumption city	53.3 mpg
Consumption extra urban	68.9 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-28

Internet history

Entry 1

Date	2021-06-10
Pictures	1
Listing price	View report



source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2025-02-10
MOT pass rate	92 %
MOT passed	11
Failed MOT tests	1
Total advice items	12
Total items failed	2

MOT #12		2024-02-08 11:48
MOT test	number	510418729416
Result		✓ Passed
Next expi	y date	2025-02-10
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in exces	sive movement (5.3.4 (a)
Advice (a) (i))	Nearside Rear Suspension arm pin or bush worn but not resulting in exce	ssive movement (5.3.4

MOT #11		2023-02-08 13:17
MOT test	number	262330667128
Result		✓ Passed
Advice	Front Brake disc worn, but not excessively Both discs (1.1.14 (a) (i))	
Minor	Offside Front Windscreen damaged but not adversely affecting driver's view (3	3.2 (a) (i))
Advice	Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b)	(i))
Advice (ii))	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened O	uter edge (1.1.14 (a)

CarCheck.co.uk page 3/12



report date: 2024-03-28

MOT #10	2023-02-02 13:07
MOT test number	972427544044
Result	× Failed
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened Out (ii))	ter edge (1.1.14 (a)
Fail Offside Front Position lamp not working Side light (4.2.1 (a) (ii))	
Advice Front Brake disc worn, but not excessively Both discs (1.1.14 (a) (i))	
Fail Nearside Rear Parking brake inoperative on one side (1.4.1 (a))	
Advice Nearside Rear Service brake binding but not excessively (1.2.1 (f))	
Minor Offside Front Windscreen damaged but not adversely affecting driver's view (3.	2 (a) (i))
Advice Offside Front Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

MOT #9	2022-02-11 14:13
MOT test number	208363782207
Result	✓ Passed
MOT #8	2021-01-17 09:48
MOT test number	642420007726
Result	✓ Passed
MOT #7	2020-01-21 12:28
MOT test number	108259797660
Result	✓ Passed
MOT #6	2019-01-15 12:56
MOT test number	712599714652
Result	✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-28

MOT #5	2018-01-30 15:58
MOT test number	209336796542
Result	✓ Passed
Result	V rasseu
MOT #4	2017-01-23 10:35
MOT test number	952768890691
Result	✓ Passed
MOT #3	2016-02-03 10:15
MOT test number	857033040624
Result	✓ Passed
MOT #2	2015-02-10 17:13
MOT test number	699701245067
Result	✓ Passed
MOT #1	2014-11-19 17:25
MOT test number	749273524333
Result	✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	10 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owner have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HYUNDAI had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	NK NY
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HYUNDAI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-11-30
Last registration	2024-02-08
Complete history	See info



Registration #1	2011-11-30	25 mi
Registration #2	2014-11-19	41.814 mi
Registration #3	2015-02-10	41.941 mi
Registration #4	2016-02-03	50.842 mi
Registration #5	2017-01-23	60.407 mi
Registration #6	2018-01-30	71.798 mi
Registration #7	2019-01-15	80.463 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		0.00 44
Registration #13		11.777 mi

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1490 mm
Length	4245 mm
Wheel base	2650 mm
Kerb weight	1395 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	53	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12