



report date: 2024-03-28

General information

Make	FIAT
Model	500 C C LOUNGE
Colour	White
Year of manufacture	2009
Top speed	113 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	99 BHP
Max. torque	131 Nm at 4.250 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.5 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	140 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-10-22
Pictures	19
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2025-02-02
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	37
Total items failed	5

MOT #13	2024-01-19 09:29
MOT test number	142521480863
Result	✓ Passed
Next expiry date	2025-02-02
Advice	Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a))

MOT #12	2023-02-03 15:14
MOT test number	617480624314
Result	✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear exhaust box deteriorating.
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Exhaust has a minor leak of exhaust gases Flexi-joint. (6.1.2 (a))

MOT #11	2021-10-27 08:31
MOT test number	104050915988
Result	✓ Passed



MOT #10

2020-09-12 11:08

MOT test number

552887810633

Result

✓ Passed

- Advice

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice

Osr wing damaged
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Engine oil level low
- Advice

Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #9**

2020-09-05 11:37

**MOT test number**

991979030272

**Result**

✗ Failed

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Rear Brake cable insecure (1.1.15 (c))
- Advice** Osr wing damaged
- Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Fail** Offside Front Macpherson strut corroded and seriously weakened (5.3.3 (b) (i))
- Minor** Nearside Rear Brake pipe inadequately clipped or supported (1.1.11 (d) (i))
- Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Engine oil level low
- Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))
- Fail** Nearside Front Macpherson strut corroded and seriously weakened (5.3.3 (b) (i))
- Minor** Offside Front Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #8**

2019-02-19 13:25

**MOT test number**

384286143928

**Result**

✓ Passed

**MOT #7**

2018-02-27 13:29

**MOT test number**

416154959017

**Result**

✓ Passed

**MOT #6** 2017-02-23 15:29**MOT test number** 908269079598**Result** ✓ Passed**MOT #5** 2016-04-04 11:33**MOT test number** 517702151511**Result** ✓ Passed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Signs of a gearbox oil leak
- Advice** Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
- Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)
- Advice** Front exhaust pipe flexi poor condition
- Advice** Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)

**MOT #4** 2015-03-10 14:40**MOT test number** 345069365025**Result** ✓ Passed

- Notice** Windscreen damaged but not affecting drivers view

**MOT #3** 2014-03-06 16:48**MOT test number** 995335964005**Result** ✓ Passed

- Notice** Slight damage to nearside front inner wheel rim



MOT #2	2014-03-05 15:36
MOT test number	278274064059
Result	✗ Failed
Fail	Nearside Front Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)
Notice	Slight damage to nearside front inner wheel rim

MOT #1	2013-03-07 13:39
MOT test number	558456463048
Result	✓ Passed
Advice	Offside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)
Advice	Nearside Front Macpherson strut has slight movement at the upper attachment (2.5.A.1c)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 August 2024

✓  
**MOT**  
**Expires:**  
2 February 2025

<b>Tax status</b>	Valid until 1 August
<b>Days left</b>	95
<b>MOT expiry date</b>	2 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-09-21
Last registration	2024-01-19
Complete history	<a href="#">See info</a>



Registration #1	2009-09-21	28 mi
Registration #2	2013-03-07	7.587 mi
Registration #3	2014-03-05	8.986 mi
Registration #4	2014-03-06	8.986 mi
Registration #5	2015-03-10	14.434 mi
Registration #6	2016-04-04	20.640 mi
Registration #7	2017-02-23	23.752 mi
Registration #8	2018-02-27	25.139 mi
Registration #9	2019-03-20	26.377 mi
Registration #10	2020-03-20	27.577 mi
Registration #11	2021-03-20	28.777 mi
Registration #12	2022-03-20	29.977 mi
Registration #13	2023-03-20	31.177 mi
Registration #14	2024-01-19	32.377 mi
Registration #15	2024-01-19	33.577 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3546 mm
Wheel base	2300 mm
Kerb weight	970 kg
Max. allowed weight	1395 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	1442865