



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ZETEC TDCI
Colour	Blue
Year of manufacture	-
Top speed	109 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	89 BHP
Max. torque	204 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	51.4 mpg
Consumption extra urban	70.6 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-06-08
Pictures	8
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT #13	2021-06-08 13:41
MOT test number	913014932402
Result	✓ Passed
Next expiry date	2022-06-30

MOT #12	2020-06-10 14:14
MOT test number	122960319689
Result	✓ Passed

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Rear exhaust heat shield loose

MOT #11	2020-06-05 10:27
MOT test number	133354216035
Result	✗ Failed

Advice Rear exhaust heat shield loose

MAJOR Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))

MAJOR Exhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a))

MAJOR Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #10	2019-06-20 15:34
MOT test number	793226794368
Result	✓ Passed

Advice Brake pipe corroded, covered in grease or other material all covered in grease unable to inspect (1.1.11 (c))

Advice Diesel smell from engine bay but no visible leaks

Advice Rear heatshield insecure

Advice Slight gearbox oil leak



MOT #9	2019-06-18 10:48
MOT test number	554081439821
Result	✗ Failed
MAJOR	Nearside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Advice	Slight gearbox oil leak
Advice	Brake pipe corroded, covered in grease or other material all covered in grease unable to inspect (1.1.11 (c))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
MAJOR	Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
Advice	Diesel smell from engine bay but no visible leaks
MAJOR	Offside Front Suspension arm pin or bush excessively worn rear bush (5.3.4 (a) (i))
Minor	Front Windscreen wiper blade defective (3.4 (b) (i))
Advice	Rear heatshield insecure
MAJOR	Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))

**MOT #8**

2018-06-14 08:46

MOT test number

767123373452

Result

✓ Passed

Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Offside Rear tyre pressure low

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

Advice Rear exhaust heat shields loose in mountings

Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement rear (5.3.4 (a) (i))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #7

2017-06-15 14:42

MOT test number

796208575025

Result

✓ Passed

MOT #6

2017-06-15 14:16

MOT test number

108799319256

Result

✗ Failed

Fail Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

Fail Offside Front position lamp(s) not working (1.1.A.3b)

Fail Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**MOT #5** 2016-06-15 12:42**MOT test number** 105885053339**Result** ✓ Passed**Advice** Windscreen chipped zone b**MOT #4** 2015-06-06 11:57**MOT test number** 439637955117**Result** ✓ Passed**Notice** Headlamp beams becoming poor**Notice** Chip in windscreen**MOT #3** 2014-06-09 12:52**MOT test number** 515880364190**Result** ✓ Passed**Notice** Front nO plate cracked**Notice** Chip in windscreen zone b**MOT #2** 2013-06-10 16:24**MOT test number** 467601063175**Result** ✓ Passed**MOT #1** 2012-06-28 15:36**MOT test number** 207620782101**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2009-06-30
Last registration	2021-06-08
Complete history	See info



Registration #1	2009-06-30	17 mi
Registration #2	2012-06-28	33.906 mi
Registration #3	2013-06-10	43.334 mi
Registration #4	2014-06-09	54.108 mi
Registration #5	2015-06-06	64.864 mi
Registration #6	2016-06-15	73.527 mi
Registration #7	2017-06-15	82.303 mi
Registration #8	2017-06-15	82.303 mi
Registration #9	2018-06-01	91.079 mi
Registration #10	2019-06-01	99.855 mi
Registration #11	2020-06-01	108.631 mi
Registration #12	2021-06-08	117.407 mi
Registration #13	2021-06-08	117.407 mi
Registration #14	2021-06-08	117.407 mi
Registration #15	2021-06-08	117.407 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1171 kg
Max. allowed weight	1675 kg

Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

9C73512