



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BEETLE 8V
Colour	Blue
Year of manufacture	2004
Top speed	111 mph
0 - 60 mph	12.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	102 BHP
Max. torque	147 Nm at 3.800 rpm
Engine capacity	1.595 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.6 mpg
Consumption extra urban	46.3 mpg
Consumption combined	36.2 mpg
CO2 emission	185 g/km
CO2 label	I





Internet history

Entry 3

Date	2022-07-31
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 2

Date	2022-04-25
Pictures	10
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)

Entry 1

Date	2021-02-05
Pictures	1
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2025-02-12
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	30
Total items failed	8

MOT #20 2024-02-13 09:36**MOT test number** 376497318527**Result** Passed**Next expiry date** 2025-02-12**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Play in steering rack inner joint(s) both sides**Minor** Offside Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge both edges worn, tyre cracked (5.2.3 (e))**Advice** Offside Front Shock absorbers has a slightly worn bush top mount (5.3.2 (c))**MOT #19** 2023-02-11 11:49**MOT test number** 775657116737**Result** Passed

**MOT #18** 2022-02-11 17:49**MOT test number** 653376010212**Result** ✓ Passed**MOT #17** 2022-02-08 08:55**MOT test number** 511838221696**Result** ✗ Failed

MAJOR Nearside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))

DANGEROUS Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure 205/55 R 16 (5.2.3 (d) (ii))

MAJOR Offside Front Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))

Minor Nearside Rear Tyre obviously under inflated (5.2.3 (l))

Advice Nearside Rear Inner Integral body structure or chassis corroded within 30cm of a mounting, but not seriously affecting overall security (6.2.2 (d) (i))

MAJOR Offside Rear Inner Integral body structure or chassis has excessive corrosion, seriously affecting its strength within 30cm of a body mounting sill (6.2.2 (d) (i))

MOT #16 2021-02-01 16:46**MOT test number** 295270032954**Result** ✓ Passed**MOT #15** 2019-06-21 13:49**MOT test number** 107882657541**Result** ✓ Passed

**MOT #14** 2018-06-21 09:33**MOT test number** 533079279827**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Slight play front upper shock mounts**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Reverse lamp inop**Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear exhaust hanger corroded**MOT #13** 2017-05-24 11:43**MOT test number** 465756012039**Result** ✓ Passed**MOT #12** 2016-05-24 07:31**MOT test number** 506279226254**Result** ✓ Passed**MOT #11** 2016-05-24 07:31**MOT test number** 695155913415**Result** ✗ Failed**Pass with rectification** Nearside Front Headlamp aim too low (1.8)**Pass with rectification** Offside Front Headlamp aim too low (1.8)

**MOT #10** 2015-05-14 13:48**MOT test number** 215094135169**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #9** 2014-04-23 09:22**MOT test number** 455503214175**Result** ✓ Passed**MOT #8** 2012-12-18 16:26**MOT test number** 386963552337**Result** ✓ Passed**Advice** Nearside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**Advice** Offside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #7** 2012-12-18 16:26**MOT test number** 347163752321**Result** ✗ Failed**Advice** Nearside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Advice** Offside Front Steering system has slight free play detected at steering wheel (2.2.A.1b)**MOT #6** 2011-12-08 12:49**MOT test number** 425372741445**Result** ✓ Passed

**MOT #5** 2010-06-02 14:51**MOT test number** 392593050152**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Notice** Both rear tyres getting low**MOT #4** 2010-06-02 14:51**MOT test number** 311753250140**Result** ✓ Passed**Notice** Both rear tyres getting low**MOT #3** 2009-02-28 16:58**MOT test number** 921879159010**Result** ✓ Passed**MOT #2** 2007-11-23 14:50**MOT test number** 850417127384**Result** ✓ Passed**MOT #1** 2007-11-23 12:32**MOT test number** 801287027377**Result** ✗ Failed**Fail** Front registration plate character(s) likely to be misread (6.3.4b)**Fail** Centre Exhaust system not adequately supported (7.1.1)**Fail** Rear registration plate character(s) likely to be misread (6.3.4b)**Fail** Front Headlamp aim too low (1.8)



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LX54NZV
Plate since	2024-03-28
Current registration	 LX54NZV
Plate since	2024-03-28

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.


Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2004-12-04
Last registration	2024-02-13
Complete history	See info



Registration #1	2004-12-04	12 mi
Registration #2	2007-11-23	34.138 mi
Registration #3	2007-11-23	34.138 mi
Registration #4	2009-02-28	47.408 mi
Registration #5	2010-06-02	55.830 mi
Registration #6	2011-12-08	63.041 mi
Registration #7	2012-12-18	66.684 mi
Registration #8	2014-04-23	71.002 mi
Registration #9	2015-05-14	74.329 mi
Registration #10	2016-05-24	76.979 mi
Registration #11	2016-05-24	76.979 mi
Registration #12	2016-05-24	76.979 mi
Registration #13	2016-05-24	76.979 mi
Registration #14	2016-05-24	76.979 mi
Registration #15	2016-05-24	76.979 mi
Registration #16	2016-05-24	76.979 mi
Registration #17	2016-05-24	76.979 mi
Registration #18	2016-05-24	76.979 mi
Registration #19	2016-05-24	76.979 mi
Registration #20	2016-05-24	76.979 mi
Registration #21	2016-05-24	76.979 mi
Registration #22	2016-05-24	76.979 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1724 mm
Height	1498 mm
Length	4081 mm
Wheel base	2508 mm
Max. allowed weight	1757 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2

Engine number

BFS020725