





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Black
Year of manufacture	2010
Top speed	116 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	125 BHP
Max. torque	285 Nm at 1.750 rpm
Engine capacity	1.753 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

Entry 1

Date 2021-09-16

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-06-20
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	32
Total items failed	1

MOT #16	2023-06-21 10:52
MOT test number	688221034002
Result	✓ Passed
Next expiry date	2024-06-20
Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #15	2023-06-21 10:52
MOT test number	105854936546
Result	≍ Failed
Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))	
Advice Oil leak, but not excessive (8.4.1 (a) (i))	
Pass with rectification Nearside Stop lamp(s) not working (4.3.1 (a) (ii))	
Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	

MOT #14	2022-06-08 13:06
MOT test number	837070989139
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-28

MOT #13 2022-06-07 14:00

MOT test number 242043047080

Result X Failed

MAJOR Nearside Front Headlamp insecure (4.1.1 (c))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

MOT #12 2021-09-06 08:38

MOT test number 108167558423

Result ✓ Passed

MOT #11 2020-11-05 11:41

MOT test number 289420143829

Result \(\sqrt{Passed} \)

Advice Coolant Reservoir Empty

Advice Child Seat fitted not allowing full inspection of adult belt OSR and Center Rear

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))

MOT #10 2020-10-29 16:45

MOT test number 515251916410

Result X Failed

MAJOR Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

Advice Child Seat fitted not allowing full inspection of adult belt OSR and Center Rear

MAJOR Nearside Rear Suspension arm pin or bush excessively worn Trailer Arm Bush (5.3.4 (a) (i))

MAJOR Offside Front Position lamp not working (4.2.1 (a) (ii))

MAJOR Exhaust has a major leak of exhaust gases Back Box holed (6.1.2 (a))

Advice Rear Coil spring corroded Both (5.3.1 (b) (i))

Advice Coolant Reservoir Empty

CarCheck.co.uk page 4/13



report date: 2024-03-28

MOT #9 2019-10-30 14:57

MOT test number 781171157064

MOT #8 2019-10-29 10:42

MOT test number 855459367998

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Offside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #7 2018-11-01 10:45

MOT test number 150821090271

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Rear Coil spring corroded o/s n/s (5.3.1 (b) (i))

MOT #6 2017-11-01 17:00

MOT test number 311928366014

Result

Passed

MOT #5 2017-05-11 11:50

MOT test number 493665994726

Result \(\sqrt{Passed} \)

Advice Oil leak

CarCheck.co.uk page 5/13



report date: 2024-03-28

MOT #4 2016-05-12 13:08

MOT test number 247907602140

Result ✓ Passed

Advice Exhaust has a minor leak of exhaust gases holes corroded in centre pipe (7.1.2)

MOT #3 2015-05-05 11:47

MOT test number 719745925140

Result \(\sqrt{Passed} \)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #2 2014-05-09 12:29

MOT test number 536589024121

Result Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2013-04-18 14:57

MOT test number 368268003165

Result ✓ Passed

Notice Oil leak

Notice Engine covers fitted obscuring some components in the engine bay

Notice Front wipers smearing slightly

Notice Under-trays fitted obscuring some underside components

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	20 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 7/13




report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

SG10GVE

report date: 2024-03-28

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report here. More info >

Plate changes

More info >

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-03-22
Last registration	2023-06-21
Complete history	See info



Registration #1	2010-03-22	15 mi
Registration #2	2013-04-18	24.434 mi
Registration #3	2014-05-09	32.157 mi
Registration #4	2015-05-05	39.528 mi
Registration #5	2016-05-12	45.893 mi
Registration #6	2017-05-11	53.074 mi
Registration #7	2017-11-01	55.890 mi
Registration #8	2018-11-01	64.390 mi
Registration #9	2019-10-29	72.058 mi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es
Registration #14		71.777 es
Registration #15		11.777 es
Registration #16		71.777 es
Registration #17		11.777 es
Registration #18		11.117 es

More info >

CarCheck.co.uk page 12/13



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1897 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/1

Number of axles 2

Engine number AS55605