




report date: 2024-03-28

General information

Make	FIAT
Model	GRANDE PUNTO ACTIVE
Colour	Blue
Year of manufacture	2009
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	77 BHP
Max. torque	115 Nm at 3.000 rpm
Engine capacity	1.368 cc
Cylinders	4
Fuel type	Petrol
Consumption city	37.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.9 mpg
CO2 emission	139 g/km
CO2 label	E





MOT history

MOT expiry date	2025-01-31
MOT pass rate	58 %
MOT passed	11
Failed MOT tests	8
Total advice items	21
Total items failed	12

MOT #19	2024-02-01 14:44
MOT test number	907664356725
Result	✓ Passed
Next expiry date	2025-01-31

MOT #18	2022-04-23 09:28
MOT test number	463167636374
Result	✓ Passed
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #17	2022-04-23 09:28
MOT test number	312889718203
Result	✗ Failed
Pass with rectification	Front Registration plate missing (0.1 (a))
Advice	Front Exhaust has a minor leak of exhaust gases (6.1.2 (a))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #16** 2021-02-20 14:03**MOT test number** 255585971586**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #15** 2021-02-17 09:56**MOT test number** 447429837307**Result** ✗ Failed**Fail** Emissions not tested (8.2.1.2 (d))**Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))**Fail** Exhaust Lambda reading after 2nd fast idle outside specified limits (8.2.1.2 (c))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2019-10-11 15:56**MOT test number** 446506137211**Result** ✓ Passed**MOT #13** 2019-10-08 10:13**MOT test number** 414148724225**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))**MOT #12** 2018-10-09 08:14**MOT test number** 102394366495**Result** ✓ Passed**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Advice** Items removed from driver's view prior to test

**MOT #11** 2018-10-09 08:14**MOT test number** 270159728249**Result** ✗ Failed**Advice** Nearside Front Anti-roll bar ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Items removed from driver's view prior to test**MOT #10** 2017-10-05 11:26**MOT test number** 694659238693**Result** ✓ Passed**Advice** Central Front Exhaust has a minor leak of exhaust gases flexy section (7.1.2)**MOT #9** 2017-10-05 07:58**MOT test number** 309496106176**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit + very low on edges (4.1.E.1)**Advice** Nearside Front tyre wearing low on edges**Advice** Items removed from driver's view prior to test**Advice** Nearside Rear Tyre worn close to the legal limit + very low on edges (4.1.E.1)**Advice** Central Front Exhaust has a minor leak of exhaust gases flexy section (7.1.2)**Advice** Offside Front tyre wearing low on edges**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #8** 2016-09-30 14:36**MOT test number** 720765754452**Result** ✓ Passed

**MOT #7** 2015-10-02 16:43**MOT test number** 878547391196**Result** ✓ Passed**Advice** Exhaust system corroded**Advice** Both front tyres bald on inner edges**MOT #6** 2015-10-02 13:39**MOT test number** 662338877642**Result** ✗ Failed**Advice** Exhaust system corroded**Advice** Both front tyres bald on inner edges**Fail** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**MOT #5** 2014-10-03 11:35**MOT test number** 376986474240**Result** ✓ Passed**MOT #4** 2014-10-03 11:35**MOT test number** 479766174294**Result** ✗ Failed**Pass with rectification** Fuel cap/sealing device does not fasten securely maintaining the sealing arrangement (7.2.4b)**Pass with rectification** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #3** 2013-08-27 09:58**MOT test number** 459379033209**Result** ✓ Passed



MOT #2	2012-08-21 13:21
MOT test number	927434932218
Result	✓ Passed

MOT #1	2012-08-20 14:48
MOT test number	265043832203
Result	✗ Failed

Fail Offside Front Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
31 January 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	31 January 2025
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	0
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-10
Last registration	2024-02-01
Complete history	See info



Registration #1	2009-09-10	28 mi
Registration #2	2012-08-20	29.273 mi
Registration #3	2012-08-21	29.275 mi
Registration #4	2013-08-27	33.467 mi
Registration #5	2014-10-03	37.595 mi
Registration #6	2015-10-02	41.700 mi
Registration #7	2015-10-02	41.700 mi
Registration #8	2016-09-30	46.464 mi
Registration #9	2017-10-05	51.105 mi
Registration #10	2017-10-05	51.105 mi
Registration #11	2018-10-05	55.105 mi
Registration #12	2019-10-05	59.105 mi
Registration #13	2020-10-05	63.105 mi
Registration #14	2021-10-05	67.105 mi
Registration #15	2022-10-05	71.105 mi
Registration #16	2023-10-05	75.105 mi
Registration #17	2024-02-01	79.105 mi
Registration #18	2024-02-01	83.105 mi
Registration #19	2024-02-01	87.105 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1687 mm
Height	1490 mm
Length	4030 mm
Wheel base	2510 mm
Kerb weight	1040 kg
Max. allowed weight	1600 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	9519694