



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T32 TDI KOMBI
Colour	Grey
Year of manufacture	2012
Top speed	119 mph
0 - 60 mph	10.2 seconds
Gearbox	7 speed Semi Auto

Engine & fuel consumption

Power	178 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	1.968 cc
Cylinders	4
Fuel type	Diesel
Consumption city	27.7 mpg
Consumption extra urban	40.9 mpg
Consumption combined	34.9 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-22
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2025-04-19
MOT pass rate	77 %
MOT passed	10
Failed MOT tests	3
Total advice items	32
Total items failed	8

MOT #13	2024-04-04 08:21
MOT test number	422815943109
Result	✓ Passed
Next expiry date	2025-04-19

MOT #12	2023-04-13 08:18
MOT test number	851560670604
Result	✓ Passed
Advice	Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #11	2022-04-20 14:37
MOT test number	849679635627
Result	✓ Passed
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Spare tyre defective well worn and very low tread
Advice	Exhaust silencer boxes outer skins corroded
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #10**

2022-04-20 08:47

MOT test number

847055088069

Result**✗ Failed****Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Offside Windscreen washer not working (3.5 (a))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Advice** Spare tyre defective well worn and very low tread**Advice** Exhaust silencer boxes outer skins corroded**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))**MOT #9**

2021-08-12 10:02

MOT test number

976404897077

Result**✓ Passed****Advice** Rear exhaust in poor condition**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #8**

2021-08-12 10:02

MOT test number

692869017451

Result**✗ Failed****Advice**

Front Brake disc worn, but not excessively (1.1.14 (a) (i))

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Rear exhaust in poor condition

Pass with rectification

Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))

Pass with rectification

Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

2020-07-08 12:23

MOT test number

528193658076

Result**✓ Passed****Advice**

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #6

2019-09-30 13:17

MOT test number

291903141345

Result**✓ Passed****Advice**

CORROSION ON CENTER&REAR EXHAUST SILENCERS

Advice

Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice

FRONT UNDER SHIELDED FITTED INSPECTION RESTRICTED



MOT #5	2018-03-23 16:39
MOT test number	461952248102
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2018-03-16 10:50
MOT test number	814910032512
Result	✗ Failed
Fail	Nearside Rear Registration plate lamp not working (1.1.C.1d)
Fail	Rear brake disc in such a condition that it is seriously weakened (3.5.1i)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Fail	Offside Rear Registration plate lamp not working (1.1.C.1d)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #3	2017-03-07 16:05
MOT test number	287375311108
Result	✓ Passed

MOT #2	2016-03-17 14:43
MOT test number	823068397437
Result	✓ Passed

MOT #1	2015-02-20 14:59
MOT test number	309021155033
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Inner Rear Brake pad(s) wearing thin (3.5.1g)



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
19 April 2025

Tax status	Valid until 1 April
-------------------	---------------------

Days left	338
------------------	-----

MOT expiry date	19 April 2025
------------------------	---------------

Full MOT history	See MOT history
-------------------------	---------------------------------



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	WU12VFG
Plate since	2019-06-29
Current registration	WU12VFG
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2012-03-14
Last registration	2024-04-04
Complete history	See info



Registration #1	2012-03-14	13 mi
Registration #2	2015-02-20	28.224 mi
Registration #3	2016-03-17	38.680 mi
Registration #4	2017-03-07	46.932 mi
Registration #5	2018-03-16	58.312 mi
Registration #6	2018-03-23	58.312 mi
Registration #7	2019-09-30	71.568 mi
Registration #8	2020-07-08	84.152 mi
Registration #9	2020-09-20	95.377 mi
Registration #10	2020-10-20	105.377 mi
Registration #11	2020-11-20	115.377 mi
Registration #12	2020-12-20	125.377 mi
Registration #13	2021-01-20	135.377 mi
Registration #14	2021-02-20	145.377 mi
Registration #15	2021-03-20	155.377 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	2283 mm
Length	4892 mm
Kerb weight	2046 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	6
Engine number	CFCA056216