





General information

| Make | FIAT |
|---------------------|----------------|
| Model | 500L POP STAR |
| Colour | Silver |
| Year of manufacture | 2017 |
| Top speed | 111 mph |
| 0 - 60 mph | 12.8 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| Power | 95 BHP |
|-------------------------|---------------------|
| Max. torque | 127 Nm at 4.500 rpm |
| Engine capacity | 1.368 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 34.9 mpg |
| Consumption extra urban | 56.5 mpg |
| Consumption combined | 46.3 mpg |
| CO2 emission | 143 g/km |
| CO2 label | F |







Internet history

| Entry 2 | |
|---------------|-------------|
| Date | 2021-08-19 |
| Pictures | 40 |
| Listing price | View report |



source: heycar.co.uk

Entry 1

Date

Pictures

Listing price

2021-07-31

View report

39



source: yesauto.com

NISSAN

snty twork and uph

lagard paints Pinsurance write-off pro sure your Tyres & Alloy Wr nart Repair Insurance







MOT history

| MOT expiry date | 2024-10-29 |
|--------------------|------------|
| MOT pass rate | 67 % |
| MOT passed | 4 |
| Failed MOT tests | 2 |
| Total advice items | 6 |
| Total items failed | 3 |

| MOT #6 | | 2023-10-30 16:45 |
|-----------|--|------------------|
| MOT test | number | 217499044257 |
| Result | | ✓ Passed |
| Next expi | ry date | 2024-10-29 |
| Advice | Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |
| Advice | Nearside Rear Child Seat fitted not allowing full inspection of adult belt | |
| Advice | Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | |

| МОТ #5 | 2023-10-30 11:38 | |
|--|------------------|--|
| MOT test number | 180554178393 | |
| Result | 🗙 Failed | |
| Advice Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) | | |
| Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt | | |
| Fail Offside Front Lower Suspension arm pin or bush likely to become detached Rear bush (5.3.4 (a) (ii)) | | |

| MOT #4 | 2022-10-26 11:51 |
|-----------------|------------------|
| MOT test number | 109093104399 |
| Result | ✓ Passed |





| MOT #3 | | 2022-10-26 11:50 |
|-------------------------|--|------------------|
| MOT test number | | 547753147933 |
| Result | | 🗙 Failed |
| Pass with rectification | Offside Stop lamp(s) not working (4.3.1 (a) (ii)) | |
| Pass with rectification | Offside Side repeater not working (4.4.1 (a) (ii)) | |

| MOT #2 | 2021-09-14 00:33 |
|-----------------|------------------|
| MOT test number | 352474576379 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2020-09-17 13:22 |
| MOT test number | 135973994129 |
| Result | ✓ Passed |



Tax & MOT check

| ✓ Taxed Tax due: 1 November 2024 | ✓ MOT Expires: 29 October 2024 |
|---|---|
| Tax status | Valid until 1 November |
| Days left | 187 |
| MOT expiry date | 29 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|-------------------------------|------------|
| Band | н |
| First licence fee (12 months) | £ 255,00,- |
| Standard rate (12 months) | £ 180,00,- |
| Standard rate (6 months) | £ 99,00,- |
| Premium rate (12 months) | £ 570,00,- |
| Premium rate (6 months) | £ 313,50,- |





Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|---------|
| Date | |
| Category | Lamp |
| Туре | |
| Damage 2 | AMPLE |
| Dumage 2 | E E E E |
| Date | J. |
| Category | amer |
| Туре | |

Extra FIAT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info \rightarrow





Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| Trade retail value | 4 10.000 |
|-----------------------------|----------|
| Auction value | 4 10.000 |
| Average private trade value | 4 10.200 |

More info \rightarrow





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| And a second sec | |
|--|-------------|
| *********** | |
| ******** | |
| ******* | |
| *********** | |
| ******** | |
| | More info > |
| Plate changes | |
| See in this check if this FIAT had different number plates. | |
| Number of plates | , |
| Carrent registration | |
| Plate since | |
| Carrent registration | |
| Plate since | |
| | More info > |





Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |


More info \rightarrow





Mileage check

| Odometer | In miles |
|----------------------------|-----------------|
| Mileage registrations | 9 |
| First mileage registration | 2017-09-29 |
| Last registration | 2023-10-30 |
| Complete history | <u>See info</u> |



| Registration #1 | 2017-09-29 | 22 mi |
|-----------------|------------|------------|
| Registration #2 | 2020-09-17 | 8.278 mi |
| Registration #3 | | 11.117 esi |
| Registration #4 | | 11.117 esi |
| Registration #5 | 2021-09-14 | 11.256 mi |
| Registration #6 | | 11.117 esi |
| Registration #7 | | 11.777 esi |
| Registration #8 | | 10.000 est |
| | | |

More info >





Car features

| S0225 | Air conditioning |
|--------|------------------|
| \$0295 | |
| 50482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 94% |
| Children | 78% |
| Pedestrian | 65% |
| Safety systems | 71% |
| Overall rating | 83% |
| Video | see crash video |



| Dimensions & weight | |
|-----------------------------------|-----------------------|
| Width | 1784 mm |
| Height | 1658 mm |
| Length | 4242 mm |
| Wheel base | 2612 mm |
| Kerb weight | 1245 kg |
| Max. allowed weight | 1805 kg |
| Additional information | |
| Fuel tank capacity | 50 I |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

| Number of axles | 2 |
|-----------------|---------|
| Engine number | 4115821 |